



Expertise

Protocol number: 41778046
Order number / reference: 25180982
Inspection date: 26 Sept 2025

Manufacturer: Ford

Model: Transit 350 L3H2 Kasten Lkw VA Basis

VIN: WF0EXXTTREL66711



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Transit 350 L3H2 Kasten Lkw VA Basis	
Vehicle Identification number	WF0EXXTTREL66711
Mileage (Read)	60,723 km
First registration	4 Sept 2020
Number of holders	1
Power / Engine displacement	79 kw / 1,995 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Frozen White
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	30,000 km
Last maintenance on / at	01/2025 at 52,760 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available
		Letter No.	FS955173
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BSB 00246		
Emission standard	EURO6;WLTP;CI;PI/CI;N1 III, N2	Fine dust sticker	
Permitted total weight	3,500 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/60 R16 115R	Winter tyres on Steel	Continental	5mm / 5mm
2)	235/60 R16 115R	Winter tyres on Steel	Continental	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 01/2024		

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel

Equipment

Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake-force distribution (EBD)
- On-board computer (with fuel consumption and mileage information (e.g. remaining range) as well as outside temperature display and Ford ECO mode)
- Double-wing rear door with 180° opening angle (without window)
- Electric front windows (with quick-down/-up switch for driver's side)
- Ford Easy Fuel (comfort fuel cap and misfuelling protection)
- Glove compartment with lid
- Paint finish: Solid paint
- Steering column, adjustable in height and reach
- Particulate filter: diesel particulate filter
- Wheels: Tire repair kit
- Wheels: Steel wheels 6.5 J x 16 with 235/65 R 16 tires
- Headlight dipped beam with switch-off delay
- Sliding door: Sliding door, right
- Side protection strips
- Seat belts (front seat belt pretensioners and force limiters - driver's seat belt not fastened warning system)
- Start-stop system
- Rear bumper with integrated step
- Daytime running light
- Partition to the cargo area without windows
- Lashing eyes
- Immobiliser
- Central locking with remote control
- Overhead storage compartment at the front
- Driver's side airbag
- Exterior mirrors, manually adjustable (2) (with integrated indicators)
- roof, medium
- Headliner in driver's cab (up to the partition wall to the cargo area)
- tachometer
- Electronic Safety and Stability Program (ESP) with Traction Control (TCS) (Hill Start Assist - Crosswind Assist - Safety Brake Assist - Rollover Protection)
- Generator, high-performance version
- Transmission: 6-speed transmission
- Interior lighting with delay circuit
- Cargo area lighting
- MyKey key system (individually programmable second key)
- Radio: Audio System 12 (Radio (FM/AM) - Four speakers, antenna - Audio remote control on the steering wheel - Bluetooth, USB connection and hands-free system - MyFord Dock)
- Rear mud flaps
- Power steering
- Seats: Seat Package 4 (driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion angle, height) - double passenger seat with storage compartment under individually foldable seat cushions - headrests, height-adjustable - tray in the double passenger seat (fold-out) - inside armrest for driver - BASIC seat cover: fabric)
- Heat-insulating glazing, slightly tinted
- auxiliary heater, electric

Extra equipment

- Exterior mirrors, electrically adjustable and heated (with integrated indicators)
- Lane Keeping Assist and Fatigue Warning and High Beam Assist (heated windscreen - Headlight Assist with day/night sensor - Windscreen wipers with rain sensor)
- Package: Load compartment protection package 1 (load compartment floor "Easy Clean" - side wall paneling high)
- Double-wing rear door with 180° opening angle (with window) (with rear window wiper including windscreen washer nozzle and automatic activation when reverse gear is engaged)
- Front air conditioning (including dust and pollen filter)
- Parking pilot system front and rear including fog lights



Brief expert findings

Documents submitted	At the time of the inspection, the registration certificate Part 2 (letter) was available, but the registration certificate Part 1 (certificate) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was verified during the inspection by the undersigned.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available to inspect the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/maneuvering was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Vehicle glazing	Windscreen - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Interior	Cargo area floor (Inklusive Laderaum komplett) - Scratch(es) - No deduction
2	Body	Body - Stone chips - No deduction
3	Body	Body - Scratch(es) - No deduction

The vehicle shows signs of wear commensurate with its age and use.

Accident damages

No.	Accident
1	Side - left
2	Side right

Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
(*Functional tests of driver assistance systems are not included in the scope of services!*)
- a photo documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles from Alphabet Fuhrparkmanagement GmbH. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects that can no longer be attributed to normal use or wear and tear according to the underlying standard are listed in the product under value-reducing factors.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

- Fahrzeug kann nicht angehoben werden
- Unterbodenbesichtigung nicht möglich, es können Folgekosten entstehen
- Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkten Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung erhebliche Mehrkosten und somit Abweichung der für den Unfall ausgewiesenen Reparaturkosten nicht ausgeschlossen werden

Minderwerte höher als HEK



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 2: Vehicle glazing: Windscreen - Stone chips - Replace



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Accident 2: Side right



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0EXXTTREL66711

Hersteller / Modell: FORD FORD Transit 350 L3H2 Lkw VA Basis

Datum	KM-Stand	Beschreibung
21.01.2025	52.760	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
10.01.2024	35.429	AU
19.12.2022	18.969	Motoröl b. Wartung; Regelwartungsdienst