

Vehicle details

VIN	WF0EXXTTR EMR79802	Brand	FORD	Maintenance date	-
Licence Plate	SVP188	Model	Transit 2.0 Tdci 170le Van Rwd L4h3 3.	Maintenance mileage	-
Registration date	06/08/2021	Year	2021	Exterior Color	White Solid
Odometer	155 904 km	Engine size	1995	interior Color	Grey
Fuel	Diesel	Body Type	Panel van	Next technical inspection	06/08/2025
Seats	3	Transmission	Manual	CO2	-
Doors	4	Gears	6		

Inspection Details


Inspection date	10/02/2025	Inspection loc.	Járműdepó Kft.
-----------------	------------	-----------------	----------------



Generic equipment	Removable element	Technical Document
Manual air-conditioning ✓	Spare wheel (wheel & tyre) ✓	Service manual holder ✗
Cruise control ✓	Toolkit ✓	User manual ✗
Anti-fog lights ✓	Jack ✓	Key ✓
Front radars ✓		Remote key ✓
Reversing radars ✓		

Tyres

Winter kit

Hankook 235/65/16 R Winter 8.9 mm		Hankook 235/65/16 R Winter 7.9 mm	
Kumho 235/65/16 R Winter 5.4 mm		Kumho 235/65/16 R Winter 5.2 mm	

Exterior

1		Part Position Damages Severity Repair mode	Sill Front left Scratched - Repair	4		Part Position Damages Severity Repair mode	Side panel Back left Blister - For info
5		Part Position Damages Severity Repair mode	Door Back left Broken - Replace	6		Part Position Damages Severity Repair mode	Door Back right Scratched Length (cm) > 10 Repair
7		Part Position Damages Severity Repair mode	Door moulding Back Scratched - For info	9		Part Position Damages Severity Repair mode	Roof Front Scratched - For info
10		Part Position Damages Severity Repair mode	Roof post A/B/C Front right Scratched - For info	11		Part Position Damages Severity Repair mode	Wing moulding Side left Scratched - For info
12		Part Position Damages Severity Repair mode	Side panel Back left Scratched - For info	13		Part Position Damages Severity Repair mode	Door Side right Scratched - For info

14



Part

Position

Damages

Severity

Repair mode

Sticker removal

-

Not carried out

-

To be carried out

15



Part

Position

Damages

Severity

Repair mode

Bonnet

-

Stone impact

-

For info

16



Part

Position

Damages

Severity

Repair mode

Wing

Front left

Stone impact

-

For info

17



Part

Position

Damages

Severity

Repair mode

Bumper

Front

Stone impact

-

For info

18



Part

Position

Damages

Severity

Repair mode

Bumper

Front

Scratched

-

For info

19



Part

Position

Damages

Severity

Repair mode

Door

Front left

Dented

-

For info

20



Part

Position

Damages

Severity

Repair mode

Bumper

Back

Scratched

-

For info

21



Part

Position

Damages

Severity

Repair mode

C-pillar

Back right

Scratched

-

For info

22



Part

Position

Damages

Severity

Repair mode

Sidewall

Back right

Scratched

-

For info

23



Part

Position

Damages

Severity

Repair mode

Door moulding

Side right

Scratched

-

For info

24



Part

Position

Damages

Severity

Repair mode

Door moulding

Front right

Scratched

-

For info

25



Part

Position

Damages

Severity

Repair mode

Exterior door mirror shell

Right

Scratched

-

For info

Interior damage

2



Part	Fabric seat
Position	Front left
Damages	Cut
Severity	Length (cm) > 2
Repair mode	Replace

3



Part	Ceiling Shelf
Position	Front left
Damages	Worn out
Severity	-
Repair mode	For info



26		Part	Service manual holder	27		Part	User manual
		Position	-			Position	-
		Damages	Missing			Damages	Missing
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	For info

Others

8		Part	Other accessory	28		Part	Paint preparation
		Position	-			Position	-
		Damages	Not conform			Damages	-
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	Paintworks
		Reg. matrica					