


Vehicle details

VIN	WF0EXXTTR EMR87699	Brand	FORD	Maintenance date	-
Licence Plate	SVP176	Model	Transit 2.0 Tdci 170le Van Rwd L4h3 3.	Maintenance mileage	-
Registration date	04/08/2021	Year	2021	Exterior Color	White Solid
Odometer	155 523 km	Engine size	1995	interior Color	Grey
Fuel	Diesel	Body Type	Panel van	Next technical inspection	04/08/2025
Seats	3	Transmission	Manual	CO2	-
Doors	4	Gears	6		

Inspection Details

Inspection date	11/02/2025	Inspection loc.	Járműdepó Kft.
-----------------	------------	-----------------	----------------




Generic equipment	Removable element	Technical Document
Manual air-conditioning ✓	Spare wheel (wheel & tyre) ✓	Service manual holder ✗
Cruise control ✓	Toolkit ✓	User manual ✗
Anti-fog lights ✓	Jack ✓	Key ✓
Front radars ✓		Remote key ✓
Reversing radars ✓		

Tyres

Winter kit

Falken 235/65/16 R Winter 5.3 mm



Falken 235/65/16 R Winter 5.3 mm



Falken 235/65/16 R Winter 4.9 mm

Falken 235/65/16 R Winter 4.8 mm

Exterior

2



Part	Sill
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Repair

4



Part	Door
Position	Back left
Damages	Scratched
Severity	-
Repair mode	For info

5



Part	Wheelcap 16"
Position	Back right
Damages	Missing
Severity	-
Repair mode	Replace

6



Part	Door
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

7



Part	Roof post A/B/C
Position	Front right
Damages	Stone impact
Severity	-
Repair mode	For info

8



Part	Wing
Position	Front right
Damages	Stone impact
Severity	-
Repair mode	For info

9



Part	Bonnet
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

10



Part	Wing moulding
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Replace

11



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Replace

12



Part	Upper bumper
Position	Front
Damages	Stone impact
Severity	-
Repair mode	For info

13		Part Position Damages Severity Repair mode	Roof post A/B/C Front left Stone impact - For info
14		Part Position Damages Severity Repair mode	Wing Front left Stone impact - For info
15		Part Position Damages Severity Repair mode	Door moulding Front left Scratched - For info
16		Part Position Damages Severity Repair mode	Door Front left Scratched - For info
17		Part Position Damages Severity Repair mode B-oszlop	Other bodywork - Stained/dirty - For info
18		Part Position Damages Severity Repair mode	Panel moulding Back left Scratched - For info
19		Part Position Damages Severity Repair mode	Side panel Back left Scratched - For info
20		Part Position Damages Severity Repair mode	C-pillar Back left Scratched - Repair
21		Part Position Damages Severity Repair mode	Rear light (wing) Back left Scratched - For info
22		Part Position Damages Severity Repair mode	Bumper Back left Scratched - Replace
23		Part Position Damages Severity Repair mode	Door Back right Rusty Diameter (mm) > 4 Repair
24		Part Position Damages Severity Repair mode	Bumper Back Scratched - For info
25		Part Position Damages Severity Repair mode	Side panel Back right Scratched - For info
26		Part Position Damages Severity Repair mode	Door Side right Dented Diameter (mm) > 20 Repair
27		Part Position Damages Severity Repair mode	Door moulding Side right Scratched - For info
28		Part Position Damages Severity Repair mode	Sticker removal - Not carried out - To be carried out

Interior damage

1



Part	Interior cleaning
Position	-
Damages	Not carried out
Severity	-
Repair mode	To be carried out

3



Part	Ceiling Shelf
Position	Front left
Damages	Worn out
Severity	-
Repair mode	For info

29



Part	Service manual holder
Position	-
Damages	Missing
Severity	-
Repair mode	For info

30



Part	User manual
Position	-
Damages	Missing
Severity	-
Repair mode	For info

Others

31



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks