


Vehicle details

VIN	WF0EXXTTR EMR87704	Brand	FORD	Maintenance date	-
Licence Plate	SVP200	Model	Transit 2.0 Tdci 170le Van Rwd L4h3 3.	Maintenance mileage	-
Registration date	12/08/2021	Year	2021	Exterior Color	White Solid
Odometer	155 789 km	Engine size	1995	interior Color	Grey
Fuel	Diesel	Body Type	Panel van	Next technical inspection	12/08/2025
Seats	3	Transmission	Manual	CO2	-
Doors	4	Gears	6		

Inspection Details

Inspection date	11/02/2025	Inspection loc.	Reálszisztéma Autókereskedelem Kft.		
-----------------	------------	-----------------	-------------------------------------	--	--




Generic equipment	
Manual air-conditioning	✓
Cruise control	✓
Anti-fog lights	✓
Front radars	✓
Reversing radars	✓

Removable element	
Spare wheel (wheel & tyre)	✓
Toolkit	✓
Jack	✓

Technical Document	
Service manual holder	✗
User manual	✗
Key	✓
Remote key	✓

Tyres



Kumho 235/65/16 Summer 8.8 mm

Pirelli 235/65/16 Summer 5.6 mm




Kumho 235/65/16 Summer 8.6 mm

Pirelli 235/65/16 Summer 5.5 mm


Exterior

1		Part Sill Position Front left Damages Scratched Severity - Repair mode For info	3		Part Door Position Back right Damages Scratched Severity - Repair mode For info
4		Part Door Position Back left Damages Scratched Severity - Repair mode For info	5		Part Roof Position Back Damages Dented Severity Diameter (mm) > 20 Repair mode Repair
6		Part Turning signal side Position Right Damages Scratched Severity - Repair mode Replace	7		Part Wing moulding Position Front right Damages Scratched Severity - Repair mode Replace
8		Part Bumper Position Front Damages Scratched Severity - Repair mode Replace	9		Part Wing Position Front right Damages Stone impact Severity - Repair mode For info
10		Part Windscreen Position - Damages Stone impact Severity Diameter (mm) > 10 Repair mode Replace	11		Part Roof post A/B/C Position Front right Damages Stone impact Severity - Repair mode For info

12		Part Position Damages Severity Repair mode	Turning signal side Left Scratched - For info
13		Part Position Damages Severity Repair mode	Door Front left Scratched - For info
14		Part Position Damages Severity Repair mode	Door Back left Dented - For info
15		Part Position Damages Severity Repair mode	Door Back right Scratched - For info
16		Part Position Damages Severity Repair mode	Bumper Back Scratched - For info
17		Part Position Damages Severity Repair mode	Rear light (wing) Back right Scratched - For info
18		Part Position Damages Severity Repair mode	C-pillar Back right Scratched - For info
19		Part Position Damages Severity Repair mode	Side panel Back right Scratched - For info
20		Part Position Damages Severity Repair mode	Panel moulding Side right Scratched - For info
21		Part Position Damages Severity Repair mode	Door moulding Side right Scratched - For info
22		Part Position Damages Severity Repair mode	Lower side panel Back right Dented - For info
23		Part Position Damages Severity Repair mode	Door Side right Dented - For info
24		Part Position Damages Severity Repair mode	Door moulding Front right Scratched - For info
25		Part Position Damages Severity Repair mode	Door Front right Scratched - For info
26		Part Position Damages Severity Repair mode	Sticker removal - Not carried out - To be carried out

Interior damage

2



Part	Fabric seat
Position	Front left
Damages	Cut
Severity	-
Repair mode	Replace

27



Part	Glove compartment cover
Position	-
Damages	Scratched
Severity	-
Repair mode	For info

28



Part	Service manual holder
Position	-
Damages	Missing
Severity	-
Repair mode	For info

29



Part	User manual
Position	-
Damages	Missing
Severity	-
Repair mode	For info

Others

30



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks

Comments

Szerviz lámpa ég, olajcsere esedékes.