



status report

customer: BCA Autoauktionen GmbH

reference:

vehicle data

Ford Mondeo Turnier Business Edition

Vehicle identification number	WF0FXXWPCFJS38190	mileage read:	125470 km
First Registration / construction year:	06.06.2018 / 2018	Visit Date / place of birth:	11.07.2025 Hoppegarten
Bodywork:	cars	Re - import:	no
Body type:	station wagon	KBA no. :	8566//BJB
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1997 ccm / 110 kW (150 PS)	Engine:	front-wheel drive
paint:	Iridium-Schwarz Metallic	Number of previous owners:	3
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	no	Vehicle roadworthy:	yes
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
Hard Disk Drive	2	maintained: no / 6	- / -
☒ Fernbed . Auxiliary heating	☒ partition net	☒ Wind Deflector	☒ AHK fixed
☒ AHK removable	☒ AHK swivel	☒ AHK key	☒ Fernbed . entertainment
☒ headphone	☒ Load compartment cover	☒ LED headlights	☒ navigation system
☒ Persenning	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	All season tires	aluminum
1st axis - Left / states .	Hankook	215/60/R16/99V 5 mm
1st axis - right / states .	Hankook	215/60/R16/99V 5 mm
2nd axis - Left / states .	Anderer	215/60/R16/99V 5 mm
2nd axis - right / states .	Anderer	215/60/R16/99V 5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment

- | | |
|--|--|
| <ul style="list-style-type: none"> • Anti -lock braking system (ABS) • Drive Front Wheel Drive • Electric wing mirror . anklappbar
<i>Bodenleuchte im Außenspiegel</i> • Body color door mirrors • board computer • Roof rails (aluminum) • Electr . Brake-force Distribution • Driving Assistance System Hill Start Assistant (Hill Holder) • Electric windows front and rear with convenience closing • carpet floor mats • Cruise control system (cruise control)
<i>Geschwindigkeits-Begrenzeranlage</i> • pollen filter • Isofix admissions for child seat • Parental control electrically • black grille • Steering wheel (leather) with multifunction • Steering column (steering wheel) height / telescopic adjustment • Reading lights in the rear • Rear center armrest • Engine 2.0 ltr. - 110 kW TDCi KAT • fog lights • Park Pilot system , front and rear
<i>Parkpilotsystem hinten</i> • Spare wheel as an emergency wheel • Back seat armrest partly / hinged (6040) • Gearshift / selector lever leather | <ul style="list-style-type: none"> • Anti-Slip Regulation (ASR) + ABS • Audio Navigation System Ford SD (with Ford SYNC)
<i>Audiobedienung am Lenkrad, 9 Lautsprecher, Sprachsteuerung und Bluetooth-Schnittstelle, Vorrüstung Mobiltelefon/Handy mit Bluetooth-/USB-Schnittstelle, Fahrassistentz-System: Sicherheitssystem SYNC mit automatischem Notruf, USB-Anschluss, Ford SYNC 3 mit Navigation</i> • Electric wing mirror . adjustable and heatable • Flashing light integrated in exterior mirrors • Coming - Home - lighting function
<i>Scheinwerfer mit Begrüßungsfunktion, Scheinwerfer mit Ausschaltverzögerung</i> • Door sill panels front • Elektron . Stability Program (ESP) • Driving Assistance System Brake Assist • Remote unlocking tailgate / lids • Luggage office cover / shade • Transmission 6-speed - Powershift MPS 6 • Intelligent Protection System (IPS)
<i>Knieairbag Fahrerseite, Airbag Fahrer-/Beifahrerseite, Kopf-Schulter-Airbag vorn und hinten, Seitenairbag vorn, 3-Punkt-Sicherheitsgurt hinten</i> • Body 5-doors • Climate control 2 zones • Lumbar support front • Steering wheel with paddles • Reading light front • LM rims • Front center armrest with storage compartment and 12V connector |
|--|--|

• Front left seat height adjustment • Front right seat adjustment (4x) • Sun visor with mirror right (lit) • Socket (12V connection) in the boot / load compartment • Door handles painted outside • Winter package <i>Frontscheibe heizbar, Sitzheizung vorn</i>	• My Key (2nd vehicle keys can be programmed) • Electric parking brake • Tire Pressure Monitoring System • Rußpartikelfilter • Low emissions Euro 6 emissions standard • Electric power steering • Front right seat height adjustment • Sun visor with mirror left (illuminated) • Start / Stop system • Daytime Running Lights • Warning system for rear seat belts • Central locking with remote control
---	---

special Features	
• Trailer Stabilization Program (TSA) • Luggage compartment partition (net) • Lacquer Iridium Black Mica	• Driving Assistance System Parking Assist (Active Park Assist) <i>Parkpilotsystem vorn und hinten, Parkpilotsystem hinten</i> • The luggage net • Sports seats

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body

outer skin. The measured values ??were within the tolerances of original finishes .
Evidence that points to a repaired accident damage or repainting carried out , were
identified.

Existing collision damage:

-
-

reference:

Overview conducted technology audit					
Alternator / Generator:			not possible	Battery / accumulator:	
					Out of order
oil loss:			examined limited		
air conditioning:			not possible	lighting system:	
					examined limited
coupling:			unavailable	exhaust System:	
					not possible
engine running:			not possible	shock absorber:	
					not possible
transmission:			not possible		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) could not be verified .
Battery / accumulator:	The battery (accumulator) was discharged for visiting time . **Battery deep discharge. Vehicle was bridged with a jumper.
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning could not be checked during the inspection .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system could not be checked during the inspection .
engine running:	A field test of the engine could not be performed
shock absorber:	The shock absorber could not be checked during the inspection .
transmission:	The transmission could not be checked for visiting time .
reference:	*Motorschaden nicht ausgeschlossen; Fzg. weist rundum erhöhte Lackschichtwerte auf

damage



component	Damage	Rep kind
1. Batterie	Not okay	Replace
2. Motor	Not Jumps On	Carry out a fault diagnosis
3. Wartung	Due	Replace
4. Wartungsnachweis	Missing	Replace
5. Laderaumabdeckung	Missing	Replace
6. Trennnetz	Missing	Replace
7. hood	Wear and tear	acceptable
8. Front bumper	Deformed (strongly)	Replace
9. Sidewall - Rear - Left	Scratch(es)	Smart repair
10. Türeinstieg h.l.	Scratch(es)	Paint
11. roof	Wear and tear	acceptable
12. Rear bumper	Wear and tear	acceptable
13. Felge h.r.	Scratch(es)	Paint
14. Sidewall - Rear - right	Deformed (slightly)	Refurbish and paint
15. Door Rear - right	Scratch(es)	Paint

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims




rims



engine compartment



service book



Others



Navigation system



3. Wartung



5. Laderaumabdeckung



6. Trennnetz



7. hood




8. Front bumper



9. Sidewall - Rear - Left



10. Türeinstieg h.l.



11. roof



12. Rear bumper



13. Felge h.r.



14. Sidewall - Rear - right



15. Door Rear - right