


Vehicle details

VIN	WF0JXXGAH JKS23892	Brand	FORD	Maintenance date	-
Licence Plate	ZR-20-5X	Model	FIESTA 1.0 EcoBoost Active Automaat 5d	Maintenance mileage	-
Registration date	29/07/2019	Year	2019	Exterior Color	Black Solid
Odometer	153 326 km	Engine size	998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	15/05/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓


Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

Spare key	✗
User manual	✓
Warranty booklet	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Hankook 205/45/17 All seasons 7.0 mm		Hankook 205/45/17 All seasons 6.0 mm	
Vredestein 205/45/17 All seasons 5.0 mm		Vredestein 205/45/17 All seasons 5.0 mm	

Exterior

2



Part	Alloy wheel 17"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

4



Part	Door
Position	Front left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

5



Part	Door lock trim
Position	Front left
Damages	Missing
Severity	-
Repair mode	Replace

6



Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

8



Part	Bumper
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

10



Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

11



Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

12



Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

13



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

14



Part	Other bodywork
Position	-
Damages	Not conform
Severity	-
Repair mode	For info

onderzijde voertuig

15



Part	Alloy wheel 17"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

16



Part	Other bodywork
Position	Front
Damages	Not conform
Severity	-
Repair mode	For info

Interior damage

1



Part	Spare key
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

3



Part	Interior cleaning
Position	Front left
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

7



Part

Position

Damages

Severity

Repair mode

Interior cleaning

Back

Stained/dirty

-

Cleaning

9



Part

Position

Damages

Severity

Repair mode

Interior tailgate lining

-

Scratched

-

Smart Repair