



status report

customer: Bank 11, Neuss
contract number: 1121995530
reference:

vehicle data

Ford S-MAX Vignale

Vehicle identification number	WF0JXXWPCJKE00355	mileage read:	138750 km
First Registration / construction year:	17.06.2019 / 2019	Visit Date / place of birth:	17.09.2025 Knautnaundorf
Bodywork:	cars	Re - import:	no
Body type:	VAN / MPV	KBA no. :	8566//BQR
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1995 ccm / 140 kW (190 PS)	Engine:	front-wheel drive
paint:	Arktis-Weiß (Metallic)	Number of previous owners:	3
Doors / seats:	5 / 7	number keys:	3
Next HU / AU:	- / -	cushion type:	leather
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle	-	state outside:	4 - moderate
documents:		condition inside:	4 - moderate
visit condition:	-		
state general:	4 - moderate		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
SD Card	3	no / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	All season tires	aluminum
1st axis - Left / states .	Goodyear	235/50/R18/110V 3 mm
1st axis - right / states .	Goodyear	235/50/R18/110V 4 mm
2nd axis - Left / states .	Goodyear	235/50/R18/110V 4 mm
2nd axis - right / states .	Goodyear	235/50/R18/110V 4 mm
traffic Safety:	roadworthy	
spare wheel:	Tirefit	
state spare wheel:	-	

standard equipment	
• <i>Scheinwerfer-Assistent mit Tag-/Nachtsensor, Tagfahrlicht LED</i> • Anti -lock braking system (ABS) • Drive Front Wheel Drive • Electric wing mirror . adjustable and heatable • Flashing light integrated in exterior mirrors • board computer • Electr . Brake-force Distribution • Driving Assistance System Hill Start Assistant (Hill Holder) • Driving Assistance System Brake Assist • • Window frames with chrome screens (chrome trim set) • Premium floor mats • Cruise control system (cruise control) <i>Geschwindigkeits-Begrenzeranlage, Innenspiegel mit Abblendautomatik, Fahrassistenz-System: Verkehrsschildassistent</i> • Intelligent Protection System (IPS) <i>Knieairbag Fahrerseite, Airbag Fahrer-/Beifahrerseite, Kopf-Schulter-Airbag vorn und hinten, Seitenairbag vorn, 3-Punkt-Sicherheitsgurt hinten, Gurtstraffer</i> • Body 5-doors • Parental control electrically • Steering wheel (leather) with multifunction <i>Schalt-/Wählhebelgriff Leder</i> • Reading lights in the rear • Front center armrest with storage compartment and 12V connector	• Ambient lighting front (LED) • Anti-Slip Regulation (ASR) • Electric wing mirror . anklappbar • Body color door mirrors • Floor lamp in the exterior mirrors • Twin tailpipe exhaust system • Elektron . Stability Program (ESP) • • Driving Assistance System Lane Departure Warning with fatigue detection sensor • Electric windows front and rear with convenience closing • Windscreen laminated glass • Luggage office cover / shade • • Isofix admissions for child seat • KeyFree system • Climate control 2 zones • Steering column (steering wheel) height / telescopic adjustment • LM rims • • Sony navigation module (in addition to the audio system) <i>Audiosystem Sony (Radio/CD-Player) mit Ford SYNC und Touchscreen-Farbdisplay, Audiobedienung am Lenkrad, 9 Lautsprecher, Vorrüstung Mobiltelefon/Handy mit Bluetooth-/USB-Schnittstelle, Fahrassistenz-System: Sicherheitssystem SYNC mit automatischem Notruf, AUX-IN-Anschluss, USB-Anschluss, Ford SYNC 3 mit Navigation</i> • Electric parking brake

• My Key (2nd vehicle keys can be programmed) • Chrome surrounds for the fog lights • Power KeyFree - start function • Tire Pressure Monitoring System • <i>Parkpilotsystem vorn und hinten</i> • • Headlights with switch-off delay <i>Scheinwerfer mit Begrüßungsfunktion</i> • Electric power steering • Start / Stop system • Stowage / storage compartment under front right seat • Warning device for seat belts front • Central locking with remote control	• Tire repair kit • Rußpartikelfilter • Low emissions Euro 6 emissions standard • Rain-sensing wipers • Body color side skirts • Sports seats, front • Stowage / storage compartment under front left seat • Warning system for rear seat belts • Winter package <i>Frontscheibe heizbar, Sitzheizung vorn</i>
--	--

special Features	
• Roof spoiler body color • <i>Parkpilotsystem vorn und hinten, Rückfahrkamera</i> • KeyFree package <i>KeyFree-System, Kofferraumdeckel / Heckklappe elektr. betätigt (Öffnung, sensorgesteuert)</i> • Front seats with massage function <i>Sitze vorn klimatisiert, Sitz vorn rechts elektr. verstellbar (8-fach), Sitz vorn links elektr. verstellbar (8-fach, mit Memory)</i> • <i>Außenspiegel mit Blind Spot Informations System, Adaptive Scheinwerfer LED mit Abbiegelicht, Scheinwerfer-Assistent mit Tag-/Nachtsensor, Tagfahrlicht LED, Fahrassistenten-System: Fernlichtassistent (Scheinwerfer mit Abblendautomatik), Kofferraumdeckel / Heckklappe elektr. betätigt (Öffnung, sensorgesteuert), Fahrassistenten-System: Spurhalteassistent mit Müdigkeitserkennungs-Sensor</i>	• Family package <i>Panorama-Glasdach mit Solar-Reflect, Frontscheibe Solar-Reflect, Sonnenschutzrollo an Türscheiben hinten, Steckdose 230V, Klapptisch in Fahrer- und Beifahrersitzlehne integriert</i> • Tailgate electrically • Steering wheel heated •

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .

Mileage plausible: **not testable**
 not testable

reference:

Note Road Safe: Frontscheibe Steinschlag, Bremse verschlissen/nicht in Ordnung

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross: **no detectable**

As part of a paint film thickness measuring the body outer skin no previous damage could be detected .

Layers of paint thickness measurement:

Within the tolerances

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.

Existing collision damage:

found

At the unrepaired vehicle accident damage were observed on visual examination on the body skin .

reference:

Fahrzeug mit bestehenden Unfallschaden, zur Schadensermittlung wurden keine Demontagearbeiten durchgeführt, verborgen gebliebene Schäden können nicht ausgeschlossen werden. Unfallschaden Kosten wurden überschlägig Kalkuliert, Kostenerweiterung möglich.

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
oil loss:			examined limited	 examined limited	
air conditioning:			examined limited	lighting system:	
coupling:			unavailable	 examined limited	
engine running:			examined limited	exhaust System:	
transmission:			examined limited	 examined limited	
				shock absorber:	
				 not possible	

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could not be checked during the inspection .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Das Fahrzeug hat starke Alters- und Gebrauchsspuren, diverse Beschädigungen ringsum

damage



component	Damage	Rep kind
1. tire front - left	Worn	Replace
2. Frontscheibenleiste links und rechts	Missing	Replace
3. Kofferraum und Innenraum	Wear and tear	acceptable
4. Türeinstieg Hinten - Links	Damaged	Refurbish and paint
5. Lenkrad	Material wear	Replace
6. Türeinstieg Hinten - Rechts	Damaged	Refurbish and paint
7.	Chipping from stones	Replace
8. hood	Rust	Paint
9. Fahrzeug vorn	Accident damage	Replace
10. Fahrzeug links	Accident damage	Replace
11. Rear bumper	Scrape	Refurbish and paint
12. Sidewall - Rear - right	Scratch(es)	Paint
13. Door Rear - right	Scrape	Paint
14. Front door - right	chipped paint	Paint
15. Outside mirror - right	Scrape	Paint
16.	Scrape	Paint
17. brake system	Not okay	Replace
18. Fahrzeug (Kratzer, Harz-/Säureeinwirkung, Flugrost, Verschmutzungen)	Not okay	
19. Wartung (nicht durch Wartungsnachweis belegt)	Missing	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims




engine compartment



service book



Others



Navigation system



1. tire front - left



2. Frontscheibenleiste links und rechts



2. Frontscheibenleiste links und rechts



2. Frontscheibenleiste links und rechts



2. Frontscheibenleiste links und rechts



3. Kofferraum und Innenraum



3. Kofferraum und Innenraum



3. Kofferraum und Innenraum



3. Kofferraum und Innenraum



4. Türeinstieg Hinten - Links



4. Türeinstieg Hinten - Links



4. Türeinstieg Hinten - Links



4. Türeinstieg Hinten - Links



4. Türeinstieg Hinten - Links



4. Türeinstieg Hinten - Links



4. Türeinstieg Hinten - Links



4. Türeinstieg Hinten - Links



5. Lenkrad




5. Lenkrad




5. Lenkrad




5. Lenkrad



6. Türeinstieg Hinten - Rechts



6. Türeinstieg Hinten - Rechts



6. Türeinstieg Hinten - Rechts




6. Türeinstieg Hinten - Rechts



6. Türeinstieg Hinten - Rechts



7.



7.



8. hood



8. hood



8. hood



8. hood



8. hood



8. hood



9. Fahrzeug vorn



9. Fahrzeug vorn



9. Fahrzeug vorn



9. Fahrzeug vorn



9. Fahrzeug vorn



9. Fahrzeug vorn



9. Fahrzeug vorn



9. Fahrzeug vorn



10. Fahrzeug links



10. Fahrzeug links



10. Fahrzeug links



10. Fahrzeug links



10. Fahrzeug links



10. Fahrzeug links



10. Fahrzeug links



10. Fahrzeug links



10. Fahrzeug links



10. Fahrzeug links



10. Fahrzeug links



10. Fahrzeug links



10. Fahrzeug links



11. Rear bumper



11. Rear bumper



11. Rear bumper



11. Rear bumper



11. Rear bumper



11. Rear bumper



11. Rear bumper



12. Sidewall - Rear - right



12. Sidewall - Rear - right




12. Sidewall - Rear - right



12. Sidewall - Rear - right



13. Door Rear - right



13. Door Rear - right



13. Door Rear - right



13. Door Rear - right



14. Front door - right



14. Front door - right



14. Front door - right



14. Front door - right



14. Front door - right



15. Outside mirror - right



15. Outside mirror - right



16.



16.



17. brake system



17. brake system



17. brake system



17. brake system



17. brake system



17. brake system



17. brake system



17. brake system



18. Fahrzeug (Kratzer, Harz-/Säureeinwirkung, Flugrost, Verschmutzungen)



18. Fahrzeug (Kratzer, Harz-/Säureeinwirkung, Flugrost, Verschmutzungen)