



status report

customer: BCA Autoauktionen GmbH

reference:

vehicle data

Ford Tourneo Courier Titanium

Vehicle identification number	WF0LXXTACLHC42051	mileage read:	61568 km
First Registration / construction year:	06.11.2017 / 2017	Visit Date / place of birth:	06.10.2025 Hoppegarten
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	8566//BIL
Fuel / emission class:	gasoline / € 6	transmission type:	manual transmission
Displacement / power:	998 ccm / 74 kW (101 PS)	Engine:	front-wheel drive
paint:	Frost-Weiß	Number of previous owners:	3
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	yes	Interior Color:	gray
smoking vehicle:	yes	Last service km / on the:	45093 / 18.12.2021
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	Eg II (veh - letter)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	yes / no	45093 / 18.12.2021
☒ Fernbed . Auxiliary heating	☒ partition net	☒ Wind Deflector	☒ AHK fixed
☒ AHK removable	☒ AHK swivel	☒ AHK key	☒ Fernbed . entertainment
☒ headphone	☒ Load compartment cover	☒ LED headlights	☒ navigation system
☒ Persenning	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	All season tires	aluminum
1st axis - Left / states .	Fulda	195/55/R16/87V 4 mm
1st axis - right / states .	Fulda	195/55/R16/87V 4 mm
2nd axis - Left / states .	Fulda	195/55/R16/87V 5 mm
2nd axis - right / states .	Fulda	195/55/R16/87V 5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment

- | | |
|---|---|
| <ul style="list-style-type: none"> • 2.Sitzreihe with bench • Anti -lock braking system (ABS) • Drive Front Wheel Drive • Sliding window sliding door left • Body color door mirrors • roof rails • Energy recovery (Smart Regenerative Charging) • Driving Assistance System Brake Assist • Heated front window • Transmission 5-speed - type IB5 • glazed tailgate
<i>Heckscheibenwischer, Heckscheibe heizbar</i> • Interior mirror with auto dip • Isofix admissions for child seat • Climate control 2 zones • Steering column (steering wheel) height / telescopic adjustment • Front center armrest with storage compartment and 12V connector • fog lights • Tire repair kit • Rear seat split / folding • Gearshift / selector lever leather • Sliding door on the left • Electric power steering • Sun visor with mirror right • Body color bumpers • Carpeting in passenger / cargo area • Glazed tinted
<i>Verglasung hinten abgedunkelt (Privacy Glass)</i> • auxiliary heating | <ul style="list-style-type: none"> • Storage in the headliner cab • Anti-Slip Regulation (ASR) • Audio Pack 16
<i>Audiosystem MyConnection (Radio/CD-Player MP3-fähig), Audiobedienung am Lenkrad, Vorrüstung Mobiltelefon/Handy mit Bluetooth-/USB-Schnittstelle</i> • Electric wing mirror . adjustable and heatable • board computer • Elektron . Stability Program (ESP) • Driving Assistance System Hill Start Assistant (Hill Holder) • Electric window . front with comfort circuit
<i>Fensterheber elektrisch vorn</i> • Cruise control system (cruise control)
<i>Geschwindigkeits-Begrenzeranlage, Lenkrad (Leder) mit Multifunktion, Audiobedienung am Lenkrad</i> • pretensioners • Dust and pollen filter • Intelligent Protection System (IPS)
<i>Airbag Fahrerseite, Airbag Beifahrerseite, Airbag Beifahrerseite abschaltbar, Seitenairbag vorn, Kopf-Schulter-Airbag vorn</i> • Body / body combination • Headrest rear center • LM rims • Engine 1.0 ltr. - 74 kW EcoBoost KAT • Wheelbase 2489 mm • Tire Pressure Monitoring System • Low emissions Euro 6 emissions standard • Rain-sensing wipers
<i>Scheinwerfer-Assistent mit Tag-/Nachtsensor</i> |
|---|---|

	• sliding right • Sun visor with mirror left • Starter Package • Daytime Running Lights • Outside handles body color • Central locking with remote control
--	---

special Features	
• Seat package 4/17/38/46 <i>Seitenairbag vorn, Kopf-Schulter-Airbag vorn, Sitzheizung vorn, Sitz vorn links höhenverstellbar, Lendenwirbelstütze Sitz vorn links, Armlehne für Fahrersitz, Stau-/Ablagefach unter Sitz vorn rechts</i>	

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	no no
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	- -
reference:	

Overview conducted technology audit					
Alternator / Generator:			examined	limited	
Battery / accumulator:			examined	limited	
oil loss:			examined	limited	
air conditioning:			examined	limited	
lighting system:			examined	limited	
coupling:			examined	limited	
exhaust System:			examined	limited	
engine running:			examined	limited	
shock absorber:			examined	limited	
transmission:			examined	limited	

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*

damage



component	Damage	Rep kind
1. maintenance	Missing	Replace
2. Cargo cover	Missing	Replace
3. Sitzbank	Not possible	acceptable
4. Rear bumper	Scratch(es)	Paint
5.	Dirty	
6. Türeinstieg Hinten - Rechts	Corroded	Paint
7.	Scratch(es)	Smart repair
8. Front bumper	Wear and tear	acceptable
9. hood	Wear and tear	acceptable
10.	Wear and tear	acceptable
11. Türeinstieg Vorne - Links	Wear and tear	acceptable
12. roof	Deformed	Refurbish and paint
13. Roof frame - right	Wear and tear	acceptable

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right




rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



2. Cargo cover




3. Sitzbank



4. Rear bumper



4. Rear bumper



5.



5.



5.



6. Türeinstieg Hinten - Rechts



6. Türeinstieg Hinten - Rechts



7.



8. Front bumper



9. hood



9. hood



10.



11. Türeinstieg Vorne - Links



12. roof



12. roof



13. Roof frame - right