

# FORD Focus 2018 SW Diesel Focus SW 1.5 ecoblue ST-Line s&s 120cv



VIN NO WF0PXXGCHPKC42710 Registration Number FV440VH

MOT Date

★ 2025-02-05

Last Service

**#**-

**Number of Owners** 

**:2:**-

Last Service Mileage

**2** 

Number of Keys

P

First Registration Date

**2**019-02-26

**Odometer Reading** 

**2** 85788 km

**Country First Registered** 

**Italy** 

## **Inspection Report Summary**

Customer	BCA Lodi	Report Number	P20250923161240
Inspection Date / Place	2025-09-23 / BCA Lodi	Cosmetic Grade	3

## Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Grey	Engine Size (cc)	1499
Engine Size	1.5	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	93

## Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			

































# Equipment


Central locking	Rain sensitive windscreen wipers	Alloys wheels	Electrically folding wing mirrors
Satellite navigation	Parcel Shef	Remote central locking	Tyre Mobility Kit
Power assisted steering	Rear parking sensors	Digital Radio	Front parking sensors
Volante multifuncion	Remote adjusting wing mirrors	Trip Computer	Stability control
Mhaala 0 Turaa			

# Wheels & Tyres

## **Mounted Tires**

Tyre / Wheel Type	Summer	
	NEXEN NEXEN-N'FERA SPORT SUV	215/50//R17 - 91W / 3 mm
	NEXEN NEXEN-N'FERA SPORT SUV	215/50//R17 - 91W / 3 mm
	NEXEN NEXEN-N'FERA SPORT SUV	215/50//R17 - 91W / 3 mm
	NEXEN NEXEN-N'FERA SPORT SUV	215/50//R17 - 91W / 3 mm

# Cosmetic Damage



	Component	Damage	Comments
1	Fender / Front Right	Bodywork / Poor Previous Repair	
2	Door / Front Right	Bodywork / Poor Previous Repair	
3	Door / Back Right	Bodywork / Poor Previous Repair	
4	Rim / Back Right	Out of Bodywork / Scratch	
5	Fender / Back Right	Bodywork / Poor Previous Repair	
6	Pillar / Front Right	Bodywork / Poor Previous Repair	
7	Front Light / Front Right	Glass Break	
8	Bumper / Front	Bodywork / Poor Previous Repair	
9	Hood	Paint / Chipping	
10	Windshield / Front	Glass Break / Impact	
11	Door / Back Left	Bodywork / Dent	
12	Door / Front Left	Paint / Scratch / Line	

13	Roof	Bodywork / Poor Previous Repair
14	Panel Filling / Back Right	Interior / Scratched
15	Dashboard / Front	Interior / Scratched



1. Fender / Front Right Bodywork / Poor Previous Repair -

2. Door / Front Right Bodywork / Poor Previous Repair -



3. Door / Back Right Bodywork / Poor Previous Repair -

4. Rim / Back Right
Out of Bodywork / Scratch -



5. Fender / Back Right Bodywork / Poor Previous Repair -

6. Pillar / Front Right Bodywork / Poor Previous Repair -



7. Front Light / Front Right Glass Break -

8. Bumper / Front Bodywork / Poor Previous Repair -



9. Hood Paint / Chipping -

10. Windshield / Front Glass Break / Impact -



11. Door / Back Left Bodywork / Dent -

12. Door / Front Left Paint / Scratch / Line -



13. Roof Bodywork / Poor Previous Repair -

14. Panel Filling / Back Right Interior / Scratched -



15. Dashboard / Front Interior / Scratched -

#### **Mechanical Condition**

Engine					
Vehicle Start - up	•	Engine Starts	•		
Engine Leak Visible	•				
Clutch					
Clutch Functioning	•				
Equipments Test					
Other Equipments	<b>⊘</b>	AC / Heating System	•		
Levels					
Brakes Fluid	•	Coolant Fluid	•		
Tact Drive Increation					
Test Drive Inspection					
Other Checks					
Steering	•	Brakes	•		
Suspension	•				
Gearbox					
Manual Gearbox	•				
General					
Test Driven Status	•				
Equipments Test					
Steering   Noise / Anomaly	•				
Engine					
Power Loss	•	Fume Quantity	•		
Engine Noise	•				
<ul> <li>No troubles detected, good condition or correct tests, according to vehicle age and mileage</li> <li>Damages or malfunction detected that requires repairs by the buyer</li> <li>Not applicable</li> <li>Not tested</li> </ul>					