



Expertise

Protocol number: 39768565
Order No. / Reference: 24769021
Inspection date: 13 May 2025

Manufacturer: Ford

Model: Focus Turnier 1.5 EcoBlue Start-Stopp-System Aut. ACTIVE

VIN: WF0PXXGCHPKU57919



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Focus Turnier 1.5 EcoBlue Start-Stopp-System Aut. ACTIVE	
Vehicle Identification number	WF0PXXGCHPKU57919
Mileage (Read)	181,541 km
First registration	16 Jan 2020
Number of holders	1
Power / Engine displacement	88 kw / 1,499 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Frozen White
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	82 %
Last maintenance on / at	03/2025 at 178,613 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available
		Letter No.	FR782257
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	conditional: light/moisture/dirt	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BPV 00082		
Emission standard	EURO6;WLTP;DG;PI/CI; M, N1 I	Fine dust sticker	
Permitted total weight	1,995 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 94H	Winter tyres on Light alloy	Continental	5mm / 5mm
2)	215/55 R17 94H	Winter tyres on Light alloy	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	125/70 R16 96M	Summer tyres on Steel	Hankook	4 mm

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel

Equipment

Standard equipment

- Airbag: Passenger airbag deactivation
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated
- Tires: 7 J x 17 alloy wheels (4) with 215/55 R 17 tires
- headliner made of woven fabric, black
- Roof spoiler painted in body color
- Digital instrument panel 12.3" (31.2 cm screen diagonal)
- Front door sill trim
- Driver information system
- Lane Assistant including Lane Keeping Assist
- Electric windows front and rear
- Electric parking brake with auto-hold function
- Ford Power start function
- Luggage compartment lighting
- Luggage compartment floor, two-way adjustable
- Cruise control system
- Glove compartment, illuminated
- Back window, heater
- Interior lighting with LED technology
- Intelligent security system
- Headrests 2 front and 3 rear, height adjustable
- Charging station for mobile devices (inductive)
- LED daytime running lights
- Steering column, adjustable
- Center console "Premium" front
- Navigation: Ford Navigation, Ford SYNC 3 with AppLink, 8" touchscreen (20.3 cm) with DAB/DAB+
- Package: Comfort
- Parking pilot system front and rear
- Upholstery: Cloth
- Pre-Collision Assist
- Tire pressure monitoring system (TPMS)
- Headlight assistant with day/night sensor
- Electro-mechanical power steering
- Seats: Driver's seat height adjustable
- Seats: Front sports seats with increased lateral support
- 12 volt socket in the luggage compartment
- Carpet floor mats front and rear, velour
- Lashing eyes in the luggage compartment
- Electronic immobilizer
- Heat-insulating glazing, tinted
- Additional heating
- Anti-lock braking system (ABS) with electronic brake-force distribution (EBD)
- Attachment points behind the second row of seats
- crossover body kit
- Roof rails, black
- Diesel particulate filter (DPF)
- tachometer
- Electronic Safety and Stability Program (ESP)
- Driving mode switch, selective
- Chassis: Chassis with 30 mm increased ground clearance
- Ford ECO Coach
- FordPass Connect including eCall, Live Traffic Information (only with navigation) and Wi-Fi hotspot
- Speed limiter
- Transmission: 8-speed automatic transmission
- Tailgate, electric and sensor-controlled
- Rear window wiper
- Instrument lighting, adjustable
- Isofix mount
- honeycomb-style grille
- LED fog lights
- Steering wheel: leather steering wheel 3-spoke design
- Armrest - centre, rear
- MyKey key system (individually programmable second key)
- Emergency brake light
- Package: Family
- Package: View
- Pollen filter and dust filter
- Post-Collision Assist
- Tire repair kit
- Rear view camera with "Split View" technology
- Side windows from 2nd row and rear window, dark tinted
- Seats: Passenger seat height adjustable, manual
- Seats: Rear seat backrest
- Start-stop system
- Carpet floor mats front, velour
- Child safety lock on sliding doors
- Unfastened seat belt warning system for the 1st and 2nd row of seats
- Central/double locking

Extra equipment

- Removable trailer hitch (including ESP trailer stabilization)
- Paint finish: Frost White
- Spare wheel: Emergency wheel (max. 80 km/h permitted when used.)



- Package: Technology II (Traffic jam assistant with stop & go function - lane pilot - intelligent cruise control, adaptive iACC - with traffic sign recognition - wrong-way driver warning function - evasive steer assistance (ESA) - high beam assist (in conjunction with intelligent LED headlights with glare-free high beam assistant) - fatigue warning)
- Seats: Ford ergonomic seat with fabric upholstery (front seats 18-way adjustable: - length, height and inclination of the seat, extendable thigh support - adjustable backrest - lumbar support 4-way electrically adjustable - headrest 4-way adjustable)

Brief expert findings

Documents submitted	At the time of the inspection, the registration certificate part 2 (letter) was available, but the registration certificate part 1 (certificate) was not available. (Copy)
VIN comparison	The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.
Inspection	A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. Lifting equipment and a pit were available for examining the vehicle.
Test drive	No test drive/maneuvering was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Rear of vehicle	Key trailer hitch - Broken / torn - Replace
2	Equipment	Vehicle key (Batterie) - Empty - Replace
3	Seat - front	Seat cover - left side - Soiled - Clean
4	Seat - front	Seat cover - right side - Soiled - Clean
5	Interior	Interior - Odour - Ozone treatment
6	Bonnet	Insulation lining - Holes - Replace
7	Body	Body - Soiled - Conditioning
8	Wheel / tyres	Alloy rim - rear left side (Materialabtrag) - Damaged - Replace
9	Wheel / tyres	Alloy rim - front left side (Materialabtrag) - Damaged - Replace
10	Rear bumper	Rear bumper (verformt) - Scratched - Repair and paint
11	Door - rear left side	Door - Dent / paintcoat damage - Repair and paint
12	Body	Body - Damage by hail - repair according to calculation

Wear and tear

No.	Component group	Description
1	Interior	Cargo area floor - Scratched - No deduction
2	Trim / covers	Cargo area - lining - right side - Scratched - No deduction
3	Trim / covers	Cargo area - lining -left side - Scratched - No deduction
4	Wheel / tyres	Alloy rim - rear right side - Corrosion - No deduction
5	Wheel / tyres	Alloy rim - front right side - Scratched - No deduction
6	Door - front right side	Door edge - Scratched - No deduction
7	Vehicle glazing	Windscreen (Kratzer) - Stone chips - No deduction
8	Vehicle glazing	Rear window - Scratched - No deduction

The vehicle shows signs of wear commensurate with its age and use.



Accident damages

No. Accident

- 1 Front, Side - left

Repainting

No. Repainting

- 1 Roof rail - left side, Professionally carried out, Invoice of repair done Non-existent
- 2 Roof rail - right side, Professionally carried out, Invoice of repair done Non-existent
- 3 Mudguard - left side, Professionally carried out, Invoice of repair done Non-existent
- 4 Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent
- 5 Door - rear left side, Professionally carried out, Invoice of repair done Non-existent
- 6 Door - rear right side, Professionally carried out, Invoice of repair done Non-existent
- 7 Door - front left side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Roof rail - left side	176 µm	Roof rail - right side	165 µm
Mudguard - left side	163 µm	Side panel - rear right side	377 µm
Door - rear left side	179 µm	Door - rear right side	232 µm
Door - front left side	171 µm		

Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
(*Functional tests of driver assistance systems are not included in the scope of services!*)
- a photo documentation of the vehicle

Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.



Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkten Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung erhebliche Mehrkosten und somit Abweichung der für den Unfall ausgewiesenen Reparaturkosten nicht ausgeschlossen werden.

Motorhaube und Korflügel zeigen Fehlstellung, deshalb wurde eine Vermessung im Unfall mitaufgenommen.

Fahrzeug hat starken Hagelschaden.

Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen im demontagefreien Zustand erstellt. Es können Mehrkosten und somit Abweichung der für den Hagelschaden ausgewiesener Reparaturkosten nicht ausgeschlossen werden.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: interior 360° view ([Online link](#))



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Navigation




Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Damage 1: Rear of vehicle: Key trailer hitch - Broken / torn - Replace




Damage 1: Rear of vehicle: Key trailer hitch - Broken / torn - Replace



Damage 2: Equipment: Vehicle key (Batterie) - Empty - Replace



Damage 3: Seat - front: Seat cover - left side - Soiled - Clean



Damage 4: Seat - front: Seat cover - right side - Soiled - Clean



Damage 5: Interior: Interior - Odour - Ozone treatment



Damage 5: Interior: Interior - Odour - Ozone treatment



Damage 6: Bonnet: Insulation lining - Holes - Replace



Damage 6: Bonnet: Insulation lining - Holes - Replace



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning




Damage 7: Body: Body - Soiled - Conditioning




Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning




Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning




Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning




Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 7: Body: Body - Soiled - Conditioning



Damage 8: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Damaged - Replace



Damage 8: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Damaged - Replace



Damage 9: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Damaged - Replace



Damage 9: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Damaged - Replace



Damage 9: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Damaged - Replace



Damage 10: Rear bumper: Rear bumper (verformt) - Scratched - Repair and paint



Damage 10: Rear bumper: Rear bumper (verformt) - Scratched - Repair and paint



Damage 10: Rear bumper: Rear bumper (verformt) - Scratched - Repair and paint



Damage 10: Rear bumper: Rear bumper (verformt) - Scratched - Repair and paint



Damage 11: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Damage 11: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Damage 11: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Damage 11: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Damage 11: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint




Damage 12: Body: Body - Damage by hail - repair according to calculation



Damage 12: Body: Body - Damage by hail - repair according to calculation




Damage 12: Body: Body - Damage by hail - repair according to calculation



Damage 12: Body: Body - Damage by hail - repair according to calculation



Damage 12: Body: Body - Damage by hail - repair according to calculation



Damage 12: Body: Body - Damage by hail - repair according to calculation



Damage 12: Body: Body - Damage by hail - repair according to calculation




Damage 12: Body: Body - Damage by hail - repair according to calculation



Damage 12: Body: Body - Damage by hail - repair according to calculation



Damage 12: Body: Body - Damage by hail - repair according to calculation



Damage 12: Body: Body - Damage by hail - repair according to calculation



Damage 12: Body: Body - Damage by hail - repair according to calculation



Damage 12: Body: Body - Damage by hail - repair according to calculation



Damage 12: Body: Body - Damage by hail - repair according to calculation



Damage 12: Body: Body - Damage by hail - repair according to calculation




Damage 12: Body: Body - Damage by hail - repair according to calculation



Damage 12: Body: Body - Damage by hail - repair according to calculation




Damage 12: Body: Body - Damage by hail - repair according to calculation



Damage 12: Body: Body - Damage by hail - repair according to calculation




Wear and tear 8: Vehicle glazing: Rear window - Scratched - No deduction



Wear and tear 8: Vehicle glazing: Rear window - Scratched - No deduction



Wear and tear 8: Vehicle glazing: Rear window - Scratched - No deduction



Wear and tear 8: Vehicle glazing: Rear window - Scratched - No deduction




Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left




Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left




Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left




Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left




Accident 1: Front, Side - left



Accident 1: Front, Side - left




Accident 1: Front, Side - left




Accident 1: Front, Side - left




Accident 1: Front, Side - left




Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left



Accident 1: Front, Side - left




Accident 1: Front, Side - left



Accident 1: Front, Side - left



Repainting 1: Roof rail - left side



Repainting 1: Roof rail - left side



Repainting 2: Roof rail - right side



Repainting 2: Roof rail - right side



Repainting 3: Mudguard - left side



Repainting 3: Mudguard - left side



Repainting 4: Side panel - rear right side



Repainting 4: Side panel - rear right side



Repainting 5: Door - rear left side



Repainting 5: Door - rear left side



Repainting 6: Door - rear right side



Repainting 6: Door - rear right side



Repainting 7: Door - front left side



Repainting 7: Door - front left side