



FORD FOCUS CLIPPER: 1YDB589

Vinnumber:	WF0PXXGCHPLK04508	Versionname:	1.5 EcoBlue 88kW Connected
First Registrationdate:	24/07/2020	Fiscalpower:	
Expertise Mileage:	85671	Power Kw:	88
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3507
Fueltype:	Diesel		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	1	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	No Tow bar
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Degree of wear

205/60/16/96 H				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/60 R 16 96 H
Tyre size FR				205/60 R 16 96 H
Tyre size RL				205/60 R 16 96 H
Tyre size RR				205/60 R 16 96 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Emergency spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	462,71
Ignition key, Missing, Replace	341,22



Seat cover FR, Dirty, Cleaning

28,43



Bonnet, Dent(s), Acceptable

0,00



Windscreen, Stone chip(s), Windscreen repair

0,00



Door FL, Scratch(es), Acceptable

0,00




Door RL, Dent(s), Paintless dent repair

93,06



Bumper R, Scratch(es), Acceptable

0,00



Wing RR, Dent(s), Acceptable

0,00



Door RR, Repaired, Acceptable

0,00



Roof, Chemical polution, Repair and paint (complete)

0,00

