



Expertise

Protocol number: 41320665  
Order No. / Reference: 25144793  
Inspection date: 27 Aug 2025

|                        |                                                                   |
|------------------------|-------------------------------------------------------------------|
| Manufacturer: Ford     | Model: Focus Turnier 2.0 EcoBlue Start-Stopp-System Aut. TITANIUM |
| VIN: WF0PXXGCHPLL32849 |                                                                   |



| Vehicle details                                                 |                           |
|-----------------------------------------------------------------|---------------------------|
| Manufacturer / Type / Model / Equipment                         |                           |
| Ford Focus Turnier 2.0 EcoBlue Start-Stopp-System Aut. TITANIUM |                           |
| Vehicle Identification number                                   | WF0PXXGCHPLL32849         |
| Mileage (Read)                                                  | 148,459 km                |
| First registration                                              | 6 Oct 2020                |
| Number of holders                                               | 1                         |
| Next periodical technical inspection                            | 09/2025                   |
| (Report on hand)                                                |                           |
| Power / Engine displacement                                     | 110 kw / 1,995 ccm        |
| Fuel type / Cylinder                                            | Diesel / 4                |
| Gearbox / Number of gears                                       | Automatic / 8             |
| Type of drive                                                   | Front drive               |
| Type of vehicle                                                 | Station wagon             |
| Colour / colour code                                            | Obsidian-Schwarz Metallic |
| Doors / Seats                                                   | 5 / 5                     |
| Upholstery type                                                 | Cloth                     |
| Colour of upholstery                                            | Anthracite                |



Vehicle details

|                                           |                              |                         |                                                           |
|-------------------------------------------|------------------------------|-------------------------|-----------------------------------------------------------|
| Maintenance booklet / proof               | digital proof / complete     | Next maintenance in     | 0 %                                                       |
| Last maintenance on / at                  | 07/2024 at 118,563 km        |                         |                                                           |
| Key is / should be                        | 2 / 2                        | FZG documents           | ZB#2 (B) was available (copy), ZB#1 (S) was not available |
|                                           |                              | Letter No.              | FY018456                                                  |
| Previous damage / Accident                | Detectable                   | Repainting              | None detectable                                           |
| Inspection conditions                     | sufficient                   | Lifting equipment / pit | yes                                                       |
| Test drive                                | Not performed                | Engine function test    | Performed                                                 |
| Manufacturer key number/ type code number | 8566 / BQQ 00171             |                         |                                                           |
| Emission standard                         | EURO6;WLTP;DG;PI/CI; M, N1 I | Fine dust sticker       |                                                           |
| Permitted total weight                    | 2,105 kg                     | Empty weight            |                                                           |

Tyres

Mounted tyres

| #  | Tyre size      | Type of tyre                | Manufacturer | Tread depth |
|----|----------------|-----------------------------|--------------|-------------|
| 1) | 205/60 R16 92V | Summer tyres on Light alloy | Continental  | 4mm / 4mm   |
| 2) | 205/60 R16 92V | Summer tyres on Light alloy | Continental  | 5mm / 5mm   |

Replacement

| Typ | Tyre size | Type of tyre            | Manufacturer | Tread depth |
|-----|-----------|-------------------------|--------------|-------------|
|     | Tirefit   | Expiration date 02/2028 |              |             |

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel



## Equipment

### Standard equipment

- Airbag: Passenger airbag deactivation
- Anti-lock braking system (ABS) with electronic brake-force distribution (EBD)
- Attachment points behind the second row of seats
- Chrome decor
- Roof console with glasses storage compartment
- Roof spoiler painted in body color
- tachometer
- Electronic Safety and Stability Program (ESP)
- Driving mode switch, selective
- Electric windows front and rear
- Ford ECO Coach
- FordPass Connect including eCall, Live Traffic Information (only with navigation) and Wi-Fi hotspot
- Speed limiter
- Transmission: 8-speed automatic transmission
- Back window, heater
- Interior lighting with LED technology
- Intelligent security system
- Headrests 2 front and 3 rear, height adjustable
- LED taillights
- Steering wheel: leather steering wheel 3-spoke design
- Armrest - centre, rear
- MyKey key system (individually programmable second key)
- Fog light
- Emergency brake light
- Package: View
- Pollen filter and dust filter
- Post-Collision Assist
- Tire repair kit
- Rear view camera with "Split View" technology
- Seats: Passenger seat height adjustable, manual
- Seats: Rear seat backrest
- Start-stop system
- Carpet floor mats front and rear, velour
- Unfastened seat belt warning system for the 1st and 2nd row of seats
- Additional heating
- Ambient lighting at the front
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated
- Tires: 6.5 J x 16 alloy wheels (4) with 205/60 R 16 tires
- Woven fabric headliner
- Roof rails, aluminum
- Diesel particulate filter (DPF)
- Front door sill trim
- Driver information system
- Lane Assistant including Lane Keeping Assist
- Electric parking brake with auto-hold function
- Ford Power start function
- Luggage compartment lighting
- Luggage compartment floor, two-way adjustable
- Cruise control system
- Glove compartment, illuminated
- Rear window wiper
- Instrument lighting, adjustable
- Isofix mount
- Charging station for mobile devices (inductive)
- LED daytime running lights
- Steering column, adjustable
- Center console "Premium" front
- Navigation: Ford Navigation, Ford SYNC 3 with AppLink, 8" touchscreen (20.3 cm) with DAB/DAB+
- Package: Comfort
- Parking pilot system front and rear
- Upholstery: Cloth
- Pre-Collision Assist
- Tire pressure monitoring system (TPMS)
- Electro-mechanical power steering
- Seats: Driver's seat height adjustable
- Seats: Front sports seats with increased lateral support
- 12 volt socket in the luggage compartment
- Lashing eyes in the luggage compartment
- Electronic immobilizer
- Central/double locking

### Extra equipment

- Anti-theft alarm system including double locking
- Paint finish: Obsidian Black Metallic
- LED headlights (with LED taillights)
- Package: Winter (heated windscreen - heated steering wheel - front seats, individually and variably heated)
- Cigarette lighter and ashtray in the center console
- Tailgate, electric and sensor-controlled (opening and closing via foot movement - Ford Key Free system (keyless unlocking/locking))
- Side windows from 2nd row and rear window, dark tinted
- Safety net to separate the passenger and luggage compartments



## Brief expert findings

|                      |                                                                                                                                                                          |
|----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the registration certificate Part 2 (letter) was available, but the registration certificate Part 1 (certificate) was not. (Copy)         |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was verified during the inspection by the undersigned. |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and a pit were available for examining the vehicle.                    |
| Test drive           | No test drive/maneuvering was carried out during the inspection of the vehicle.                                                                                          |
| Engine function test | An engine test run was performed.                                                                                                                                        |

## Value reducing factors

| No. | Component group              | Description                                                             |
|-----|------------------------------|-------------------------------------------------------------------------|
| 1   | Fuel system                  | Tank flap - Scratch(es) - Smart repair                                  |
| 2   | Engine                       | Engine (Rohr Ölabscheider) - Damage caused by marten / rodent - Replace |
| 3   | Door - rear left side        | Door - Scratch(es) - Smart repair                                       |
| 4   | Boot lid / rear door         | Boot lid - dent(s) - Smooth repair work                                 |
| 5   | Front bumper                 | Spoiler (Links und Rechts) - Scratch(es) - Replace                      |
| 6   | Side panel - rear right side | Sill - Dent / paintcoat damage - Smart repair                           |
| 7   | Engine                       | Engine cover - top / cover - Damage caused by marten / rodent - Replace |
| 8   | Misc.                        | Inspection / maintenance - Due - Perform                                |
| 9   | Boot lid / rear door         | Rear spoiler (Anätzung) - Paint defect - Paint                          |
| 10  | Door - rear right side       | Door - Scratch(es) - Paint                                              |
| 11  | Front bumper                 | Front bumper - Scratch(es) - Paint                                      |
| 12  | Bonnet                       | Bonnet (Vogelkotverätzung + Kratzer) - Paint defect - Paint             |
| 13  | Roof                         | Roof (Vogelkotverätzung) - Paint defect - Paint                         |

## Wear and tear

| No. | Component group             | Description                                             |
|-----|-----------------------------|---------------------------------------------------------|
| 1   | Trim / covers               | Floor mats - Scratched - No deduction                   |
| 2   | Sill - left side            | Sill - Scratch(es) - No deduction                       |
| 3   | Body                        | Body (Waschanlagenkratzer) - Scratch(es) - No deduction |
| 4   | Trim / covers               | Boot lid - interior trim - Scratched - No deduction     |
| 5   | Rear bumper                 | Rear bumper ((Polieren)) - Scratched - No deduction     |
| 6   | Side panel - rear left side | Side panel ((Polieren)) - Scratch(es) - No deduction    |

The vehicle shows signs of wear commensurate with its age and use.

## Previous damages

| No. | Previous damage                                     | Extent of damage (Net) |
|-----|-----------------------------------------------------|------------------------|
| 1   | Rear, Provided by user / customer, from 19 May 2025 | 3.292,41 €             |



## Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features  
*(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.  
*(Functional tests of driver assistance systems are not included in the scope of services!)*
- a photo documentation of the vehicle

## Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

## Comments

Marderschaden im Motorraum-weitere nicht sichtbare Schäden nicht ausgeschlossen





**Figure 1:** Diagonal front (left)



**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)



**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear





Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: interior 360° view



Figure 10: Cargo area





Figure 11: VIN



Figure 12: Mounted tyres



### Figure 14: Documents



**Figure 16: Documents**



**Figure 18: Misc.**





Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.





Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Damage 1: Fuel system: Tank flap - Scratch(es) - Smart repair



Damage 1: Fuel system: Tank flap - Scratch(es) - Smart repair






**Damage 2:** Engine: Engine (Rohr Ölabscheider) - Damage caused by marten / rodent - Replace



**Damage 2:** Engine: Engine (Rohr Ölabscheider) - Damage caused by marten / rodent - Replace



**Damage 3:** Door - rear left side: Door - Scratch(es) - Smart repair



**Damage 3:** Door - rear left side: Door - Scratch(es) - Smart repair



**Damage 4:** Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



**Damage 4:** Boot lid / rear door: Boot lid - dent(s) - Smooth repair work






**Damage 5:** Front bumper: Spoiler (Links und Rechts) - Scratch(es) - Replace



**Damage 5:** Front bumper: Spoiler (Links und Rechts) - Scratch(es) - Replace



**Damage 5:** Front bumper: Spoiler (Links und Rechts) - Scratch(es) - Replace



**Damage 6:** Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



**Damage 6:** Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



**Damage 6:** Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair





**Damage 7:** Engine: Engine cover - top / cover - Damage caused by marten / rodent - Replace



**Damage 7:** Engine: Engine cover - top / cover - Damage caused by marten / rodent - Replace



**Damage 7:** Engine: Engine cover - top / cover - Damage caused by marten / rodent - Replace



**Damage 8:** Misc.: Inspection / maintenance - Due - Perform



**Damage 8:** Misc.: Inspection / maintenance - Due - Perform



**Damage 9:** Boot lid / rear door: Rear spoiler (Anätzung) - Paint defect - Paint






**Damage 9:** Boot lid / rear door: Rear spoiler (Anätzung) - Paint defect - Paint




**Damage 9:** Boot lid / rear door: Rear spoiler (Anätzung) - Paint defect - Paint



**Damage 10:** Door - rear right side: Door - Scratch(es) - Paint



**Damage 10:** Door - rear right side: Door - Scratch(es) - Paint



**Damage 10:** Door - rear right side: Door - Scratch(es) - Paint



**Damage 10:** Door - rear right side: Door - Scratch(es) - Paint



**Damage 10:** Door - rear right side: Door - Scratch(es) - Paint



**Damage 11:** Front bumper: Front bumper - Scratch(es) - Paint



**Damage 11:** Front bumper: Front bumper - Scratch(es) - Paint



**Damage 11:** Front bumper: Front bumper - Scratch(es) - Paint



**Damage 11:** Front bumper: Front bumper - Scratch(es) - Paint



**Damage 11:** Front bumper: Front bumper - Scratch(es) - Paint







**Damage 11:** Front bumper: Front bumper - Scratch(es) - Paint



**Damage 11:** Front bumper: Front bumper - Scratch(es) - Paint




**Damage 11:** Front bumper: Front bumper - Scratch(es) - Paint



**Damage 12:** Bonnet: Bonnet (Vogelkotverätzung + Kratzer) - Paint defect - Paint



**Damage 12:** Bonnet: Bonnet (Vogelkotverätzung + Kratzer) - Paint defect - Paint




**Damage 12:** Bonnet: Bonnet (Vogelkotverätzung + Kratzer) - Paint defect - Paint






**Damage 12:** Bonnet: Bonnet (Vogelkotverätzung + Kratzer) - Paint defect - Paint



**Damage 12:** Bonnet: Bonnet (Vogelkotverätzung + Kratzer) - Paint defect - Paint



**Damage 12:** Bonnet: Bonnet (Vogelkotverätzung + Kratzer) - Paint defect - Paint



**Damage 12:** Bonnet: Bonnet (Vogelkotverätzung + Kratzer) - Paint defect - Paint



**Damage 12:** Bonnet: Bonnet (Vogelkotverätzung + Kratzer) - Paint defect - Paint



**Damage 13:** Roof: Roof (Vogelkotverätzung) - Paint defect - Paint





**Damage 13:** Roof: Roof (Vogelkotverätzung) - Paint defect - Paint



**Damage 13:** Roof: Roof (Vogelkotverätzung) - Paint defect - Paint



# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0PXXGCHPLL32849

Hersteller / Modell: FORD FORD Focus Turnier 2.0 EcoBlue Start-Stopp-System Aut.  
TITANIUM

| Datum      | KM-Stand | Beschreibung                                                                                                                                                                                               |
|------------|----------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 14.02.2025 | 135.170  | Batterie ern; Systemtest/Eigendiagnose                                                                                                                                                                     |
| 18.07.2024 | 118.563  | Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                              |
| 06.09.2023 | 89.491   | AU; Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremssattel ern/inst; Bremsscheiben + Klötze v; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges |
| 08.09.2022 | 60.485   | Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                              |
| 28.09.2021 | 31.038   | Kleine Inspektion; Motoröl b. Wartung; Ölfilter ern; Wartung Sonstiges                                                                                                                                     |