



status report

customer: Bank 11, Neuss
contract number: 851756830
reference:

vehicle data

Ford Focus Turnier Titanium

Vehicle identification number	WF0PXXGCHPLL50197	mileage read:	41646 km
First Registration / construction year:	23.09.2021 / 2020	Visit Date / place of birth:	18.09.2025 Neuss
Bodywork:	cars	Re - import:	yes
Body type:	hatchback	KBA no. :	8566//BUE
Fuel / emission class:	gasoline / € 6	transmission type:	6 speed manual transmission
Displacement / power:	999 ccm / 114 kW (155 PS)	Engine:	front-wheel drive
paint:	Panther-Blau Metallic	Number of previous owners:	Unbekannt
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	yes	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
SD Card	2	yes / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	All season tires	aluminum
1st axis - Left / states .	Kumho	205/60/R16/96V 3 mm
1st axis - right / states .	Kumho	205/60/R16/96V 3 mm
2nd axis - Left / states .	Kumho	205/60/R16/96V 5 mm
2nd axis - right / states .	Kumho	205/60/R16/96V 5 mm
traffic Safety:	not roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • Airbag deactivated • Anti -lock braking system (ABS) • Audio navigation system Ford with AppLink
<i>Radioempfang digital (DAB), Audiobedienung am Lenkrad, 6 Lautsprecher, Sprachsteuerung und Bluetooth-Schnittstelle, Vorrüstung Mobiltelefon/Handy mit Bluetooth-/USB-Schnittstelle, Fahrassistenz-System: Sicherheitssystem SYNC mit automatischem Notruf, Ford SYNC 3 mit Navigation, Farbdisplay (8 Zoll)</i> • Electric wing mirror . adjustable and heatable • On-board / computer usage • Chrome surround side windows • Roof rails (aluminum) • Dimmer instrument lighting • Elektron . Stability Program (ESP) • Driving Assistance System Brake Assist •
<i>Fahrassistenz-System: Auffahrwarnsystem</i> • Color display for on-board computer • FordPass Connect inkl. eCall
<i>Fahrassistenz-System: Sicherheitssystem SYNC mit automatischem Notruf</i> • Luggage office cover / shade • Transmission 6-speed - Type 6MX65 • Dust and pollen filter • Smart Speed Limiter
<i>Geschwindigkeits-Begrenzeranlage</i> • Body 5-doors • Headrests behind mechan . adjustable (3 pieces) • Adjustable load compartment floor • Steering column (steering wheel) height / telescopic adjustment | <ul style="list-style-type: none"> • Ambient lighting front (LED) • Anti-Slip Regulation (ASR) • Electric wing mirror . anklappbar
<i>Bodenleuchte im Außenspiegel</i> • Flashing light integrated in exterior mirrors • Spectacles compartment in roof liner / roof console • Headlining cloth • Roof spoiler body color • Electr . Brake-force Distribution • Driving Assistance System Hill Start Assistant (Hill Holder) • Fahrassistenz-Post-Collision-System • • Electric windows front and rear with convenience closing • Velour floor mats • Cruise control system (cruise control) • LED taillights • Intelligent Protection System (IPS)
<i>Airbag Fahrer-/Beifahrerseite, Kopf-Schulter-Airbag vorn und hinten, Seitenairbag vorn, 3-Punkt-Sicherheitsgurt hinten, Gurtstraffer</i> • Isofix admissions for child seat • Comfort Package
<i>Scheibenwischer mit Regensensor, Scheinwerfer mit Ausschaltverzögerung, Klimaautomatik 2-Zonen, KeyFree-System, Power KeyFree-Startfunktion, Innenspiegel mit Abblendautomatik</i> • 4-way adjustable front headrests • Steering wheel (leather 3-spoke) • LM rims |
|--|---|

• Mild-Hybrid ... kW (Motor 1,0 Ltr. - 114 kW EcoBoost) • Center console Premium <i>Mittelarmlehne vorn mit Staufach und 12V-Anschluß, Getränkehalter vorn</i> • Fog lights with static cornering light • Park Pilot system , front and rear • Spare wheel as an emergency wheel • Low-pollutant according to the Euro 6d emissions standard • Gear shift indicator • Electric power steering • Front left seat height adjustment <i>Lendenwirbelstütze Sitz vorn links</i> • Sun visor with mirror left (illuminated) • Sports seats, front • Socket (12V connection) in the boot / load compartment • tinted glazing • Warning device for seat belts front	• Rear center armrest • My Key (2nd vehicle keys can be programmed) • Parking brake electric with auto-hold function • Tire Pressure Monitoring System • Back seat armrest partly / hinged (6040) • Gearshift / selector lever leather • Headlamp Assist with day / night sensor • Visibility Package <i>Scheibenwischer mit Regensensor, Frontscheibe heizbar, Innenspiegel mit Abblendautomatik</i> • Front right seat height adjustment <i>Lendenwirbelstütze Sitz vorn rechts</i> • Sun visor with mirror right • Start / Stop system • Daytime Running Lights LED • Warning system for rear seat belts • Central locking with remote control
---	--

special Features	
• Outside mirror with Blind Spot Assist <i>Fahrassistenz-System: Totwinkel-Assistent, Cross Traffic Alert und Notbremsfunktion</i> • Metallic paint • LED headlights <i>Nebelscheinwerfer mit statischem Abbiegelicht, Heckleuchten LED</i> • Winter package <i>Frontscheibe heizbar, Sitzheizung vorn, Lenkrad heizbar</i>	• Induction charging cradle for mobile devices • Rear view camera with split view • Glazing behind darkened (privacy glass)

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable

reference:

Note Road Safe: Reifen hr beschädigt.

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross: If not properly repaired

The vehicle repaired previous damage have been observed on the body outer skin that are exposed and apparently with no disassembly of components with residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.

Layers of paint thickness measurement:

Out of tolerance

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
oil loss:			examined limited	examined limited	
air conditioning:			not possible	lighting system:	
coupling:			examined limited	examined limited	
engine running:			examined limited	exhaust System:	
transmission:			examined limited	not possible	

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning could not be checked during the inspection . **Due to weather conditions not possible examination.
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could not be checked during the inspection .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Alters-, Transport- und Laufleistungsbedingte Gebrauchsspuren vorhanden. Kosten- und Schadenserweiterung möglich.

damage



component	Damage	Rep kind
1. Front fender - left	Subsequently painted	acceptable
2. Front door - left	Subsequently painted	acceptable
3. Rim rear - right	Damaged	Smart repair
4. tire rear - right	Damaged	Replace
5. tire front - right	Worn	Replace
6. tire front - right	Worn	Replace
7. maintenance	Due	Replace
8.	Dirty	
9. Sidewall - Rear - right		Refurbish and paint
10. Door trim Rear - right	Stain	
11. Rear bumper	Scratch(es)	Refurbish and paint
12. roof	Delle	Smart repair
13. Front door - left	Execution defect	Paint
14. Front fender - left	Execution defect	Refurbish and paint
15. Windshield	Wear and tear	acceptable

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims




rims



engine compartment



service book



Others



Navigation system



1. Front fender - left



2. Front door - left



3. Rim rear - right



3. Rim rear - right



4. tire rear - right



4. tire rear - right



5. tire front - right



6. tire front - right




8.




8.



9. Sidewall - Rear - right



9. Sidewall - Rear - right



9. Sidewall - Rear - right



10. Door trim Rear - right



10. Door trim Rear - right



11. Rear bumper




11. Rear bumper



11. Rear bumper



11. Rear bumper




11. Rear bumper



11. Rear bumper




12. roof



12. roof



13. Front door - left



13. Front door - left



13. Front door - left



14. Front fender - left




14. Front fender - left



14. Front fender - left



15. Windshield



15. Windshield