


Vehicle details

VIN	WF0TXXWPG TLK76825	Brand	FORD	Maintenance date	-
Licence Plate	L611TH	Model	Tourneo Connect 1,5 TDCi Titanium 74KW	Maintenance mileage	-
Registration date	11/09/2020	Year	1000	Exterior Color	White Solid
Odometer	95 296 km	Engine size	1499	interior Color	Black
Fuel	Diesel	Body Type	Passenger van	Next technical inspection	01/09/2025
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details


Inspection date	03/03/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Panoramic roof	✓
Anti-fog lights	✓
Front radars	✓
Reversing radars	✓
Reversing camera	✓
Tow	✓

Removable element




Technical Document

User manual	✓
Log books	✓
Spare key	✓
Remote key	✓

Tyres

Winter kit

Pirelli 205/60/16 H Winter 5.8 mm



Pirelli 205/60/16 H Winter 5.9 mm



Pirelli 205/60/16 H Winter 7.4 mm

Pirelli 205/60/16 H Winter 7.3 mm

Exterior

1		Part	Windscreen
		Position	-
		Damages	Stone impact
		Severity	Diameter (mm) > 10
		Repair mode	Replace
2		Part	Bonnet
		Position	-
		Damages	Dent & Chips
		Severity	-
		Repair mode	Repair

3



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

4



Part	Door
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Repair

5



Part	Door
Position	Side left
Damages	Scratched
Severity	-
Repair mode	For info

7



Part	Tailgate / Boot door
Position	-
Damages	Scratched
Severity	-
Repair mode	Repair

8



Part	Bumper
Position	Back
Damages	Broken
Severity	-
Repair mode	Replace

9



Part	Bumper
Position	Back right
Damages	Broken
Severity	-
Repair mode	Replace

10



Part	Side panel
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

11



Part	Door
Position	Side right
Damages	Scratched
Severity	-
Repair mode	For info

12



Part	Door
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

13



Part	Wing
Position	Front right
Damages	Dented
Severity	-
Repair mode	Repair

14



Part	Door sill
Position	Side right
Damages	Scratched
Severity	-
Repair mode	Repair

15



Part	Exterior door mirror shell
Position	Right
Damages	Scratched
Severity	-
Repair mode	Repair

Interior damage

6



Part	Interior cleaning
Position	-
Damages	Not carried out
Severity	-
Repair mode	Lumpsum

Others



16



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks

17



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Plastic paint