



FORD Ka 2009 Diesel
ka 1.3 tdcI + Esp/Tcs 75cv E5

VIN NO WF0UXXLTRUDM12602
Registration Number EP208VW



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-04-09	-	-	194924 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2013-04-11	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250926111406
Inspection Date / Place	2025-09-26 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Silver	Engine Size (cc)	1248
Engine Size	1.2	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour	Grey	No of Seats	4
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	112

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Digital Radio	Remote central locking	Stability control
Power assisted steering	Parcel Shef	Trip Computer	


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Summer	
	NOKIAN NOKIAN-ILINE	175/65//R14 - 82T / 3 mm
	NOKIAN NOKIAN-ILINE	175/65//R14 - 82T / 3 mm
	NOKIAN NOKIAN-ILINE	175/65//R14 - 82T / 3 mm
	NOKIAN NOKIAN-ILINE	175/65//R14 - 82T / 3 mm

Cosmetic Damage

18 Danni



7 Danni



Component		Damage	Comments
1	Seat Cushion / Front Right	Interior / Burn	
2	Dashboard / Front	Interior / Warning Light ON	
3	Dashboard / Front	Interior / Warning Light ON	
4	Dashboard / Front	Interior / Warning Light ON	
5	Seat / Front Left	Interior / Burn	
6	Seat / Front Left	Interior / Ripped	
7	Seat / Front Left	Interior / Ripped	
8	Windshield / Front	Glass Break / Impact	
9	Hood	Bodywork / Dent	
10	Hood	Paint / Chipping	
11	Bumper / Front	Bodywork / Breakage	
12	Fender / Front Left	Paint / Scratch / Line	

13	Fender / Front Left	Bodywork / Poor Previous Repair
14	Mirror Shell / Front Left	Paint / Scratch / Line
15	Door / Front Left	Bodywork / Dent
16	Fender / Back Left	Bodywork / Dent
17	Fender / Back Left	Bodywork / Dent
18	Back Light / Left	Glass Break
19	Bumper / Back	Bodywork / Dent
20	Tailgate	Bodywork / Dent
21	Fender / Back Right	Bodywork / Dent
22	Door / Front Right	Bodywork / Dent
23	Fender / Front Right	Bodywork / Dent
24	Roof	Bodywork / Dent
25	Mirror Shell / Front Right	Paint / Scratch / Line



1. Seat Cushion / Front Right
Interior / Burn -



2. Dashboard / Front
Interior / Warning Light ON -



3. Dashboard / Front
Interior / Warning Light ON -



4. Dashboard / Front
Interior / Warning Light ON -



5. Seat / Front Left
Interior / Burn -



6. Seat / Front Left
Interior / Ripped -



7. Seat / Front Left
Interior / Ripped -



8. Windshield / Front
Glass Break / Impact -



9. Hood
Bodywork / Dent -



10. Hood
Paint / Chipping -



11. Bumper / Front
Bodywork / Breakage -




12. Fender / Front Left
Paint / Scratch / Line -



13. Fender / Front Left
Bodywork / Poor Previous Repair -



14. Mirror Shell / Front Left
Paint / Scratch / Line -




15. Door / Front Left
Bodywork / Dent -



16. Fender / Back Left
Bodywork / Dent -



17. Fender / Back Left
Bodywork / Dent -



18. Back Light / Left
Glass Break -



19. Bumper / Back
Bodywork / Dent -



20. Tailgate
Bodywork / Dent -



21. Fender / Back Right
Bodywork / Dent -



22. Door / Front Right
Bodywork / Dent -



23. Fender / Front Right
Bodywork / Dent -



24. Roof
Bodywork / Dent -



25. Mirror Shell / Front Right
Paint / Scratch / Line -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Other Checks			
Brakes	✓	Steering	✓
Suspension	!		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	!
Engine Noise	!		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓	Test Drive Comment	SPIA MOTORE ACCESA.

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested