



Hüsges Gruppe®
Die Gutachter

status report

customer: BCA Autoauktionen GmbH

reference:

vehicle data

Ford Transit Custom Kasten 290 L1 Sport

Vehicle identification number	WF0YXXTTGYKP54683	mileage read:	114595 km
First Registration / construction year:	03.02.2020 / 2020	Visit Date / place of birth:	08.09.2025 Hoppegarten
Bodywork:	transporter	Re - import:	no
Body type:	van	KBA no. :	8566//BSD
Fuel / emission class:	diesel / € 6	transmission type:	manual transmission
Displacement / power:	1997 ccm / 136 kW (185 PS)	Engine:	front-wheel drive
paint:	Obsidian-Schwarz Metallic	Number of previous owners:	1
Doors / seats:	4 / 3	number keys:	2
Next HU / AU:	- / -	cushion type:	Leather / fabric
Service book available:	no	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle documents:	Eg II (veh - letter)	state outside:	3 - Average
visit condition:	-	condition inside:	2 - Good
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	2	no / 6	- / -
☒ Fernbed . Auxiliary heating	☒ partition net	☒ Wind Deflector	☒ AHK fixed
☒ AHK removable	☒ AHK swivel	☒ AHK key	☒ Fernbed . entertainment
☒ headphone	☒ Load compartment cover	☒ LED headlights	☒ navigation system
☒ Persenning	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	Winter tires	Steel with wheel cover
1st axis - Left / states .	Semperit	235/65/16/115/113R 6 mm
1st axis - right / states .	Semperit	235/65/16/115/113R 6 mm
2nd axis - Left / states .	Semperit	235/65/16/115/113R 6 mm
2nd axis - right / states .	Semperit	235/65/16/115/113R 6 mm
traffic Safety:	roadworthy	
spare wheel:	vorhanden	
state spare wheel:	-	

standard equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • Cornering in the spotlight • Airbag driver • Acceleration skid control (ASR) • Indicator integrated into mirrors • board computer • Electr . Brakeforce Distribution (EBD) • Electron. Traction control • • Power windows • Transmission 6-speed • Lockable glove compartment • pollen filter • Karosserievariante Normal roof • fender Flares • Hold high partition behind the driver and passenger , with no windows with through-loading facility down • Truck admission • facelift • Parkpilotsystem • Wheelbase 2933 mm • • Low emissions according to Euro 6d TEMP emission standard • Windscreen wipers with interval switching, adjustable • Mud flaps, front and rear • Side moldings wide (side plating) • Seat package 34 driver's seat (4 positions) - passenger double seat including seat heating, partial leather . <p><i>Seitenairbag, Sitze im Fahrerhaus: Fahrersitz heizbar, Sitze</i></p> | <ul style="list-style-type: none"> • Airbag • Anti- lock braking system (ABS) • Drive Front Wheel Drive • Vinyl flooring in load / passenger compartment • entrance lights • Electron. Stability Program (ESP) • Driving Assistance System Hill Start Assist • Driver assistance system Crosswind Assist • Front bumper • • rear apron • Body / Structure box • air Conditioning • Cargo area protection package <i>Verkleidung im Lade-/FG-Raum: hoch</i> • Steering column (steering wheel) height / longitudinally adjustable • LM rims • Motor 2.0 Ltr. - 136 kW TDCi CAT • Park Pilot system , front and rear <i>Nebelscheinwerfer</i> • Tire pressure monitoring system • RuÃypartikelfilter • Gearshift / selector lever leather • Sliding load / passenger compartment right • Side moldings • Side skirts sports design • Special Modellsport • Sports Styling Package <i>Dekor-/Zierstreifen, Dekor-/Zierstreifen GT (auf Motorhaube), Stoßfänger in Wagenfarbe</i> |
|---|--|

<i>im Fahrerhaus: Beifahrersitz heizbar, Sitze im Fahrerhaus: Fahrersitz mit Lendenwirbelstütze</i> • Sport • Start / Stop system • Farb-style-Paket <i>Außenspiegel in Wagenfarbe, Stoßfänger in Wagenfarbe</i> • tinted glazing • Soursop (8) • Thermal insulation glazed slightly tinted	• Partially painted bumpers • Daytime running light LED • Panel in load / FG - room Vinyl • immobilizer • Central locking with remote control
--	---

special Features	
• Towbar fixed ball head <i>Anhänger-Stabilisierungs-Programm (TSA)</i> • <i>Radiovorbereitung, 4 Lautsprecher</i> • Bi-xenon headlights with cornering lights • Driving assistance system Lane departure warning • Ford SYNC 3 <i>Audio-/Radio-Fernbedienung am Lenkrad, Radiovorbereitung, 4 Lautsprecher, Vorrüstung Mobiltelefon/Handy mit Bluetooth-/USB-Schnittstelle, Touchscreen-Farbdisplay (8 Zoll)</i> • Rear wing doors with glazing <i>Heckscheibe heizbar</i> • Cold Start Package <i>2. Batterie, Batterie verstärkt</i> • Load compartment light LED • Metallic paint • Visibility Package Premium <i>Außenspiegel elektr. anklappbar, Außenspiegel elektr. verstell- und heizbar, Scheinwerfer-Assistent mit Tag-/Nachtsensor, Scheibenwischer mit Regensensor, Frontscheibe heizbar, Parkpilotsystem vorn und hinten, Nebelscheinwerfer, Rückfahrkamera mit Farbdisplay, Fahrassistenz-System: Spurhalteassistent mit Müdigkeitserkennungs-Sensor, Geschwindigkeits-Regelanlage (Tempomat), Lenkrad (Leder)</i> • Exterior door handles and tailgate handle in body color	• front armrest • <i>Nebelscheinwerfer, Tagfahrlicht LED</i> • Theft alarm system • Remote control for auxiliary heating / auxiliary heating • Generator 240 A • Wooden floor in the hold • • • View package 3 <i>Außenspiegel elektr. anklappbar, Außenspiegel elektr. verstell- und heizbar, Nebelscheinwerfer, Scheinwerfer-Assistent mit Tag-/Nachtsensor, Scheibenwischer mit Regensensor, Frontscheibe heizbar, Rückfahrkamera mit Farbdisplay, Fahrassistenz-System: Spurhalteassistent mit Müdigkeitserkennungs-Sensor, Geschwindigkeits-Regelanlage (Tempomat), Lenkrad (Leder)</i> • Auxiliary heating • Panel in load / FG - room wooden <i>Verkleidung im Lade-/FG-Raum: hoch</i>

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Frontscheibe beschädigt

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	- -
reference:	

Overview conducted technology audit							
Alternator / Generator:			examined limited	Battery / accumulator:			
oil loss:			examined limited			examined limited	
air conditioning:			examined limited	lighting system:			examined limited
coupling:			examined limited	exhaust System:			examined limited
engine running:			Out of order	shock absorber:			examined limited
transmission:			examined limited				

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine had to acoustic or visual defects for visiting time . **Engine warning light.
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Oberflächenkratzer/Kratzer rundum

damage



component	Damage	Rep kind
1. maintenance	Due	Replace
2. motor	Error message	Carry out a fault diagnosis
3. proof of maintenance	Missing	Replace
4.	Wear and tear	acceptable
5. Tailgate left	Wear and tear	acceptable
6. Tailgate right	Corroded	Paint
7.	Not available	acceptable
8. Door Rear - right	Wear and tear	acceptable
9. Windshield	Damaged	Replace
10. Front door - left	Wear and tear	acceptable
11. hood	Wear and tear	acceptable

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right




rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims




engine compartment



service book



Others



Navigation system



1. maintenance



2. motor



4.



4.



4.




4.



5. Tailgate left




6. Tailgate right



8. Door Rear - right



9. Windshield



9. Windshield



10. Front door - left



11. hood



11. hood