



Expertise

Protocol number: 41601540  
Order No. / Reference: 25133138  
Inspection date: 17 Sept 2025

Manufacturer: Ford

Model: Transit Custom 320 L1H1 LKW VA Trend

VIN: WF0YXXTTGYLE03711



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Transit Custom 320 L1H1 LKW VA Trend	
Vehicle Identification number	WF0YXXTTGYLE03711
Mileage (Read)	81,626 km
First registration	20 Nov 2020
Number of holders	1
Next periodical technical inspection	01/2027
(Report on hand)	
Power / Engine displacement	96 kw / 1,995 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Frost-Weiß
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Driving readiness	Roadworthy



## Vehicle details

<b>Maintenance booklet / proof</b>	Available / incomplete	<b>Next maintenance in</b>	30,000 km
<b>Last maintenance on / at</b>	01/2025 at 72,043 km		
<b>Key is / should be</b>	2 / 2	<b>FZG documents</b>	ZB#2 (B) was available (copy), ZB#1 (S) was not available
		<b>Letter No.</b>	FY015211
<b>Previous damage / Accident</b>	Detectable	<b>Repainting</b>	Detectable
<b>Inspection conditions</b>	sufficient	<b>Lifting equipment / pit</b>	yes
<b>Test drive</b>	Not performed	<b>Engine function test</b>	Performed
<b>Driving readiness</b>	Roadworthy		
<b>Manufacturer key number/ type code number</b>	8566 / BMU 05919		
<b>Emission standard</b>	EURO6;WLTP;CI;PI/CI;N1 III, N2	<b>Fine dust sticker</b>	
<b>Permitted total weight</b>	3,200 kg	<b>Empty weight</b>	

## Tyres

### Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 107T	Summer tyres on Steel rim with wheel cover	Goodyear	7mm / 7mm
2)	215/65 R16 107T	Summer tyres on Steel rim with wheel cover	Pirelli	8mm / 8mm

### Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	215/65 R16 107T C	Summer tyres on Steel	Goodyear	7 mm

**Legend:** Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel

## Equipment

### Standard equipment

- |  |   |
|--|---|
| <ul style="list-style-type: none"> <li>• 1 battery</li> <li>• Anti-lock braking system with electronic brake-force distribution (EBD)</li> <li>• roof, flat</li> <li>• Double-wing rear door with 180° opening angle (without window)</li> <li>• Electronic Safety and Stability Program (ESP) with Traction Control (TCS)</li> <li>• FordPass Connect</li> <li>• Generator, 240 A</li> <li>• Cruise control including leather steering wheel</li> <li>• Glove compartment with lockable lid</li> <li>• Front air conditioning</li> <li>• Cargo area lighting with activatable switch-off delay</li> <li>• Steering column, adjustable in height and reach</li> <li>• Package: Style Color Package</li> <li>• Particulate filter: diesel particulate filter</li> <li>• Wheels/Tires: Spare wheel, steel wheel</li> <li>• Headlights: Halogen projector headlights</li> <li>• Sliding door: Sliding door, right</li> <li>• Side protection strips</li> <li>• Power steering</li> <li>• Start-stop system</li> <li>• Front bumper in body color</li> <li>• Immobiliser</li> <li>• Central locking with remote control</li> <li>• Second key with remote control</li> </ul> | <ul style="list-style-type: none"> <li>• Driver's side airbag</li> <li>• Exterior mirrors, electrically adjustable and heated</li> <li>• On-board computer</li> <li>• Headlining in driver's cab</li> <li>• tachometer</li> <li>• Third brake light</li> <li>• Front window lifter, electric</li> <li>• Ford Easy Fuel</li> <li>• Warranty 2-year Ford new car warranty including the Ford Assistance mobility guarantee</li> <li>• Transmission: 6-speed transmission</li> <li>• Interior lighting with delay circuit</li> <li>• Paint finish: Solid paint</li> <li>• Cargo area floor: Vinyl floor covering, sealed, "Easy Clean"</li> <li>• Emergency braking assistance including emergency brake light</li> <li>• Hubcaps</li> <li>• Wheels: Steel wheels 6.5 J x 16 with 215/65 R 16 R tires</li> <li>• Sliding door entry light automatically when door is opened</li> <li>• Mud flaps front and rear</li> <li>• Low side wall cladding</li> <li>• Seat belts</li> <li>• Socket: 12-volt connection</li> <li>• Lashing eyes 8</li> <li>• Heat-insulating glazing, slightly tinted</li> <li>• auxiliary heater, electric</li> </ul> |
|--|---|

### Extra equipment

- |   |   |
|---|---|
| <ul style="list-style-type: none"> <li>• Package: Service Line (Shelving systems (left and right) - Vice - Ventilation for transporting gas cylinders - HDF wall paneling - Screen-printed wooden floor in the cargo area (the standard lashing eyes are omitted))</li> <li>• Rear view camera with parking pilot system front and rear with fog lights (with image transmission of the rear path in the multifunction display [additionally with coupling aid in conjunction with tow bar (extra charge)] with high-mounted LED exterior downlight)</li> <li>• Seats: Seat package 17A - Partition (through-loading hatch), without window (Custom Truck Trend (driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion angle, height) - Double passenger seat with storage compartment under individually foldable seat cushions - Height-adjustable headrests - Tray integrated in the double passenger seat (fold-out) - Seat heating for driver - Seat heating for passenger (outer seat) - Inside armrest for driver - Manual lumbar support (driver's seat) - Passenger and side airbags and head/shoulder airbags in the front - TREND seat cover: fabric)</li> </ul> | <ul style="list-style-type: none"> <li>• LED lights in the cargo area</li> <li>• Package: Smoker (cigarette lighter and ashtray)</li> <li>• Radio: Audio system 24: Ford audio system including Ford SYNC3 with AppLink, DAB/DAB+, navigation system (FM/AM radio, 8" touchscreen multifunction display (20.32 cm), 4 speakers, FordPass Connect Wi-Fi hotspot, integrated control panel and audio remote control on the steering wheel, Ford SYNC 3 with touchscreen (hands-free system with voice command control, SMS reading/sending function, Bluetooth, emergency call assistant, etc.), AppLink (advanced voice control, private mode, support for Android Auto and Apple CarPlay, capacitive touchscreen technology, etc.), dynamic navigation, lane recommendation, road map for Western Europe)</li> <li>• Sortimo equipment</li> </ul> |
|---|---|



## Brief expert findings

Documents submitted	At the time of the inspection, the registration certificate Part 2 (letter) was available, but the registration certificate Part 1 (certificate) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was verified during the inspection by the undersigned.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and a pit were available for examining the vehicle.
Test drive	No test drive/maneuvering was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
Driving readiness	The vehicle was drivable at the time of inspection.

## Value reducing factors

No.	Component group	Description
1	Door - front right side	Door - dent(s) - Smart repair
2	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
3	Bonnet	Bonnet - Scratch(es) - Paint
4	Side panel - rear right side	Side panel - Scratch(es) - Paint

## Wear and tear

No.	Component group	Description
1	Interior	Cargo space division - Scratch(es) - No deduction
2	Rear bumper	Rear bumper - Scratch(es) - No deduction
3	Body	Body - Scratch(es) - No deduction

The vehicle shows signs of wear commensurate with its age and use.

## Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer	6.165,39 €
2	Side - left, Side right, Professionally repaired, Invoice of repair done	Non-existent

## Repainting

No.	Repainting
1	Mudguard - left side, Mudguard - right side, Side panel - rear right side, Door - front left side, Professionally carried out, Invoice of repair done Non-existent

## Paint coat thickness measurement

Mudguard - left side	202 µm	Mudguard - right side	164 µm
Side panel - rear right side	178 µm	Door - front left side	184 µm



## Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features  
*(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.  
*(Functional tests of driver assistance systems are not included in the scope of services!)*
- a photo documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles from Alphabet Fuhrparkmanagement GmbH. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

Professionally repaired previous damages were found at the vehicle.





Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear





Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Mounted tyres



Figure 14: Documents



Figure 15: Documents




Figure 16: Documents




Figure 17: Documents




Figure 18: Documents






Figure 19: Documents



Figure 20: Navigation



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.





Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Damage 1: Door - front right side: Door - dent(s) - Smart repair



**Damage 1:** Door - front right side: Door - dent(s) - Smart repair




**Damage 2:** Side panel - rear left side: Side panel - dent(s) - Smooth repair work



**Damage 2:** Side panel - rear left side: Side panel - dent(s) - Smooth repair work



**Damage 2:** Side panel - rear left side: Side panel - dent(s) - Smooth repair work



**Damage 2:** Side panel - rear left side: Side panel - dent(s) - Smooth repair work



**Damage 3:** Bonnet: Bonnet - Scratch(es) - Paint





**Damage 3:** Bonnet: Bonnet - Scratch(es) - Paint



**Damage 3:** Bonnet: Bonnet - Scratch(es) - Paint



**Damage 3:** Bonnet: Bonnet - Scratch(es) - Paint



**Damage 3:** Bonnet: Bonnet - Scratch(es) - Paint



**Damage 3:** Bonnet: Bonnet - Scratch(es) - Paint



**Damage 4:** Side panel - rear right side: Side panel - Scratch(es) - Paint





**Damage 4:** Side panel - rear right side: Side panel - Scratch(es) - Paint



**Damage 4:** Side panel - rear right side: Side panel - Scratch(es) - Paint



**Damage 4:** Side panel - rear right side: Side panel - Scratch(es) - Paint



**Damage 4:** Side panel - rear right side: Side panel - Scratch(es) - Paint



**Damage 4:** Side panel - rear right side: Side panel - Scratch(es) - Paint



**Damage 4:** Side panel - rear right side: Side panel - Scratch(es) - Paint



**Wear and tear 1:** Interior: Cargo space division - Scratch(es) - No deduction



**Wear and tear 1:** Interior: Cargo space division - Scratch(es) - No deduction



**Wear and tear 1:** Interior: Cargo space division - Scratch(es) - No deduction



**Wear and tear 1:** Interior: Cargo space division - Scratch(es) - No deduction



**Repainting 1:** Mudguard - left side, Mudguard - right side, Side panel - rear right side, Door - front left side



**Repainting 1:** Mudguard - left side, Mudguard - right side, Side panel - rear right side, Door - front left side



**Repainting 1:** Mudguard - left side, Mudguard - right side, Side panel - rear right side, Door - front left side



**Repainting 1:** Mudguard - left side, Mudguard - right side, Side panel - rear right side, Door - front left side