



Hüsges Gruppe®
Die Gutachter

status report

customer: Bank 11, Neuss
contract number: 807115230
reference:

vehicle data

Ford Transit Custom Kasten 300 L2 Trend

Vehicle identification number	WF0YXTTGYMA23429	mileage read:	65005 km
First Registration / construction year:	31.08.2021 / 2021	Visit Date / place of birth:	19.09.2025 Riedstadt-Goddelau
Bodywork:	transporter	Re - import:	no
Body type:	van	KBA no. :	8566//BMU
Fuel / emission class:	diesel / € 6	transmission type:	manual transmission
Displacement / power:	1995 ccm / 96 kW (131 PS)	Engine:	front-wheel drive
paint:	Frost-Weiß	Number of previous owners:	2
Doors / seats:	4 / 3	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	yes	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	84 / 24.09.2021
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	-	state outside:	3 - Average
documents:		condition inside:	3 - Average
visit condition:	-		
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	yes / -	84 / 24.09.2021

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	steel
1st axis - Left / states .	Anderer	215/65/15/104/102T 4 mm
1st axis - right / states .	Anderer	215/65/15/104/102T 4 mm
2nd axis - Left / states .	Goodyear	215/65/15/104/102T 5 mm
2nd axis - right / states .	Goodyear	215/65/15/104/102T 5 mm
traffic Safety:	roadworthy	
spare wheel:	vorhanden	
state spare wheel:	Vollwertig	

standard equipment	
• Cornering in the spotlight • Trailer Stabilization Program (TSA) • Drive Front Wheel Drive • Audio system Radio with USB and Bluetooth handsfree <i>Radiovorbereitung, 4 Lautsprecher</i> • Indicator integrated into mirrors • board computer • Electr . Brakeforce Distribution (EBD) • Electron. Traction control • • Power windows • Transmission 6-speed • Rear wing doors without glazing (opening angle 180 degrees) • pollen filter • Karosserievariante medium height roof • Grille black grey • Truck admission • • Park Pilot system , front and rear <i>Nebelscheinwerfer</i> • Wheelbase 3300 mm • RuÃpartikelfilter • Low in emissions according to the Euro 6d emissions standard • Headlight H4 • Side moldings • Steel rims 6.5x16 • Partially painted bumpers • Daytime running light LED	• Airbag driver • Anti- lock braking system (ABS) • Audio system 13 digital radio reception (DAB / DAB+) with 4" multifunction display • Power side mirrors . adjustable and heated • Vinyl flooring in load / passenger compartment • entrance lights • Electron. Stability Program (ESP) • Driving Assistance System Hill Start Assist • Driver assistance system Crosswind Assist • Cruise control system (cruise control) <i>Lenkrad (Leder)</i> • Lockable glove compartment • Interior lights in the cab Front reading light • Body / Structure box high room • air Conditioning • Steering column (steering wheel) height / longitudinally adjustable • facelift • Parkpilotsystem • Digital radio reception (DAB +) • Spare wheel • Low emissions according to emission standard Euro 6 • Windscreen wipers with interval switching, adjustable • Mud flaps, front and rear • Seat package 13 driver's seat (4 positions) - passenger double seat fabric <i>Sitze im Fahrerhaus: Fahrersitz mit Lendenwirbelstütze</i> • Start / Stop system

• Soursop (8) • Central locking with remote control	• Farb-style-Paket <i>Stoßfänger in Wagenfarbe</i> • trend • Thermal insulation glazed slightly tinted • Additional heating electrically
--	---

special Features	
• front armrest • Battery monitoring programmable • Generator 240 A • Loading protection package <i>Verkleidung im Lade-/FG-Raum: hoch</i> • Rear view camera with color display • Panel in load / FG - room wooden <i>Verkleidung im Lade-/FG-Raum: hoch</i>	• Audio system 21 Digital radio reception (DAB / DAB +) with 8 "multifunction display <i>Radiovorbereitung, 4 Lautsprecher</i> • Ford SYNC 3 <i>Audio-/Radio-Fernbedienung am Lenkrad, Radiovorbereitung, 4 Lautsprecher, Vorrüstung Mobiltelefon/Handy mit Bluetooth-/USB-Schnittstelle, Touchscreen-Farbdisplay (8 Zoll)</i> • Load compartment light LED • My Key (2nd vehicle key programmable) • Sliding load / passenger compartment right

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable Wartung Fällig
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes .

Existing collision damage:

Evidence that points to a repaired accident damage or repainting carried out , were identified.

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			in order		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			examined limited	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug Teilweise Beklebt darunter liegende Schäden können nicht ausgeschlossen werden Nutzfahrzeug typische Gebrauchsspuren und Beschädigungen.

damage



component	Damage	Rep kind
1. Sitzreihe Vorne	Dirty	
2. maintenance	Due	Replace
3. spoiler	Damaged	Replace
4. hood	Delle	Smart repair
5.	Breakage	Replace
6. Front door - left	Damaged	Refurbish and paint
7. Türeinstieg Vorne - Links	Scratch(es)	Paint
8. Sidewall - Rear - Left	Deformed	Refurbish and paint
9. Rear bumper	Wear and tear	acceptable
10. Tailgate right	Damaged	Refurbish and paint
11. Fahrzeug Beklebt	Sticker	
12. Laderaum und Verkleidungen Diverse Kratzer, Dellen, Verformungen, Beschädigungen	Damaged	Replace
13. Door Rear - right	Scratch(es)	
14. Front door - right	Scratch(es)	Paint
15. Türeinstieg Vorne - Rechts	Damaged	Refurbish and paint
16.		
17. Front bumper	Damaged	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



1. Sitzreihe Vorne



1. Sitzreihe Vorne



3. spoiler



4. hood



5.



5.



6. Front door - left



6. Front door - left



6. Front door - left



7. Türeinstieg Vorne - Links



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



9. Rear bumper



9. Rear bumper



10. Tailgate right



10. Tailgate right



11. Fahrzeug Beklebt



11. Fahrzeug Beklebt



11. Fahrzeug Beklebt



12. Laderaum und Verkleidungen Diverse Kratzer, Dellen, Verformungen, Beschädigungen



12. Laderaum und Verkleidungen Diverse Kratzer, Dellen, Verformungen, Beschädigungen



12. Laderaum und Verkleidungen Diverse Kratzer, Dellen, Verformungen, Beschädigungen



12. Laderaum und Verkleidungen Diverse Kratzer, Dellen, Verformungen, Beschädigungen



12. Laderaum und Verkleidungen Diverse Kratzer, Dellen, Verformungen, Beschädigungen



12. Laderaum und Verkleidungen Diverse Kratzer, Dellen, Verformungen, Beschädigungen



12. Laderaum und Verkleidungen Diverse Kratzer, Dellen, Verformungen, Beschädigungen

Verformungen, Beschädigungen



12. Laderaum und Verkleidungen Diverse Kratzer, Dellen, Verformungen, Beschädigungen

Verformungen, Beschädigungen



13. Door Rear - right



14. Front door - right



14. Front door - right



14. Front door - right



15. Türeinstieg Vorne - Rechts

14. Front door - right



15. Türeinstieg Vorne - Rechts



16.



17. Front bumper



17. Front bumper



17. Front bumper