



status report

customer: Bank 11, Neuss
contract number:
reference:

vehicle data

Smart fortwo cabrio Basis 52 kW

Vehicle identification number	WME4534421K133139	mileage read:	57570 km
First Registration / construction year:	08.06.2016 / 2016	Visit Date / place of birth:	25.09.2025 Dahlwitz-Hoppegarten
Bodywork:	cars	Re - import:	unknown
Body type:	Convertible	KBA no. :	1313//EXJ
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	999 ccm / 52 kW (71 PS)	Engine:	rear-wheel drive
paint:	TRIDION- SICHERHEITSZELLE MOUNTAIN GREY MAGNO	Number of previous owners:	4
Doors / seats:	2 / 2	number keys:	1
Next HU / AU:	- / -	cushion type:	imitation leather
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	4 - moderate
visit condition:	-	condition inside:	3 - Average
state general:	4 - moderate		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	1	no / -	- / -
☒ Fernbed . Auxiliary heating	☒ partition net	☒ Wind Deflector	☒ AHK fixed
☒ AHK removable	☒ AHK swivel	☒ AHK key	☒ Fernbed . entertainment
☒ headphone	☒ Load compartment cover	☒ LED headlights	☒ navigation system
☒ Persenning	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	All season tires	aluminum
1st axis - Left / states .	Maxxis	185/50/R16/81V 4 mm
1st axis - right / states .	Maxxis	185/50/R16/81V 4 mm
2nd axis - Left / states .	Maxxis	205/45/R16/87V 4 mm
2nd axis - right / states .	Maxxis	205/45/R16/87V 4 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Airbag Driver / passenger side • Outside temperature display • board computer • Direct-Steer system with variable servo assistance • Driving Assistance System Hill Start Assist • Transmission 6-speed - DCT DCT • Body 2-door • Instrument cluster with monochrome display • Radiator mask black, grained • Engine 1.0 ltr. - 52 kW KAT • Low emissions to Euro 6 emission standards • Sun visor left with mirror • Start / Stop system • LED daytime running lights • Lashing luggage / cargo space	• Anti- lock braking system (ABS) • White side indicators • Design and equipment line Prime <i>Außenspiegel Farbe Tridion-Sicherheitszelle, Sitzheizung, Sitzbezug / Polsterung: Leder</i> • Electron. Stability Program (ESP) with start assist • Window lifter electr. front, with anti-trap • Isofix admissions for child seat • Knee Airbag driver • Head airbag system / side airbag • Steering wheel (sports / leather, 3-spoke) • Tire Pressure Monitoring System • Seatback folded front right • Sun visor right with mirror • Socket 12V (12V connection) • Tritop top • Remote central locking with immobilizer

special Features	
• Storage package <i>Mittelkonsole mit Ablagenetz seitlich, Handschuhfach abschließbar</i> • Bodypanel Cool Silver Metallic • First aid kit / first aid kit • Velour floor mats • larger fuel tank • Load compartment cover • Reversing camera • Tridion safety cell graphite-gray • Wind Deflector	• Ambient lighting • Cool & Media package <i>Audiosystem Smart mit Touchscreen, Freisprecheinrichtung Bluetooth, AUX-IN-Anschluss, USB-Anschluss, Klimaautomatik</i> • Driving Assistance System Lane Departure • Comfort Package <i>Außenspiegel elektr. verstell- und heizbar, Sitz vorn links höhenverstellbar, Lenksäule (Lenkrad) verstellbar</i> • LED & Sensor package <i>Nebelscheinwerfer, Scheinwerfer mit Begrüßungsfunktion, Heckleuchten LED, Regen-/Lichtsensor</i>

-
- Cruise control with distance control
- warning triangle

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	- -
reference:	

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			examined limited		
oil loss:			examined limited		
air conditioning:			not possible	lighting system:	
			examined limited		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning could not be checked during the inspection . **Due to weather conditions not possible examination.
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Automatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fzg. nur bedingt fahrbereit, Reifen h.r. Druckverlust

damage



component	Damage	Rep kind
1. maintenance	Missing	Replace
2. proof of maintenance	Missing	Replace
3.	Missing	Replace
4. key	Missing	Replace
5.	Damaged	Replace
6. Rear bumper	Scrape	Paint
7. tailgate	Scratch(es)	Smart repair
8.	Scratch(es)	Smart repair
9. tire rear - right	Not okay	Carry out a fault diagnosis
10. Front door - right	Delle	Smart repair
11.	Scratch(es)	Smart repair
12. Türeinstieg Vorne - Rechts	Damaged	Refurbish and paint
13. Door Seal Front - right	Damaged	Replace
14.	Missing	Replace
15.	Scratch(es)	Paint
16. Front door - left	Delle	Smart repair
17. side skirt - left	Deformed (slightly)	Refurbish and paint
18. Front door seal - left	Damaged	Replace
19. Türeinstieg Vorne - Links	Deformed (slightly)	Refurbish and paint
20.	Wear and tear	acceptable
21. Front bumper	Wear and tear	acceptable
22. side skirt - right	Deformed (slightly)	Refurbish and paint

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



Navigation system



1. maintenance



5.



6. Rear bumper



6. Rear bumper



7. tailgate



8.



9. tire rear - right



10. Front door - right



11.



12. Türeinstieg Vorne - Rechts



13. Door Seal Front - right



14.



15.



16. Front door - left



17. side skirt - left



18. Front door seal - left



19. Türeinstieg Vorne - Links



20.



21. Front bumper



22. side skirt - right