



OPEL Cascada Benzina
Cascada 1.6 t sidi Cosmo s&s

VIN NO WOLWT3D95GG074610
Registration Number FC409SR



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2024-09-04	-	-	135178 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2016-03-21	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250926102711
Inspection Date / Place	2025-09-26 / BCA Lodi	Cosmetic Grade	5




Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Gearbox Type	Automatic
Colour	Silver	Engine Size (cc)	1598
Engine Size	1.6	No of Doors	2
Body Type	Convertible	Drive Train	Front
Seat Colour	Black	No of Seats	4
Seat Covering Name		Seat Covering	Cloth/Leather
Charging Cables		NEDC CO2 Rating (q/km)	148

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment


Central locking	Alloys wheels	Sunroof	Remote adjusting wing mirrors
Cruise control	Tyre Mobility Kit	Power assisted steering	Digital Radio
Volante multifuncion	Remote central locking	Trip Computer	Stability control

Wheels & Tyres


Mounted Tires

Tyre / Wheel Type	Summer	
	MICHELIN MICHELIN-CROSSCLIMATE 2	235/50//R18 - 101Y / 2 mm
	MICHELIN MICHELIN-CROSSCLIMATE 2	235/50//R18 - 101Y / 2 mm
	MICHELIN MICHELIN-CROSSCLIMATE 2	235/50//R18 - 101Y / 2 mm
	MICHELIN MICHELIN-CROSSCLIMATE 2	235/50//R18 - 101Y / 2 mm

20 Danni



4 Danni

6/12 - Report Number P20250926102711


13	Door / Front Left	Bodywork / Dent
14	Door / Front Left	Paint / Scratch / Line
15	Rim / Back Left	Out of Bodywork / Scratch
16	Fender / Back Left	Bodywork / Dent
17	Bumper / Back	Bodywork / Breakage
18	Tailgate	Bodywork / Dent
19	Bumper / Back	Bodywork / Breakage
20	Rim Brake pads	Out of Bodywork / Scratch
21	Fender / Back Right	Bodywork / Dent
22	Door / Front Right	Bodywork / Dent
23	Mirror Shell / Front Right	Paint / Scratch / Line
24	Convertible Roof	Paint / Scratch / Line



1. Dashboard / Front
Interior / Warning Light ON -



2. Gear Knob
Interior / Broken -



3. Seat / Front Left
Interior / Worn - out -



4. Floor Carpet
Interior / Ripped -



5. Rim / Front Right
Out of Bodywork / Scratch -



6. Fender / Front Right
Bodywork / Dent -



7. Bumper / Front
Bodywork / Dent -




8. Shield Grid / Front Center
Bodywork / Breakage -




9. Hood
Bodywork / Dent -



10. Rim / Front Left
Out of Bodywork / Scratch -



11. Fender / Front Left
Paint / Scratch / Line -




12. Windshield / Front
Glass Break -




13. Door / Front Left
Bodywork / Dent -



14. Door / Front Left
Paint / Scratch / Line -



15. Rim / Back Left
Out of Bodywork / Scratch -




16. Fender / Back Left
Bodywork / Dent -



17. Bumper / Back
Bodywork / Breakage -



18. Tailgate
Bodywork / Dent -




19. Bumper / Back
Bodywork / Breakage -




20. Rim Brake pads
Out of Bodywork / Scratch -



21. Fender / Back Right
Bodywork / Dent -



22. Door / Front Right
Bodywork / Dent -



23. Mirror Shell / Front Right
Paint / Scratch / Line -



24. Convertible Roof
Paint / Scratch / Line -

Mechanical Condition

Equipments Test

AC / Heating System



Other Equipments



Engine

Vehicle Start - up



Engine Starts



Engine Leak Visible



Clutch

Clutch Functioning



Levels

Brakes Fluid



Coolant Fluid



Test Drive Inspection

Other Checks

Steering



Brakes



Suspension



Equipments Test

Steering | Noise / Anomaly



Engine

Power Loss



Fume Quantity



Engine Noise



Gearbox

Manual Gearbox



General

Test Driven Status



 **No troubles detected, good condition or correct tests, according to vehicle age and mileage**

 **Damages or malfunction detected that requires repairs by the buyer**

 **Not applicable**

 **Not tested**