



VOLKSWAGEN CRAFTER FOURGON

CRAFTER VAN 30 L2H2 2.0 TDI 136 FAP

EURO5 BUSINESS LINE

VIN NO WV1ZZZ2EZF6037231
Registration Number DV607VM



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250828101847
Inspection Date / Place	2025-08-28 / BCA AUNAY	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	White	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	4
Body Type	Box Wagon	Drive Train	Rear
Seat Colour		No of Seats	3
Charging Cables		NEDC CO2 Rating (q/km)	226

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Radio	Front parking sensors	Roof rails	Cruise control
-------	-----------------------	------------	----------------


Power assisted steering

Equipment Details


Seat Heating	No	Air Conditioning	Yes
--------------	----	------------------	-----

Cosmetic Damage

21 Dommages



6 Dommages



Component		Damage	Comments
1	Seat / Front Right	Interior / Dirty	
2	Steering Wheel / Front	Interior / Scratched	
3	Seat / Front Left	Interior / Ripped	
4	Window Switch / Front Left	Interior / Broken	
5	Door / Front Left	Paint / Scratch / Line	
6	Side Panel / Back Left	Paint / Scratch / Line	
7	Wing Stick / Back Left	Paint / Scratch / Line	
8	Side Panel / Back Left	Paint / Scratch / Line	
9	Side Panel / Back Left	Paint / Scratch / Line	
10	Bumper / Back	Paint / Scratch / Line	
11	Bumper / Back	Paint / Scratch / Line	
12	Outside Sensor / Back	Bodywork / Breakage / Hole	
13	Tailgate	Paint / Scratch / Line	

14	Side Panel / Back Right	Paint / Scratch / Line
15	Bumper / Back	Paint / Scratch / Line
16	Door / Back Right	Bodywork / Dent / Dent
17	Door / Back Right	Paint / Scratch / Line
18	Door / Front Right	Bodywork / Dent / Dent
19	Seat / Front Right	Interior / Ripped
20	Window Switch / Front Right	Interior / Broken
21	Mirror / Front Right	Bodywork / Breakage / Hole
22	Fender / Front Right	Bodywork / Dent / Dent
23	Bumper / Front	Bodywork / Breakage / Hole
24	License Plate / Front	Out of Bodywork / Breakage
25	Bumper / Front	Bodywork / Breakage / Hole
26	Fender / Front Left	Paint / Scratch / Line
27	Mirror / Front Left	Bodywork / Breakage / Hole



1. Seat / Front Right
Interior / Dirty -



2. Steering Wheel / Front
Interior / Scratched -



3. Seat / Front Left
Interior / Ripped -



4. Window Switch / Front Left
Interior / Broken -



5. Door / Front Left
Paint / Scratch / Line -



6. Side Panel / Back Left
Paint / Scratch / Line -



7. Wing Stick / Back Left
Paint / Scratch / Line -



8. Side Panel / Back Left
Paint / Scratch / Line -



9. Side Panel / Back Left
Paint / Scratch / Line -



10. Bumper / Back
Paint / Scratch / Line -




11. Bumper / Back
Paint / Scratch / Line -



12. Outside Sensor / Back
Bodywork / Breakage / Hole -



13. Tailgate
Paint / Scratch / Line -



14. Side Panel / Back Right
Paint / Scratch / Line -



15. Bumper / Back
Paint / Scratch / Line -



16. Door / Back Right
Bodywork / Dent / Dent -



17. Door / Back Right
Paint / Scratch / Line -



18. Door / Front Right
Bodywork / Dent / Dent -



19. Seat / Front Right
Interior / Ripped -



20. Window Switch / Front Right
Interior / Broken -



21. Mirror / Front Right
Bodywork / Breakage / Hole -



22. Fender / Front Right
Bodywork / Dent / Dent -




23. Bumper / Front
Bodywork / Breakage / Hole -



24. License Plate / Front
Out of Bodywork / Breakage -



25. Bumper / Front
Bodywork / Breakage / Hole -



26. Fender / Front Left
Paint / Scratch / Line -



27. Mirror / Front Left
Bodywork / Breakage / Hole -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.