

DEKRA Automotive Solutions

Vehicle details

VIN	WV1ZZZ2KZ KX070474	Brand	VOLKSWAGEN	Maintenance date	29/04/2025
Licence Plate	KSN29S	Model	Caddy-LCV-SA-2015	Maintenance mileage	129 007 km
Registration date	15/08/2019	Year	2019	Exterior Color	Other
Odometer	131 344 km	Engine size	-	interior Color	
Fuel	Diesel	Body Type	Saloon / Hatchback	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	4	Gears	6		

Inspection Details

Inspection date	02/10/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Bluetooth	✓
Reversing radars	✓
Automatic Gearbox	✓
Central locking	✓
4x4	✓
Park Distance Control	✓
Audio System	✓

Removable element

Refill emergency kit	✓
----------------------	---

Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓

DEKRA Automotive Solutions

Tyres

Continental 205/55/16 H Summer 4.0 mm		Continental 205/55/16 H Summer 4.0 mm	
Continental 205/55/16 H Summer 4.0 mm		Continental 205/55/16 H Summer 4.0 mm	

Winter kit

Nokian 205/55/16 T Winter 4.0 mm		Nokian 205/55/16 T Winter 4.0 mm	
Nokian 205/55/16 T Winter 6.0 mm		Nokian 205/55/16 T Winter 6.0 mm	

Damages

1		Part	Complete service track record	2		Part	Other mechanical
		Position	-			Position	-
3		Damages	Missing	4		Damages	Defective
		Severity	-			Severity	-
5		Repair mode	Lumpsum	6		Repair mode	For info
						Ac unit not cooling	
7		Part	Other mechanical	8		Part	Bumper grille
		Position	-			Position	Front
9		Damages	Defective	10		Damages	Pierced
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	Replace
		Steering play					
		Part	Door			Part	Wing
		Position	Back right			Position	Back left
		Damages	Dented			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	For info
		Part	Other mechanical			Part	Bumper grille
		Position	-			Position	Front
		Damages	Defective			Damages	Stone impact
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	For info
		Part	Door			Part	Bonnet
		Position	Front left			Position	Front
		Damages	Dented			Damages	Stone impact
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	For info
		Part	Other mechanical			Part	Steering wheel
		Position	-			Position	-
		Damages	Defective			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	For info

DEKRA Automotive Solutions

11		Part	Other mechanical
		Position	-
		Damages	Defective
		Severity	-
		Repair mode	For info
		Breaking vibrations during test drive	