



Volkswagen Caddy: VBB23D

Vinnumber:	WV1ZZZ2KZKX125297	Versionname:	Caddy Maxi 1.4 TGI Ecofuel 81kW
First Registrationdate:	31/07/2019	Fiscalpower:	
Expertise Mileage:	214640	Power Kw:	81
Bodytype:		Body colour	Candywit
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	Front	Type of rims (mounted)	Steel
Fueltype:	Gas	Parking lot	869
Number of seats	2		
Type of rims (mounted)	Steel		
Maintenance needed	Yes		

Options

Number of keys total	2	Telephone equipment
Number keys remote	2	Rear parking sensors
Windows electric F		Sliding door right-side
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 65 / 15 / 95 / V / Steel	1,8 mm	Continental	All season
	Right	195 / 65 / 15 / 95 / V / Steel	3,0 mm	Continental	All season
Rear	Left	195 / 65 / 15 / 95 / V / Steel	5,4 mm	Goodyear	All season
	Right	195 / 65 / 15 / 95 / V / Steel	7,6 mm	Continental	All season

Assistance equipment

Spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service, Maintenance, Execute



Seat, Worn, Replace



Outside rear-view mirror housing L, Scratch(es), Replace



Door FL, Dent(s), Repair and paint (complete)



Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)



[Damage Picture - 3](#)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Broken, Replace



Bumper grille FR, Deformed / Strained, Replace



Bumper grille FL, Deformed / Strained, Replace



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)





Outer sill R, Scratch(es), Repair and paint (complete)



Sliding door R, Scratch(es), Repair and paint (complete)



Door FR, Dent(s), Repair and paint (complete)



Boot door lining L, Crack, Replace



Boot door lining R, Crack, Replace



Supplementary brake light, Crack, Replace



Bull bar R, Deformed / Strained, Replace



Reflector, Broken, Replace



Bumper R, Dent(s), Replace



Hub cap RR, Missing, Replace

