



Expertise

Protocol number: 41634455
Order No. / Reference: 25254742
Inspection date: 19 Sept 2025

Manufacturer: Volkswagen	Model: Caddy 2.0 TDI Maxi EcoProfi
VIN: WV1ZZZ2KZLX117237	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volkswagen Caddy 2.0 TDI Maxi EcoProfi	
Vehicle Identification number	WV1ZZZ2KZLX117237
Mileage (Read)	110,736 km
First registration	7 Aug 2020
Number of holders	1
Power / Engine displacement	75 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 5
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Candyweiß
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite



Vehicle details

Maintenance booklet / proof	digital proof / incomplete	Next maintenance in	
Last maintenance on / at	11/2024 at 35,300 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available
		Letter No.	FU531805
Previous damage / Accident	None detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0603 / BXG 21761		
Emission standard	EURO6;WLTP;CH;PI/CI; N1 II	Fine dust sticker	
Permitted total weight	2,299 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/65 R15 95T	Summer tyres on Steel	Hankook	3mm / 3mm
2)	195/65 R15 95T	Summer tyres on Steel	Hankook	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/65 R15 91T	Winter tyres on Steel	Pirelli	2mm / 2mm
2)	195/65 R15 91T	Winter tyres on Steel	Pirelli	5mm / 5mm

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel



Equipment

Standard equipment

- Airbag: driver and passenger side
- Exterior mirror: Car exterior mirror, left aspherical, right convex
- Brake light, third
- tachometer
- ESP Electronic Stability Program with Brake Assist
- Transmission: 5-speed transmission
- Headrests (2), height adjustable
- Steering column adjustable in height and tilt
- Upholstery: Seat covers in fabric, design "Austin"
- Wheels/Tires: 195/65 R 15 95 T xl, rolling resistance optimized
- Power steering, speed-dependent (Servotronic)
- Seat: height-adjustable driver's seat
- Right sun visor without make-up mirror and including airbag label
- Daytime running light
- Partition walls: high partition wall without window
- Lashing eyes (8 in the passenger compartment)
- Thermal insulation glazing
- Exterior mirrors electrically adjustable and heated
- Hill Start Assist
- Floor coverings, carpeting in the driver's cab
- Roof rail/roof rack preparation
- Three-point automatic seat belts
- Electric windows, front
- Tailgate sheeted
- Paint finish: Solid paint
- Particle filter: Soot particle filter for diesel
- Wheel cover center
- Wheels/Tires: Steel wheels 6J x 15
- Sliding door, right in the passenger/cargo area
- Seat belt check
- Seats: Seat in the driver's cab right
- Start-stop system
- Dust and pollen filter
- Tire Mobility Set
- First aid kit, warning triangle and safety vest
- Electronic immobilizer
- Central locking with radio remote control and interior operation

Extra equipment

- Cruise control including speed limiter
- Air conditioning including glove compartment with lockable flap as LNFZ version (cooling - lighting)
- Fatigue detection and multifunction display "Plus"
- Fog light
- ParkPilot in the rear area with rear view camera "Rear View"
- Upholstery: special fabric
- Seat heating (heated driver's seat)
- Transport protection for the cargo area (high side paneling made of fiberboard - side lashing rails)
- Partitions: Partition (high) with window (behind the driver's seat (no passenger seat), for vehicles with up to 800 kg payload - safety interior mirror, dimmable)
- Rear wing doors, windows covered with opaque film on the inside (without rear window wiper/washer/window heating - rear wing doors including rear windows, covered with opaque film on the inside, asymmetrically divided - rear window covered with opaque film on the inside (window heating not included) - without rear window wiper/washer)
- "Discover Media" radio navigation system with 6.33" touchscreen (4 speakers, drowsiness detection, USB interface and AUX-IN multimedia jack, comfort interior lighting in the driver's cab, "Plus" multifunction display, mobile phone interface)

Brief expert findings

Documents submitted	At the time of the inspection, the registration certificate Part 2 (letter) was available, but the registration certificate Part 1 (certificate) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was verified during the inspection by the undersigned.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and a pit were available for examining the vehicle.
Test drive	No test drive/maneuvering was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors



No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Boot lid / rear door	Rear door - left side (Verkleidung) - Broken / torn - Replace
3	Boot lid / rear door	Rear door - right side (Verkleidung) - Broken / torn - Replace
4	Misc.	Inspection / maintenance (digitaler Nachweis / unplausibel) - Missing - Perform diagnosis
5	Trim / covers	Cargo area - lining -left side - Broken / torn - Replace
6	Interior	Interior (SEITENTEIL H I L) - Scratched - Smart repair
7	Interior	Interior (SEITENTEIL H I R) - Scratched - Smart repair
8	Seat - front	Seat cover - left side - Holes - Smart repair
9	Body	Body - Glued / labelled - De-glue / neutralise
10	Door - front right side	Door - dent(s) - Smooth repair work
11	Side panel - rear right side	Side panel - Scratched - Smart repair
12	Rear bumper	Rear bumper - Scratched - Loss in value
13	Front bumper	Front bumper - Scratched - Smart repair
14	Vehicle glazing	Rear window - right side - Scratched - Loss in value
15	Seat - front	Seat cover - right side - Holes - Replace
16	Sliding door, right	Sliding door (Kratzer) - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	Partition wall (Dellen) - Scratched - No deduction
2	Interior	Cargo area floor - Scratched - No deduction
3	Vehicle glazing	Rear window - left side - Scratch(es) - No deduction
4	Vehicle glazing	Windscreen - Stone chips - No deduction
5	Headlight	Headlight - right side - Stone chips - No deduction
6	Headlight	Headlight - left side - Stone chips - No deduction
7	Bonnet	Bonnet - Stone chips - No deduction
8	Body	Body (Flugrost) - Soiled - No deduction
9	Wing mirror - right side	Cap - Scratched - No deduction
10	Side panel - rear left side	Side panel - Scratched - No deduction
11	Roof	Roof - Scratch(es) - No deduction
12	Misc.	Main inspection - No evidence - No deduction
13	Interior	Interior - Scratch(es) - No deduction
14	2nd wheel set	2 tyres - Expired - No deduction

The vehicle shows signs of wear commensurate with its age and use.

Repainting

No. Repainting

- Side panel - rear right side, Invoice of repair done Non-existent

Paint coat thickness measurement

Side panel - rear right side 256 µm |



Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
(Functional tests of driver assistance systems are not included in the scope of services!)
- a photo documentation of the vehicle

Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Apparently, no repaired previous damage could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view ([Online link](#))



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.




Figure 35: Misc.



Damage 2: Boot lid / rear door: Rear door - left side (Verkleidung) - Broken / torn - Replace



Damage 2: Boot lid / rear door: Rear door - left side (Verkleidung) - Broken / torn - Replace



Damage 3: Boot lid / rear door: Rear door - right side (Verkleidung) - Broken / torn - Replace



Damage 3: Boot lid / rear door: Rear door - right side (Verkleidung) - Broken / torn - Replace



Damage 3: Boot lid / rear door: Rear door - right side (Verkleidung) - Broken / torn - Replace




Damage 3: Boot lid / rear door: Rear door - right side (Verkleidung) - Broken / torn - Replace



Damage 4: Misc.: Inspection / maintenance (digitaler Nachweis / unplausibel) - Missing - Perform diagnosis



Damage 5: Trim / covers: Cargo area - lining -left side - Broken / torn - Replace



Damage 5: Trim / covers: Cargo area - lining -left side - Broken / torn - Replace



Damage 6: Interior: Interior (SEITENTEIL H I L) - Scratched - Smart repair



Damage 6: Interior: Interior (SEITENTEIL H I L) - Scratched - Smart repair



Damage 6: Interior: Interior (SEITENTEIL H I L) - Scratched - Smart repair



Damage 6: Interior: Interior (SEITENTEIL H I L) - Scratched - Smart repair



Damage 7: Interior: Interior (SEITENTEIL H I R) - Scratched - Smart repair




Damage 7: Interior: Interior (SEITENTEIL H I R) - Scratched - Smart repair




Damage 7: Interior: Interior (SEITENTEIL H I R) - Scratched - Smart repair



Damage 7: Interior: Interior (SEITENTEIL H I R) - Scratched - Smart repair



Damage 8: Seat - front: Seat cover - left side - Holes - Smart repair



Damage 8: Seat - front: Seat cover - left side - Holes - Smart repair



Damage 9: Body: Body - Glued / labelled - De-glue / neutralise



Damage 9: Body: Body - Glued / labelled - De-glue / neutralise



Damage 9: Body: Body - Glued / labelled - De-glue / neutralise



Damage 9: Body: Body - Glued / labelled - De-glue / neutralise



Damage 9: Body: Body - Glued / labelled - De-glue / neutralise



Damage 9: Body: Body - Glued / labelled - De-glue / neutralise



Damage 9: Body: Body - Glued / labelled - De-glue / neutralise



Damage 9: Body: Body - Glued / labelled - De-glue / neutralise



Damage 10: Door - front right side: Door - dent(s) - Smooth repair work



Damage 10: Door - front right side: Door - dent(s) - Smooth repair work



Damage 10: Door - front right side: Door - dent(s) - Smooth repair work



Damage 11: Side panel - rear right side: Side panel - Scratched - Smart repair



Damage 11: Side panel - rear right side: Side panel - Scratched - Smart repair




Damage 11: Side panel - rear right side: Side panel - Scratched - Smart repair



Damage 12: Rear bumper: Rear bumper - Scratched - Loss in value



Damage 12: Rear bumper: Rear bumper - Scratched - Loss in value



Damage 12: Rear bumper: Rear bumper - Scratched - Loss in value



Damage 12: Rear bumper: Rear bumper - Scratched - Loss in value



Damage 13: Front bumper: Front bumper - Scratched - Smart repair



Damage 13: Front bumper: Front bumper - Scratched - Smart repair



Damage 13: Front bumper: Front bumper - Scratched - Smart repair




Damage 13: Front bumper: Front bumper - Scratched - Smart repair



Damage 13: Front bumper: Front bumper - Scratched - Smart repair



Damage 13: Front bumper: Front bumper - Scratched - Smart repair




Damage 13: Front bumper: Front bumper - Scratched - Smart repair



Damage 13: Front bumper: Front bumper - Scratched - Smart repair



Damage 14: Vehicle glazing: Rear window - right side - Scratched - Loss in value



Damage 14: Vehicle glazing: Rear window - right side - Scratched - Loss in value



Damage 14: Vehicle glazing: Rear window - right side - Scratched - Loss in value



Damage 14: Vehicle glazing: Rear window - right side - Scratched - Loss in value



Damage 15: Seat - front: Seat cover - right side - Holes - Replace



Damage 15: Seat - front: Seat cover - right side - Holes - Replace



Damage 16: Sliding door, right: Sliding door (Kratzer) - Dent / paintcoat damage - Repair and paint



Damage 16: Sliding door, right: Sliding door (Kratzer) - Dent / paintcoat damage - Repair and paint



Damage 16: Sliding door, right: Sliding door (Kratzer) - Dent / paintcoat damage - Repair and paint



Damage 16: Sliding door, right: Sliding door (Kratzer) - Dent / paintcoat damage - Repair and paint



Wear and tear 7: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 7: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 7: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 7: Bonnet: Bonnet - Stone chips - No deduction




Wear and tear 14: 2nd wheel set: 2 tyres - Expired - No deduction



Wear and tear 14: 2nd wheel set: 2 tyres - Expired - No deduction



Wear and tear 14: 2nd wheel set: 2 tyres - Expired - No deduction



Wear and tear 14: 2nd wheel set: 2 tyres - Expired - No deduction



Repainting 1: Side panel - rear right side



Repainting 1: Side panel - rear right side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WV1ZZZ2KZLX117237

Hersteller / Modell: VOLKSWAGEN VW Caddy 2.0 TDI Maxi EcoProfi

Datum	KM-Stand	Beschreibung
29.11.2024	35.300	Regelwartungsdienst
10.09.2024	33.348	HU + AU; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
24.11.2023	25.401	Bremsflüssigkeit; Bremsflüssigkeit ern; Regelwartungsdienst
05.11.2022	14.627	AU; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges