



Expertise

Protocol number: 41685748  
Order No. / Reference: 25226674  
Inspection date: 24 Sept 2025

Manufacturer: Volkswagen

Model: Transporter T6 Kurz BlueMotion

VIN: WV1ZZZ7HZKH186751



| Vehicle details                           |                       |
|-------------------------------------------|-----------------------|
| Manufacturer / Type / Model / Equipment   |                       |
| Volkswagen Transporter T6 Kurz BlueMotion |                       |
| Vehicle Identification number             | WV1ZZZ7HZKH186751     |
| Mileage (Read)                            | 103,128 km            |
| First registration                        | 3 Feb 2020            |
| Number of holders                         | 1                     |
| Next periodical technical inspection      | 05/2026               |
| (Report not on hand)                      |                       |
| Power / Engine displacement               | 75 kw / 1,968 ccm     |
| Fuel type / Cylinder                      | Diesel / 4            |
| Gearbox / Number of gears                 | Manual / 5            |
| Type of drive                             | Front drive           |
| Type of vehicle                           | Van                   |
| Colour / colour code                      | Reflexsilber Metallic |
| Doors / Seats                             | 4 / 2                 |
| Upholstery type                           | Cloth                 |
| Colour of upholstery                      | Black-Blue            |



## Vehicle details

|                                                  |                                |                                |                                                           |
|--------------------------------------------------|--------------------------------|--------------------------------|-----------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | digital proof / complete       | <b>Next maintenance in</b>     | 26,900 km                                                 |
| <b>Last maintenance on / at</b>                  | 01/2025 at 99,830 km           |                                |                                                           |
| <b>Key is / should be</b>                        | 2 / 2                          | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available |
|                                                  |                                | <b>Letter No.</b>              | FN449026                                                  |
| <b>Previous damage / Accident</b>                | Detectable                     | <b>Repainting</b>              | Detectable                                                |
| <b>Inspection conditions</b>                     | sufficient                     | <b>Lifting equipment / pit</b> | yes                                                       |
| <b>Test drive</b>                                | Not performed                  | <b>Engine function test</b>    | Performed                                                 |
| <b>Manufacturer key number/ type code number</b> | 0603 / AVQ 54985               |                                |                                                           |
| <b>Emission standard</b>                         | EURO6;WLTP;CI;PI/CI;N1 III, N2 | <b>Fine dust sticker</b>       |                                                           |
| <b>Permitted total weight</b>                    | 2,700 kg                       | <b>Empty weight</b>            |                                                           |

## Tyres

### Mounted tyres

| #  | Tyre size       | Type of tyre          | Manufacturer | Tread depth |
|----|-----------------|-----------------------|--------------|-------------|
| 1) | 215/65 R16 107T | Winter tyres on Steel | Goodyear     | 5mm / 5mm   |
| 2) | 215/65 R16 107T | Winter tyres on Steel | Goodyear     | 5mm / 5mm   |

### Additional tyres

| #  | Tyre size       | Type of tyre                               | Manufacturer | Tread depth |
|----|-----------------|--------------------------------------------|--------------|-------------|
| 1) | 205/65 R16 107T | Summer tyres on Steel rim with wheel cover | Continental  | 5mm / 5mm   |
| 2) | 205/65 R16 107T | Summer tyres on Steel rim with wheel cover | Continental  | 6mm / 6mm   |

### Replacement

| Typ | Tyre size | Type of tyre            | Manufacturer | Tread depth |
|-----|-----------|-------------------------|--------------|-------------|
|     | Tirefit   | Expiration date 07/2023 |              |             |

**Legend:** Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel



## Equipment

### Standard equipment

- Storage and storage boxes
- Exterior mirrors, left and right convex
- Floor coverings: Rubber floor covering in the driver's cab
- Braking systems: Electronic Stabilization Program, ABS, ASR (with deactivation button), EDS
- Chassis: 16" chassis with 16" brake system
- Chassis: Suspension and damping lowered
- Speed limit system up to 100 km/h
- Transmission: 5-speed transmission
- Interior panels: Side panels (half-height) made of hardboard in the cargo area
- Non-smoking version
- Upholstery: fabric, design "Austin"
- Wheels/Tires: 205/65 R 16 C 107/105 T, rolling resistance optimized
- Sliding door in the passenger/cargo area: Sliding door on the right
- Start-stop system
- Daytime running light
- First aid kit, warning triangle and safety vest
- Electronic immobilizer
- Registration as "closed truck"
- Airbag for driver and front passenger
- Hill Start Assist
- Brake light, third
- tachometer
- Cancellation: Without child safety lock in the passenger compartment
- Total weight: Gross vehicle weight 2700 kg
- Cruise control system
- Tailgate without window
- Front headrests, height adjustable
- Multi-collision brake
- Particle filter: Soot particle filter for diesel
- Tire pressure monitoring indicator
- Wheels/Tires: Steel wheels 6.5 J x 16 in 20-hole design
- Wheels: Tire Mobility Set
- Power steering
- Seat belts: three-point automatic seat belts
- Dust and pollen filter
- Step inside, in the driver's cab and cargo area
- Lashing eyes for securing loads
- Green thermal insulation glazing

### Extra equipment

- Electrics Package I (electrically adjustable and heated exterior mirrors - electric windows)
- Air conditioning "Climatic" in the driver's cab
- Paint finish: metallic
- ParkPilot in the rear area
- Radio "Composition Audio" with TFT display (monochrome) (2 speakers)
- Smoker version (12 V socket with cigarette lighter, ashtray and 2 cup holders in the dashboard)
- Wheels/Tires: Winter tires (additional) 2WB
- Seat heating for seat in driver's cab, left, adjustable
- Partitions: high partition without windows (and 8 lashing eyes for securing the load - lashing eyes for securing the load, reinforced (ISO 27956))
- Rear wing doors without windows (mechanical locking/unlocking of the tailgate/wing door lock with unlocking function from the inside)
- Package: Comfort Package Plus (electric air conditioning in the driver's cab, fabric seat covers in "Bricks" design, 1 waste bin for the door pockets in the driver's cab, additional sound deadening measures in the driver's cab, height adjustment for the left single seat in the driver's cab, folding grab handles and storage compartments on the cab seats, sun visors with mirrors, and airbag label on the passenger sun visor, grab handle for entry on the A-pillar, on the front/rear lumbar support for the left single seat in the cab, 1 dimmable instrument lighting)
- Permissible total weight 3,000kg 0WQ

## Brief expert findings

|                      |                                                                                                                                                                          |
|----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the registration certificate Part 2 (letter) was available, but the registration certificate Part 1 (certificate) was not. (Copy)         |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was verified during the inspection by the undersigned. |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and a pit were available for examining the vehicle.                    |
| Test drive           | No test drive/maneuvering was carried out during the inspection of the vehicle.                                                                                          |
| Engine function test | An engine test run was performed.                                                                                                                                        |



## Value reducing factors

| No. | Component group         | Description                                                                  |
|-----|-------------------------|------------------------------------------------------------------------------|
| 1   | Body                    | Identification plate - Missing - Replace                                     |
| 2   | Equipment               | Tirefit filler - Expired - Replace                                           |
| 3   | Door - front left side  | Door edge - Scratched - Smart repair                                         |
| 4   | Sliding door, right     | Sliding door (Verkleidung) - Broken / torn - Replace                         |
| 5   | Steering system         | Steering wheel - Scratched - Smart repair                                    |
| 6   | Door - front right side | Door - Scratched - Smart repair                                              |
| 7   | Front bumper            | Front bumper - Scratched - Smart repair                                      |
| 8   | Trim / covers           | Boot lid - interior trim (Kratzer) - Broken / torn - Replace                 |
| 9   | Headlight               | Headlight - left side - Scratched - Replace                                  |
| 10  | Bonnet                  | Bonnet (Steinschlag) - Corrosion - Repair and paint                          |
| 11  | Sliding door, right     | Sliding door (Dellen) - Scratched - Repair and paint                         |
| 12  | Boot lid / rear door    | Rear door - right side (Kratzer) - Deformed - Repair and paint               |
| 13  | Boot lid / rear door    | Rear door - left side (Kratzer) - Dent / paintcoat damage - Repair and paint |
| 14  | Vehicle glazing         | Windscreen (Rissbildung) - Stone chips - Replace                             |

## Wear and tear

| No. | Component group             | Description                                        |
|-----|-----------------------------|----------------------------------------------------|
| 1   | Interior                    | Cargo area floor (Kratzer) - Holes - No deduction  |
| 2   | Body                        | Partition wall (Dellen) - Scratched - No deduction |
| 3   | Side panel - rear left side | Side panel - Scratched - No deduction              |
| 4   | Wing mirror - right side    | Cap - Scratched - No deduction                     |
| 5   | Rear bumper                 | Rear bumper - Scratched - No deduction             |
| 6   | Interior                    | Interior - Scratch(es) - No deduction              |

The vehicle shows signs of wear commensurate with its age and use.

## Previous damages

| No. | Previous damage                                                   | Extent of damage (Net) |
|-----|-------------------------------------------------------------------|------------------------|
| 1   | Front, Side - left, Provided by user / customer, from 11 Feb 2024 | 3.897,34 €             |
| 2   | Side - left, Provided by user / customer, from 28 Oct 2021        | 4.614,18 €             |

## Repainting

| No. | Repainting                                                                                   |
|-----|----------------------------------------------------------------------------------------------|
| 1   | Mudguard - left side, Professionally carried out, Invoice of repair done Non-existent        |
| 2   | Side panel - rear left side, Professionally carried out, Invoice of repair done Non-existent |

## Paint coat thickness measurement

|                      |        |                             |        |
|----------------------|--------|-----------------------------|--------|
| Mudguard - left side | 191 µm | Side panel - rear left side | 191 µm |
|----------------------|--------|-----------------------------|--------|



## Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features  
*(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.  
*(Functional tests of driver assistance systems are not included in the scope of services!)*
- a photo documentation of the vehicle

## Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view ([Online link](#))



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.




Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.




Figure 40: Misc.



Figure 41: Misc.




Figure 42: Misc.



**Figure 43:** Misc.




**Damage 1:** Body: Identification plate - Missing - Replace



**Damage 2:** Equipment: Tirefit filler - Expired - Replace



**Damage 3:** Door - front left side: Door edge - Scratched - Smart repair



**Damage 3:** Door - front left side: Door edge - Scratched - Smart repair



**Damage 3:** Door - front left side: Door edge - Scratched - Smart repair




**Damage 3:** Door - front left side: Door edge - Scratched - Smart repair



**Damage 4:** Sliding door, right: Sliding door (Verkleidung) - Broken / torn - Replace



**Damage 4:** Sliding door, right: Sliding door (Verkleidung) - Broken / torn - Replace




**Damage 5:** Steering system: Steering wheel - Scratched - Smart repair




**Damage 5:** Steering system: Steering wheel - Scratched - Smart repair



**Damage 6:** Door - front right side: Door - Scratched - Smart repair




**Damage 6:** Door - front right side: Door - Scratched - Smart repair



**Damage 7:** Front bumper: Front bumper - Scratched - Smart repair



**Damage 7:** Front bumper: Front bumper - Scratched - Smart repair



**Damage 7:** Front bumper: Front bumper - Scratched - Smart repair



**Damage 8:** Trim / covers: Boot lid - interior trim (Kratzer) - Broken / torn - Replace



**Damage 8:** Trim / covers: Boot lid - interior trim (Kratzer) - Broken / torn - Replace




**Damage 8:** Trim / covers: Boot lid - interior trim (Kratzer) - Broken / torn - Replace



**Damage 8:** Trim / covers: Boot lid - interior trim (Kratzer) - Broken / torn - Replace



**Damage 8:** Trim / covers: Boot lid - interior trim (Kratzer) - Broken / torn - Replace




**Damage 9:** Headlight: Headlight - left side - Scratched - Replace



**Damage 9:** Headlight: Headlight - left side - Scratched - Replace



**Damage 9:** Headlight: Headlight - left side - Scratched - Replace



**Damage 9:** Headlight: Headlight - left side - Scratched - Replace




**Damage 9:** Headlight: Headlight - left side - Scratched - Replace



**Damage 10:** Bonnet: Bonnet (Steinschlag) - Corrosion - Repair and paint



**Damage 10:** Bonnet: Bonnet (Steinschlag) - Corrosion - Repair and paint



**Damage 10:** Bonnet: Bonnet (Steinschlag) - Corrosion - Repair and paint



**Damage 10:** Bonnet: Bonnet (Steinschlag) - Corrosion - Repair and paint



**Damage 10:** Bonnet: Bonnet (Steinschlag) - Corrosion - Repair and paint



**Damage 10:** Bonnet: Bonnet (Steinschlag) - Corrosion - Repair and paint



**Damage 10:** Bonnet: Bonnet (Steinschlag) - Corrosion - Repair and paint



**Damage 10:** Bonnet: Bonnet (Steinschlag) - Corrosion - Repair and paint




**Damage 11:** Sliding door, right: Sliding door (Dellen) - Scratched - Repair and paint



**Damage 11:** Sliding door, right: Sliding door (Dellen) - Scratched - Repair and paint



**Damage 11:** Sliding door, right: Sliding door (Dellen) - Scratched - Repair and paint



**Damage 11:** Sliding door, right: Sliding door (Dellen) - Scratched - Repair and paint



**Damage 11:** Sliding door, right: Sliding door (Dellen) - Scratched - Repair and paint



**Damage 11:** Sliding door, right: Sliding door (Dellen) - Scratched - Repair and paint



**Damage 11:** Sliding door, right: Sliding door (Dellen) - Scratched - Repair and paint



**Damage 12:** Boot lid / rear door: Rear door - right side (Kratzer) - Deformed - Repair and paint



**Damage 12:** Boot lid / rear door: Rear door - right side (Kratzer) - Deformed - Repair and paint




**Damage 12:** Boot lid / rear door: Rear door - right side (Kratzer) - Deformed - Repair and paint



**Damage 12:** Boot lid / rear door: Rear door - right side (Kratzer) - Deformed - Repair and paint




**Damage 12:** Boot lid / rear door: Rear door - right side (Kratzer) - Deformed - Repair and paint



**Damage 12:** Boot lid / rear door: Rear door - right side (Kratzer) - Deformed - Repair and paint



**Damage 12:** Boot lid / rear door: Rear door - right side (Kratzer) - Deformed - Repair and paint



**Damage 12:** Boot lid / rear door: Rear door - right side (Kratzer) - Deformed - Repair and paint



**Damage 13:** Boot lid / rear door: Rear door - left side (Kratzer) - Dent / paintcoat damage - Repair and paint



**Damage 13:** Boot lid / rear door: Rear door - left side (Kratzer) - Dent / paintcoat damage - Repair and paint




**Damage 13:** Boot lid / rear door: Rear door - left side (Kratzer) - Dent / paintcoat damage - Repair and paint



**Damage 13:** Boot lid / rear door: Rear door - left side (Kratzer) - Dent / paintcoat damage - Repair and paint



**Damage 13:** Boot lid / rear door: Rear door - left side (Kratzer) - Dent / paintcoat damage - Repair and paint



**Damage 13:** Boot lid / rear door: Rear door - left side (Kratzer) - Dent / paintcoat damage - Repair and paint




**Damage 13:** Boot lid / rear door: Rear door - left side (Kratzer) - Dent / paintcoat damage - Repair and paint



**Damage 13:** Boot lid / rear door: Rear door - left side (Kratzer) - Dent / paintcoat damage - Repair and paint



**Damage 13:** Boot lid / rear door: Rear door - left side (Kratzer) - Dent / paintcoat damage - Repair and paint



**Damage 14:** Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace



**Damage 14:** Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace



**Damage 14:** Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace



**Damage 14:** Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace



**Wear and tear 1:** Interior: Cargo area floor (Kratzer) - Holes - No deduction



**Wear and tear 1:** Interior: Cargo area floor (Kratzer) - Holes - No deduction



**Wear and tear 1:** Interior: Cargo area floor (Kratzer) - Holes - No deduction



**Wear and tear 1:** Interior: Cargo area floor (Kratzer) - Holes - No deduction



**Wear and tear 2:** Body: Partition wall (Dellen) - Scratched - No deduction




**Wear and tear 2:** Body: Partition wall (Dellen) - Scratched - No deduction



**Wear and tear 5:** Rear bumper: Rear bumper - Scratched - No deduction




**Wear and tear 5:** Rear bumper: Rear bumper - Scratched - No deduction



**Repainting 1:** Mudguard - left side



**Repainting 1:** Mudguard - left side



**Repainting 2:** Side panel - rear left side



**Repainting 2:** Side panel - rear left side



# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WV1ZZZ7HZKH186751

Hersteller / Modell: VOLKSWAGEN VW Transporter T6 Kurz BlueMotion

| Datum      | KM-Stand | Beschreibung                                                                                                                                                               |
|------------|----------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 24.01.2025 | 99.830   | Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                                                   |
| 19.08.2024 | 91.443   | Batterie ern; Systemtest/Eigendiagnose                                                                                                                                     |
| 14.05.2024 | 89.300   | AU; Wartung Sonstiges                                                                                                                                                      |
| 04.01.2024 | 82.650   | Bremse Sonstiges; Bremsklötze hinten; Bremsscheiben hinten; Reparatur Sonstiges; Systemtest/Eigendiagnose; Wartung Sonstiges                                               |
| 05.12.2023 | 82.279   | Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze vorne; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges |
| 25.10.2022 | 56.502   | AU; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                                               |
| 09.05.2022 | 42.017   | AU; Kombiinstrument ern; Reparatur Sonstiges; Systemtest/Eigendiagnose; Wartung Sonstiges                                                                                  |
| 19.10.2021 | 30.893   | AU; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                                               |