



Volkswagen Transporter: VDL54P

Vinnumber:	WV1ZZZ7HZKH198571	Versionname:	Transporter 2.0 TDI 75kW L2H1 GB
First Registrationdate:	21/11/2019	Fiscalpower:	
Expertise Mileage:	118819	Power Kw:	75
Bodytype:		Body colour:	Candywit
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Type of rims (mounted):	Steel
Fueltype:	Diesel	Parking lot:	970
Number of seats:	2		
Type of rims (mounted):	Steel		
Maintenance needed:	Yes		

Options

Number of keys total	3	Telephone equipment
GPS		Central consol F
Manual climate control		Rear parking sensors
Windows electric F		Tow bar removable
Radio multimedia		Roof rack
		Sliding door right-side

Degree of wear

	205/65/16/107 T			
Winter tyres:	Fr.L.	Continental: 7,3 mm	Fr.R.	Continental: 6,1 mm
	Re.L.	Continental: 3,7 mm	Re.R.	Continental: 3,7 mm
Tyre profile depth FL				7.3
Tyre profile depth FR				6.1
Tyre profile depth RL				3.7
Tyre profile depth RR				3.7
Tyre size FL				205/65 R 16 107 T
Tyre size FR				205/65 R 16 107 T
Tyre size RL				205/65 R 16 107 T
Tyre size RR				205/65 R 16 107 T
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service, Maintenance, Execute



Interior, Stain, Cleaning



Seat cover FL, Burned, Replace




Interior, Smell, Ozone treatment



Outside rear-view mirror housing L, Scratch(es), Replace



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Bonnet, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Smart repair



Bumper grille, Dent(s) and scratch(es), Replace



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace



Side wall RR, Dent(s), Repair and paint (complete)



Sliding door R, Scratch(es), Repair and paint (complete)



Fuel cap cover, Deformed / Strained, Replace and paint



Wheel aperture RR, Scratch(es), Polish



Bumper R, Dent(s), Replace



Roof, Chemical pollution, Polish

