

Vehicle details

VIN	WV1ZZZSYZ J9047402	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	V8-02-RJ	Model	Crafter 35 2.0TDI 103kW L3H3 RWD EL 4d	Maintenance mileage	-
Registration date	30/07/2018	Year	2018	Exterior Color	White Solid
Odometer	206 572 km	Engine size	1968	interior Color	Grey
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	4	Gears	6		

Inspection Details

Inspection date	03/04/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Tow	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel (wheel & tyre)	✓
----------------------------	---

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Winter kit

Continental 235/65/16 Winter 7.0 mm		Continental 235/65/16 Winter 7.0 mm	
Goodyear 235/65/16 Winter 6.0 mm		Goodyear 235/65/16 Winter 6.0 mm	

Exterior

1



PartDoor

PositionFront left

DamagesDented

SeverityDiameter (mm) > 20

Repair modeSmart Repair

3



PartDoor

PositionBack right

DamagesDented

SeverityDiameter (mm) > 20

Repair modeSmart Repair

5



PartStep plate

PositionFront left

DamagesScratched

Severity-

Repair modeFor info

7



PartSill

PositionRight

DamagesDent & Chips

SeverityDiameter (mm) > 20

Repair modeRepair

9



PartWindscreen

Position-

DamagesStone impact

Severity-

Repair modeFor info

11



PartDoor

PositionFront right

DamagesDented

SeverityDiameter (mm) > 20

Repair modeSmart Repair

2



PartDoor

PositionBack left

DamagesDented

SeverityDiameter (mm) > 20

Repair modeSmart Repair

4



PartBumper

PositionBack

DamagesScratched

SeverityLength (cm) > 10

Repair modeRepair

6



PartSill

PositionLeft

DamagesScratched

SeverityLength (cm) > 10

Repair modeRepair

8



PartDoor

PositionSide right

DamagesDented

SeverityDiameter (mm) > 20

Repair modeSmart Repair

10



PartWing

PositionFront left

DamagesDented

SeverityDiameter (mm) > 20

Repair modeSmart Repair