



status report

customer: Bank 11, Neuss
contract number: 1089861130
reference:

vehicle data

Volkswagen Touran Highline

Vehicle identification number	WVGZZZ1TZW063845	mileage read:	222268 km
First Registration / construction year:	28.12.2011 / 2011	Visit Date / place of birth:	19.09.2025 Riedstadt-Goddelau
Bodywork:	cars	Re - import:	no
Body type:	VAN / MPV	KBA no. :	0603//AKZ
Fuel / emission class:	gasoline / € 5	transmission type:	automatic
Displacement / power:	1390 ccm / 125 kW (170 PS)	Engine:	front-wheel drive
paint:	Acapulcoblau Metallic	Number of previous owners:	Unbekannt
Doors / seats:	5 / 7	number keys:	2
Next HU / AU:	- / -	cushion type:	Cloth / Alcantara
Service book available:	yes	Interior Color:	gray
smoking vehicle:	yes	Last service km / on the:	132354 / 05.05.2021
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	-	state outside:	3 - Average
documents:		condition inside:	3 - Average
visit condition:	-		
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	yes / -	132354 / 05.05.2021

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	aluminum
1st axis - Left / states .	Nexen	205/60/R16/92V 3 mm
1st axis - right / states .	Nexen	205/60/R16/92V 3 mm
2nd axis - Left / states .	Nexen	205/60/R16/92V 3 mm
2nd axis - right / states .	Nexen	205/60/R16/92V 3 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• 2.Sitzreihe with individual seats (3 seats) • Storage pocket on front seat backrests • Airbag Driver / passenger side • Acceleration skid control (ASR) • Display for wash water level • Amenities High Line • Mirrors, aspheric, left • painted mirrors • brake Assist • Doppeltonhorn • Electron. Stability Program (ESP) • Electric windows front + rear • Textile floor mats • Cruise control system (cruise control) • Leather handbrake grip • Interior aluminum inlays Black • Dust and pollen filter with activated carbon filter • Isofix admissions for child seat in back seat • Folding tables integrated into the driver's and front passenger seat • Lumbar support front • Steering column (steering wheel) mechan. adjustable height / length adjustment • Front center armrest • Multi-function display Premium • Rear fog light • Tire repair kit • Gearshift / selector lever leather • Windscreen wipers with rain sensor • Drawer / storage compartment under front seats • Body color side moldings with chrome inserts	• 3-point rear center seat belt • Airbag switched off • Anti- lock braking system (ABS) • Drive Front Wheel Drive • Audio system RCD 310 with MP3 playback function (Radio / CD) <i>Antennen-Diversity, Multimediabuchse AUX-IN</i> • Automatic headlight activation (AS) <i>Lichtassistent (Coming Home, Leaving Home)</i> • Power side mirrors . adjustable and heated • Indicator integrated into mirrors • Anodized roof rails • Electron. Differential lock (EDL) • Driving Assistance System Hill Start Assist • Front glass laminated glass tinted • Luggage compartment cover / shade • Transmission 7 - speed dual - clutch gearbox DSG • Lockable glove compartment • Interior cloth / alcantara • Rearview mirror with auto dip • Body 4 doors • Climatronic air conditioning 2-zone • Steering wheel (leather) with multifunction • Reading lights front and rear • Engine 1.4 ltr. - 125 kW 16V TSI • Fog lights with static cornering light • Non smoking package • Low emissions Euro 5 emissions standard • Heated windshield washer nozzles • Headlight cleaning system (SRA) • Front side airbags with head airbag unit



• Seats, front height adjustable • Heated front seats • Sun visors with mirrors (illuminated) • Exterior door handles body color • Glazing behind darkened (65 %) • Tinted heat insulating glass green	• Controlled electronic power steering (Servotronic) • Front sports seats <i>Sitze: Sportsitz vorn links, Sitze: Sportsitz vorn rechts</i> • Seat back folded down front right • bumper painted • First aid kit and warning triangle • Immobiliser (electronic) • Central <i>Fernbedienung für Zentralverriegelung</i>
---	---

special Features	
• 2 seats in addition - 2.Sitzreihe back • Bi - Xenon headlights with dynamic cornering lights <i>Scheinwerfer-Reinigungsanlage (SRA), Anzeige für Waschwasserstand</i> • LM rims 6,5x16 (Sedona) • Metallic paint • Digital radio reception (DAB +)	• Trailer hitch (ball head removable) • Driving Assistance System Park Assist (Park Assist) <i>Einparkhilfe vorn und hinten</i> • Steering wheel with shift paddles for the DSG - operation • RNS 315 navigation module (for audio system RCD 310) <i>Multimediabuchse AUX-IN</i> • Top Package <i>Panorama-Schiebedach elektrisch, Multimediabuchse MEDIA-IN, Reifenkontroll-Anzeige, Ablagefach am Dachhimmel, Diebstahl-Warnanlage mit Innenraumüberwachung</i>

We remind you that the data provided were taken from the DAT database.\r\nNo liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed.
Mileage plausible:	not testable not testable Wartung Fällig
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment
Rep. Predamages / -height gross: Expertly repaired

	On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			in order		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1. Sidewall - Rear - right	Subsequently painted	acceptable
2. Door Rear - right	Subsequently painted	acceptable
3. Armaturen Brett Klappe	Breakage	Replace
4. maintenance	Due	Replace
5. Lüftungsgitter Vorne Mitte Versteller	Damaged	Replace
6. Mittelkonsole Hinten Verkleidung	Missing	Replace
7. AHK Abnehmbar Zweitschlüssel	Missing	Replace
8. Rim rear - right	Scratch(es)	Paint
9. Rim front - right	Damaged	Replace
10. Front bumper	Scrape	Paint
11. hood	Wear and tear	acceptable
12. Front fender - left	Deformed	Refurbish and paint
13. Front door - left	Scratch(es)	Paint
14. Rear door - left	Scratch(es)	Paint
15. Dachhimmel	Dirty	
16. headlining	Damaged	Smart repair
17. Türeinstieg Hinten - Links	Damaged	Refurbish and paint
18. Rear door seal - left	Damaged	Replace
19. Sidewall - Rear - Left	Scratch(es)	Paint
20. tailgate	Deformed	Refurbish and paint
21. Rear bumper	Damaged	Refurbish and paint
22. tailgate trim	Damaged	Smart repair
23. side skirt - right	Scratch(es)	Paint
24. Türeinstieg Hinten - Rechts	Damaged	Refurbish and paint
25. Front door - right	Deformed	Refurbish and paint
26. Outside Door Handle Front - right	Scrape	Paint
27. Door Rear - right	Delle	Smart repair
28.	Scratch(es)	Paint
29. Front fender - right	Delle	Smart repair
30. Sidewall - Rear - right	Damaged	Paint

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted , and for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



1. Sidewall - Rear - right



2. Door Rear - right



3. Armaturenbrett Klappe



3. Armaturenbrett Klappe



5. Lüftungsgitter Vorne Mitte Versteller



6. Mittelkonsole Hinten Verkleidung



8. Rim rear - right



9. Rim front - right



9. Rim front - right



10. Front bumper



10. Front bumper



10. Front bumper




11. hood



11. hood



12. Front fender - left




13. Front door - left



13. Front door - left



14. Rear door - left



14. Rear door - left



14. Rear door - left



15. Dachhimmel



16. headlining



17. Türeinstieg Hinten - Links



18. Rear door seal - left



19. Sidewall - Rear - Left




19. Sidewall - Rear - Left



19. Sidewall - Rear - Left



20. tailgate



20. tailgate



21. Rear bumper



21. Rear bumper



21. Rear bumper



21. Rear bumper




22. tailgate trim



22. tailgate trim



23. side skirt - right



24. Türeinstieg Hinten - Rechts



24. Türeinstieg Hinten - Rechts



25. Front door - right



25. Front door - right




25. Front door - right



25. Front door - right



26. Outside Door Handle Front - right



27. Door Rear - right



28.



29. Front fender - right



30. Sidewall - Rear - right



30. Sidewall - Rear - right



30. Sidewall - Rear - right