



VOLKSWAGEN Touran

Touran 1.6 TDI DPF

VIN NO WVGZZZ1TZDW061354
Registration Number TZDW061354



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	2	2	268057 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2024-06-24	249943	2012-12-17	-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250916094321
Inspection Date / Place	2025-09-16 / ARS Altmann AG Wolnzach	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	1598
Engine Size	1.6	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	134
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Alloys wheels	Cruise control	Front fog lamps
Remote adjusting wing mirrors	Roof rails	CD Player	Electrically folding wing mirrors
Radio	Airbag Status	Anti-lock braking	Diesel particulate filter
Heated wing mirrors	Remote central locking	Stability control	Central locking
Leather steering wheel	Rear parking sensors		

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	16
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	3	Left Front Tyre Depth	3
Right Rear Tyre Depth	3	Left Rear Tyre Depth	3

Cosmetic Damage

14 Schäden



1 Schäden




Component		Damage	Comments
1	Tailgate	Paint / Poor Previous Repair	
2	Roof	Bodywork / Dent / Dent	
3	Side Panel / Back Right	Bodywork / Dent / Dent	
4	Hood	Paint / Scratch / Scuff	
5	Rim / Front Left	Out of Bodywork / Scratch	
6	Door / Front Left	Paint / Corrosion	
7	Rocker Panel / Center Left	Paint / Corrosion	
8	Door / Front Left	Paint / Scratch / Scuff	
9	Pillar / Back Left	Bodywork / Dent / Dent	
10	Bumper / Back	Paint / Scratch / Scuff	
11	Pillar / Back Right	Bodywork / Dent / Dent	
12	Seat / Front Right	Interior / Dirty	


13	Rocker Panel / Center Right	Paint / Corrosion
14	Rim / Front Right	Out of Bodywork / Scratch
15	Bumper / Front	Paint / Stone Chip




1. Tailgate
Paint / Poor Previous Repair -



2. Roof
Bodywork / Dent / Dent -




3. Side Panel / Back Right
Bodywork / Dent / Dent -




4. Hood
Paint / Scratch / Scuff -



5. Rim / Front Left
Out of Bodywork / Scratch -



6. Door / Front Left
Paint / Corrosion -



7. Rocker Panel / Center Left
Paint / Corrosion -



8. Door / Front Left
Paint / Scratch / Scuff -




9. Pillar / Back Left
Bodywork / Dent / Dent -



10. Bumper / Back
Paint / Scratch / Scuff -



11. Pillar / Back Right
Bodywork / Dent / Dent -



12. Seat / Front Right
Interior / Dirty -



13. Rocker Panel / Center Right
Paint / Corrosion -



14. Rim / Front Right
Out of Bodywork / Scratch -



15. Bumper / Front
Paint / Stone Chip -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	!
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
All - wheel Drive	✓	No Dashboard Lights	✓
Tire Pressure Monitoring System	✓		

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	NA	Coolant Fluid	✓
--------------	----	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	Fume Quantity	✓
Power Loss	✓		
Clutch			
Clutch Functioning	✓		
Brake			
Brake System Anomaly	!		
General			

- ✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage
- ! Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- ☐ Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)