



status report

customer: BCA Autoauktionen GmbH
contract number:
reference:

vehicle data

Volkswagen Touran Cup

Vehicle identification number	WVGZZZ1TZFW021814	mileage read:	180687 km
First Registration / construction year:	08.10.2014 / 2014	Visit Date / place of birth:	16.05.2025 Knautnaundorf
Bodywork:	cars	Re - import:	no
Body type:	VAN / MPV	KBA no. :	0603//ATE
Fuel / emission class:	diesel / € 5	transmission type:	manual transmission
Displacement / power:	1598 ccm / 77 kW (105 PS)	Engine:	front-wheel drive
paint:	orange	Number of previous owners:	Unbekannt
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	yes	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / 15.03.2024
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	-	state outside:	3 - Average
documents:		condition inside:	3 - Average
visit condition:	-		
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
CD / DVD	2	maintained:	- / 15.03.2024
		yes / -	

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	Winter tires	steel
1st axis - Left / states .	Dunlop	205/55/R16/91H 4 mm
1st axis - right / states .	Dunlop	205/55/R16/91H 4 mm
2nd axis - Left / states .	Anderer	205/55/R16/91H 6 mm
2nd axis - right / states .	Anderer	205/55/R16/91H 6 mm
traffic Safety:	roadworthy	
spare wheel:	Tirefit	
state spare wheel:	-	

standard equipment

- | | |
|---|---|
| <ul style="list-style-type: none"> • 2.Sitzreihe with individual seats (3 seats) • Storage pocket on front seat backrests • Airbag Driver / passenger side • Acceleration skid control (ASR) • Audio system RCD 310 with MP3 playback function (Radio / CD)
<i>Antennen-Diversity, Multimediabuchse AUX-IN</i> • Automatic headlight activation (AS)
<i>Lichtassistent (Coming Home, Leaving Home)</i> • Power side mirrors . adjustable and heated • Indicator integrated into mirrors • Anodized roof rails • Aluminum door sill plates • Electron. Stability Program (ESP) • Driving Assistance System Park Assist (Park Assist)
<i>Einparkhilfe vorn und hinten</i> • Front glass laminated glass tinted • Luggage compartment cover / shade • Transmission 6-speed • Lockable glove compartment • Dust and pollen filter with activated carbon filter • Isofix admissions for child seat in back seat • LED License Plate Lights • Climatronic air conditioning 2-zone • Steering wheel (leather) with multifunction • Reading lights front and rear • Front center armrest • Multifunctional Display Plus • Fog lights with static cornering light • Non smoking package | <ul style="list-style-type: none"> • 3-point rear center seat belt • Airbag switched off • Anti- lock braking system (ABS) • Drive Front Wheel Drive • Comfort Line • Mirrors, aspheric, left • painted mirrors • brake Assist • Doppeltonhorn • Electron. Differential lock (EDL) • Driving Assistance System Hill Start Assist • Electric windows front + rear • Textile floor mats • Cruise control system (cruise control)
<i>Fahrassistenz-System: Müdigkeitserkennung</i> • Leather handbrake grip • Interior inlays titanium silver • Interior mirror dimming • Body 4 doors • Folding tables integrated into the driver's and front passenger seat • Lumbar support front • Steering column (steering wheel) mechan. adjustable height / length adjustment • LM rims • Engine 1.6 ltr. - 77 kW TDI DPF • MEDIA- IN • Rear fog light • Tire repair kit • Rußpartikelfilter • Gearshift / selector lever leather |
|---|---|

• Tire pressure warning indicator • Low emissions Euro 5 emissions standard • Windscreen wipers with rain sensor • Front side airbags with head airbag unit • Controlled electronic power steering (Servotronic) • Seats, front height adjustable • Sun visors with mirrors (illuminated) • Daytime running lights • First aid kit and warning triangle • Immobiliser (electronic) • Tinted heat insulating glass green	• Drawer / storage compartment under front seats • Body color side moldings • Seat cover / upholstery fabric • Seat back folded down front right • bumper painted • Exterior door handles body color • Glazing behind darkened (65 %) • Winter package <i>Scheinwerfer-Reinigungsanlage (SRA), Scheibenwaschdüsen heizbar, Anzeige für Waschwasserstand, Sitzheizung vorn</i> • Central <i>Fernbedienung für Zentralverriegelung</i>
--	--

special Features	
• Trailer hitch (ball head removable) • RNS 315 navigation module (for audio system RCD 310) <i>Multimediabuchse AUX-IN</i>	• Business Package Premium with Navigation <i>Nebelscheinwerfer mit integriertem Abbiegelicht, Vorrüstung Mobiltelefon/Handy Plus mit Bluetooth-Schnittstelle, Multimediabuchse MEDIA-IN, Multifunktionsanzeige Plus, Gepäckraum-Abtrennung (Netztrennwand)</i> • Winter tires also

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	yes yes
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	If not properly repaired The vehicle repaired previous damage have been observed on the body outer skin that are exposed and apparently with no disassembly of components with residual traces accident . If there is an impairment of the observed accident before it was taken into

**Layers of paint thickness
measurement:**

account in if conducted vehicle valuation.

Out of tolerance

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit

Alternator / Generator:	✓ examined limited	Battery / accumulator:	✓ examined limited
oil loss:	✓ examined limited		
air conditioning:	✓ in order	lighting system:	✓ examined limited
coupling:	✓ examined limited	exhaust System:	✓ examined limited
engine running:	✓ examined limited	shock absorber:	✓ examined limited
transmission:	✓ examined limited		

Performed testing technology

Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	A function of the air conditioning was found to visiting time .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1. Front fender - left	Subsequently painted	acceptable
2. Fahrzeug (Farbtonunterschied, Spaltmaße ungenau)	Execution defect	Paint
3. tailgate	Delle	Refurbish and paint
4. roof	Delle	Refurbish and paint
5. Seitenwand hinten links		Refurbish and paint
6. Rear door - left	Rust	Refurbish and paint
7. Rear door - left	Rust	Refurbish and paint
8. Türleiste vorne links	Scratch(es)	Refurbish and paint
9. side skirt - left	Material wear	Paint
10. Kofferraum Innenraum	Wear and tear	acceptable
11. key	Not okay	Replace
12. maintenance	Due	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims




rims



engine compartment



service book



Others



Navigation system



1. Front fender - left



2. Fahrzeug (Farbtonunterschied, Spaltmaße ungenau)



2. Fahrzeug (Farbtonunterschied, Spaltmaße ungenau)



2. Fahrzeug (Farbtonunterschied, Spaltmaße ungenau)




2. Fahrzeug (Farbtonunterschied, Spaltmaße ungenau)



2. Fahrzeug (Farbtonunterschied, Spaltmaße ungenau)



2. Fahrzeug (Farbtonunterschied, Spaltmaße ungenau)



3. tailgate



3. tailgate



4. roof



4. roof



5. Seitenwand hinten links




5. Seitenwand hinten links



5. Seitenwand hinten links



5. Seitenwand hinten links



5. Seitenwand hinten links



6. Rear door - left



6. Rear door - left



7. Rear door - left



7. Rear door - left



8. Türleiste vorne links



8. Türleiste vorne links



9. side skirt - left



9. side skirt - left




10. Kofferraum Innenraum




10. Kofferraum Innenraum



10. Kofferraum Innenraum



11. key



11. key