



status report

customer: Bank 11, Neuss
contract number: 1187389230
reference:

vehicle data

Volkswagen Touran Comfortline BMT/Start-Stopp

Vehicle identification number	WVGZZZ1TZLW021842	mileage read:	216114 km
First Registration / construction year:	28.11.2019 / 2019	Visit Date / place of birth:	20.05.2025 Dorfmark
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	0603//BWR
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1968 ccm / 110 kW (150 PS)	Engine:	front-wheel drive
paint:	white	Number of previous owners:	Unbekannt
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	03.2026 / 03.2026	cushion type:	substance
Service book available:	digital	Interior Color:	Multicolor
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	4 - moderate
visit condition:	-	condition inside:	4 - moderate
state general:	4 - moderate		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
SD Card	2	digital / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Anderer	205/60/R16/96H 6 mm
1st axis - right / states .	Anderer	205/60/R16/96H 6 mm
2nd axis - Left / states .	Michelin	205/60/R16/92H 5 mm
2nd axis - right / states .	Michelin	205/60/R16/92H 5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• 2.Sitzreihe single seats and armrests (3 seats) • Storage compartments in roof console • Airbag Driver / passenger side • Acceleration skid control (ASR) • Mirrors, aspheric, left • painted mirrors • Indicator integrated into mirrors • Chrome package <i>Chromefassung Lichtschalter</i> • roof rails • Park Distance Control (front and rear) • Electron. Stability Program (ESP) • Driving Assistance System Multi Collision Brake (Multi Collision Brake) • Driving Assistance System environment monitoring system (front assist) with City Emergency Braking <i>Fahrassistenz-System: City-Notbremsfunktion</i> • Window moldings black • Textile floor mats • Luggage compartment cover / shade • Luggage compartment lighting in addition • Transmission 7 - speed dual - clutch gearbox DSG • rear window wiper • Occupant protection system proactively • Body 4 doors • Knee airbag , driver's side • Black grille with chrome trim • Reading lights front and rear • Front center armrest height / longitudinally adjustable • Engine 2.0 ltr. - 110 kW TDI	• 3-point rear center seat belt • Airbag switched off • Anti- lock braking system (ABS) • Drive Front Wheel Drive • Power side mirrors . adjustable and heated • Outside temperature display • brake Assist • Headliner fabric , gray • Doppeltonhorn • Electron. Differential lock (EDL) • Trailer stabilization program • Driving Assistance System fatigue detection sensor • Electric windows front + rear • Front glass laminated glass tinted • Luggage management package • Luggage compartment lighting • Luggage compartment floor height adjustable • Glove compartment with cooling function • Interior Inlays New Brushed Design • Isofix admissions for child seat in back seat • LED License Plate Lights • Rear headrests (3- fold) • Steering column (steering wheel) mechan. adjustable height / length adjustment • LM rims <i>Diebstahlsicherung für Räder (Felgenschlösser)</i> • Mobile Online Services VW Connect • Positive Torque Regulator (MSR) • Rear fog light • Parking brake electrically <i>Auto-Hold-Funktion</i>

- Multifunctional Display Plus
- Non smoking package
- Tire repair kit
- Low emissions according to Euro 6d TEMP emission standard
- SCR (AdBlue technology)
- Controlled electronic power steering (Servotronic)
- Seat belts front with belt tensioner, height adjustable
- Comfort front seats
- Sun visors with mirrors (illuminated)
- Socket (12V) port in the trunk / cargo area
- Exterior door handles body color
- Warning system for rear seat belts
- Immobiliser (electronic)
- Central

- Rußpartikelfilter
- Gearshift / selector lever leather
- Front side airbags with head airbag unit
- Belt tensioner rear outside
- Seats, front height adjustable
- Seat back folded down front right
- Start / Stop system
- bumper painted
- First aid kit and warning triangle
- Warning system for safety
- Tinted heat insulating glass green
- Central locking with remote control

special Features

- Audio System Composition Media (MP3 playback capability , Radio / CD player , Bluetooth)
Antennen-Diversity, Audiosystem: CD-Player, Multimedia-Schnittstelle USB (iPhone / iPod)
- Driving Assistance System lane change assistant (Side Assist)
Fahrassistenz-System: Blind Spot Sensor mit Auspark-Assistent
- Metallic paint
- Mobile phone interface Comfort with wireless charging function
Multimedia-Schnittstelle 2 x USB (iPhone / iPod) mit AUX-IN
- Fog lights with static cornering light
- Rear View Camera
- Glazing behind darkened (65 %)

- Business Package Premium with Navigation
Scheinwerfer-Reinigungsanlage (SRA), Scheibenwaschdüsen heizbar, Multimedia-Schnittstelle 2 x USB (iPhone / iPod) mit AUX-IN, Anzeige für Waschwasserstand, Gepäckraum-Abtrennung (Netztrennwand), Klimaanlage Climatronic 3-Zonen, Innenraumfilter: Staub- und Pollenfilter mit Aktivkohlefilter, Sitzheizung vorn, Sitzbezug / Polsterung: Stoff / Mikrovlies ArtVelours, Sitz vorn links ErgoActive (inkl. Sitzverstellung 14-Wege, Massagefunktion), Sitze: Top-Komfortsitze vorn, Sitz vorn links mit ausziehbarer Oberschenkelaufklappung, Sitz vorn links mit Massagefunktion, Lendenwirbelstützen vorn, links elektr. verstellbar, Schublade / Ablagefach unter Sitz vorn rechts, Fahrassistenz-System: Autom. Distanzregelung (ACC) mit Umfeldbeobachtungssystem (Front assist, bis 210 km/h), Geschwindigkeits-Begrenzeranlage, Fahrassistenz-System: City-Notbremsfunktion
- Steering wheel (leather) with multifunction and switching function
- Mobile Online Services Car Net
- Navigation module Discover Media (audio system)
Volkswagen Media Control, Multimediabuchse AUX-IN und USB-Schnittstelle
- Tire Pressure Monitoring System
- Mirror package
Außenspiegel elektr. anklappbar, Außenspiegel mit Umfeldleuchte, Außenspiegel mit Abblendautomatik, links,

*Außenspiegel mit autom. Absenkfunktion, rechts,
Automatische Fahrlichtschaltung (ALS), Lichtassistent
(Coming Home, Leaving Home), Scheibenwischer mit
Regensensor, Innenspiegel mit Abblendautomatik*

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	found At the unrepaired vehicle accident damage were observed on visual examination on the body skin .
reference:	Fahrzeug mit bestehenden Unfallschaden, zur Schadensermittlung wurden keine Demontagearbeiten durchgeführt, verborgen gebliebene Schäden können nicht ausgeschlossen werden. Unfallschaden Kosten wurden überschlägig Kalkuliert, Kostenerweiterung möglich.

Overview conducted technology audit							
Alternator / Generator:			examined limited	Battery / accumulator:			
oil loss:			examined limited			examined limited	
air conditioning:			examined limited	lighting system:			examined limited
coupling:			unavailable	exhaust System:			examined limited
engine running:			examined limited	shock absorber:			examined limited
transmission:			examined limited				

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen Unfallschaden Stoßfänger vorne rechts, Kotflügel VR Schaden und Kosten Erweiterung möglich

damage



	component	Damage	Rep kind
1.	maintenance	Due	Replace
2.	proof of maintenance	Missing	Replace
3.	tailgate	Sticker	
4.	Rear bumper	Damaged	Replace
5.	Sidewall - Rear - Left	Deformed (slightly)	Refurbish and paint
6.	roof	chipped paint	Smart repair
7.	Rim front - left	Scratch(es)	Paint
8.	Front fender - left	Damaged	Paint
9.	Front bumper	Accident damage	Replace
10.	hood		Refurbish and paint
11.	Front fender - right	Accident damage	Refurbish and paint
12.	Rim front - right	Scratch(es)	Paint
13.		Scrape	Smart repair
14.	Front door - right	Deformed (slightly)	Refurbish and paint
15.	Door Rear - right	Damaged	Refurbish and paint
16.	Sidewall - Rear - right	Damaged	Refurbish and paint
17.	exterior body	Surface scratch(es)	
18.		Wear and tear	acceptable
19.		Dirty (strong)	
20.		Odour	Ozone treatment
21.		Damaged	Replace
22.		Burn hole	Replace
23.		Dirty (animal hair)	
24.	Türeinstieg Hinten - Rechts	Delle	Smart repair

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims



rims



engine compartment



service book



Others



Navigation system



3. tailgate



3. tailgate



4. Rear bumper




4. Rear bumper



4. Rear bumper



4. Rear bumper



4. Rear bumper




5. Sidewall - Rear - Left



5. Sidewall - Rear - Left



6. roof



6. roof



7. Rim front - left



7. Rim front - left



8. Front fender - left



8. Front fender - left



9. Front bumper



9. Front bumper



9. Front bumper



10. hood




10. hood



10. hood



11. Front fender - right



11. Front fender - right



11. Front fender - right



12. Rim front - right



12. Rim front - right



12. Rim front - right



13.



13.



14. Front door - right



14. Front door - right



15. Door Rear - right



15. Door Rear - right



15. Door Rear - right



16. Sidewall - Rear - right



16. Sidewall - Rear - right



16. Sidewall - Rear - right



17. exterior body



18.



18.



19.



19.



21.



21.




21.



22.



22.



23.




23.



23.



24. Türeinstieg Hinten - Rechts



24. Türeinstieg Hinten - Rechts