



Expertise

Protocol number: 41081683  
Order No. / Reference: 25013382  
Inspection date: 11 Aug 2025

Manufacturer: Volkswagen

Model: Touran 2.0 TDI SCR Comfortline

VIN: WVGZZZ1TZNW000957



Vehicle details

Manufacturer / Type / Model / Equipment

Volkswagen Touran 2.0 TDI SCR Comfortline

Vehicle Identification number WVGZZZ1TZNW000957

Mileage (Read) 59,839 km

First registration 9 Sept 2021

Number of holders 1

Power / Engine displacement 90 kw / 1,968 ccm

Fuel type / Cylinder Diesel / 4

Gearbox / Number of gears Manual / 6

Type of drive Front drive

Type of vehicle Van

Colour / colour code Reflexsilber metallic (A7W)

Doors / Seats 5 / 5

Upholstery type Cloth

Colour of upholstery Black



## Vehicle details

<b>Maintenance booklet / proof</b>	digital proof / complete	<b>Next maintenance in</b>	15,200 km
<b>Last maintenance on / at</b>	07/2025 at 59,690 km		
<b>Key is / should be</b>	2 / 2	<b>FZG documents</b>	ZB#2 (B) was available (copy), ZB#1 (S) was not available
		<b>Letter No.</b>	GF289068
<b>Previous damage / Accident</b>	Detectable	<b>Repainting</b>	Detectable
<b>Inspection conditions</b>	sufficient	<b>Lifting equipment / pit</b>	yes
<b>Test drive</b>	Not performed	<b>Engine function test</b>	Performed
<b>Manufacturer key number/ type code number</b>	0603 / CNT 00057		
<b>Emission standard</b>	EURO6;WLTP;AP;PI/CI; M, N1 I	<b>Fine dust sticker</b>	
<b>Permitted total weight</b>	2,190 kg	<b>Empty weight</b>	

## Tyres

### Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96V	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	205/60 R16 96V	Summer tyres on Light alloy	Pirelli	7mm / 7mm

### Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Light alloy	Bridgestone	6mm / 5mm
2)	205/60 R16 96H	Winter tyres on Light alloy	Bridgestone	6mm / 6mm

### Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 07/2028		

**Legend:** Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel

## Equipment

### Standard equipment

- 2 USB-C ports at the front
- Storage compartments in the roof console
- Airbag, head airbag system for front and rear passengers
- Exterior mirror housings and door handles in body color
- Headlining in Storm Grey
- Decorative inlays "New Brushed Design"
- diesel particulate filter
- Parking assistance
- Electronic Stability Program (ESP) with counter-steering support
- Luggage compartment cover
- Luggage compartment floor height adjustable
- Transmission: 6-speed manual transmission
- Rear window heated
- Interior lights with switch-off delay and dimming function, 2 reading lights front and rear
- Headrests (3) in the 2nd row of seats
- Black radiator grille with chrome strips on the slats
- Headlight range adjustment
- Front center armrest
- Fatigue detection
- Emergency braking assistant "Front Assist"
- Upholstery: Cloth
- Radio "Composition"
- Radio accessories: 8 speakers
- Wheels: light alloy (4) "Karlstad" 6.5 J x 16 (tires 205/60 R 16)
- Leather gearshift knob
- Electromechanical power steering
- Seats: 3 individual seats in the 2nd row
- Seats: Folding tables on the backs of the front seats
- Seats: Lumbar supports in front
- Start-stop system
- Bumpers in body color
- Textile floor mats
- Warning sound and light for unfastened seat belts at the front and rear
- Central locking without safe security, with radio remote control and 2 radio folding keys
- Storage compartment with lid on the instrument panel
- Airbag for driver and front passenger
- Exterior mirrors electrically adjustable and heated
- Brake light, third
- Roof rails black
- Decorative inlays "Piano Black"
- tachometer
- Electronic parking brake including auto-hold function
- Windscreen in heat-insulating glass
- Baggage management package
- Additional luggage compartment lighting
- Speed limiter
- Glove compartment with cooling option
- Rear window wiper with interval control
- ISOFIX anchor points on rear seats
- Air conditioning
- Front headrests
- Steering wheel: leather
- Make-up mirrors in the sun visors, illuminated
- Multifunction display "Plus"
- Non-smoking version
- Emergency call service
- Proactive occupant protection system in conjunction with "Front Assist"
- Tire pressure monitoring indicator (passive)
- Wheels: Tire Mobility Set (12-volt compressor and tire sealant)
- Drawers under the front seats
- Seat belts: 3 three-point automatic belts at the rear
- Seats: Passenger seat backrest completely foldable
- Seats: Comfort seats in the front
- Seats: Front seats height adjustable
- 12V socket on the rear center console
- Daytime running light
- First aid kit and warning triangle and safety vest
- Electronic immobilizer
- Green thermal insulation glazing
- Black trim strips on the side windows

### Extra equipment

- Air Care Climatronic air conditioning system
- Automatic distance control ACC up to 210 km/h and emergency braking assistant "Front Assist"
- Mesh partition
- Paint finish: metallic
- Rear side windows and rear window tinted
- Rear View camera (displays the rear area of the vehicle in real time on the radio/navigation system display)
- Fog lights and cornering lights
- Navigation system "Discover Media" including "Streaming & Internet"



- Steering wheel: Multifunction steering wheel in leather, heated (with controls for multifunction display, radio and telephone - gear lever knob in leather)
- Telephone interface "Comfort" with inductive charging function
- Package: Business Premium (manual transmission) (Air Care Climatronic, active combo filter, adaptive cruise control (ACC), speed limiter, front assist, front lumbar support, electrically adjustable driver's side with massage function, leather-trimmed multifunction steering wheel, mesh partition, heated windshield washer, headlight cleaning system, drawer under right front seat, microfleece seat center panels, heated top-of-the-line comfort seats in the front, emergency brake assist, "Front Assist," height-adjustable front seats, ergoActive seat on the driver's side, washer fluid warning light).

## Brief expert findings

Documents submitted	At the time of the inspection, the registration certificate Part 2 (letter) was available, but the registration certificate Part 1 (certificate) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and a pit were available for examining the vehicle.
Test drive	No test drive/maneuvering was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

## Value reducing factors

No.	Component group	Description
1	Front bumper	Front bumper - Scratched - Smart repair

## Wear and tear

No.	Component group	Description
1	Tail light	Tail lamp - left side - Scratch(es) - No deduction
2	Door - rear right side	Door - Scratch(es) - No deduction
3	Wheel / tyres	Alloy rim - front left side - Scratch(es) - No deduction
4	Vehicle glazing	Windscreen - Stone chips - No deduction
5	Door - rear left side	Door - Scratch(es) - No deduction
6	Door - front right side	Door - Scratch(es) - No deduction
7	2nd wheel set	1 alloy rim - Scratch(es) - No deduction
8	Door - front left side	Door handle - outside - Scratch(es) - No deduction

The vehicle shows signs of wear commensurate with its age and use.

## Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 22 May 2025	2.371,99 €

## Repainting

No.	Repainting
1	Door - front left side, Professionally carried out

## Paint coat thickness measurement

Door - front left side	193 µm
------------------------	--------



## Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features  
*(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.  
*(Functional tests of driver assistance systems are not included in the scope of services!)*
- a photo documentation of the vehicle

## Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

## Comments

Das Fahrzeug befand sich zum Besichtigungszeitpunkt in beschädigten, nicht demontierten Zustand. Schadenausweitung möglich, Zusatzkosten können entstehen.



**Figure 1:** Diagonal front (left)



**Figure 2:** Diagonal front (left)



**Figure 3:** Diagonal front (right)



**Figure 4:** Diagonal front (right)



**Figure 5:** Diagonal rear (left)



**Figure 6:** Diagonal rear (left)



Figure 7: Diagonal rear (right)



Figure 8: Diagonal rear (right)



Figure 9: Interior - front



Figure 10: Interior - rear



Figure 11: Instrument cluster



Figure 12: Instrument panel




Figure 13: interior 360° view



Figure 14: Cargo area



Figure 15: VIN



Figure 16: Mounted tyres




Figure 17: Documents




Figure 18: Documents



Figure 19: Additional tyres




Figure 20: Navigation



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



**Damage 1:** Front bumper: Front bumper - Scratched - Smart repair



**Damage 1:** Front bumper: Front bumper - Scratched - Smart repair



**Damage 1:** Front bumper: Front bumper - Scratched - Smart repair



**Wear and tear 1:** Tail light: Tail lamp - left side - Scratch(es) - No deduction



**Wear and tear 1:** Tail light: Tail lamp - left side - Scratch(es) - No deduction



**Repainting 1:** Door - front left side



**Door - front left side:** 193 µm



# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WVGZZZ1TZNW000957

Hersteller / Modell: VOLKSWAGEN VW Touran 2.0 TDI SCR Comfortline

Datum	KM-Stand	Beschreibung
08.07.2025	59.690	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Reparatur Sonstiges; Wartung Sonstiges
16.10.2024	47.818	AU
17.01.2024	36.244	Bremse Sonstiges; Bremsklötze hinten
14.08.2023	29.975	Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
21.09.2022	15.989	Motoröl b. Wartung; Ölwechsel