



status report

customer: BCA Autoauktionen GmbH

reference:

vehicle data

Volkswagen Tiguan R-Line

Vehicle identification number	WVGZZZ5NZMW560299	mileage read:	32818 km
..			
First Registration / construction year:	12.07.2021 / 2021	Visit Date / place of birth:	15.05.2025 Hoppegarten
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	0603//BZG
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1968 ccm / 110 kW (150 PS)	Engine:	front-wheel drive
paint:	Oryxweiß Perlmutteffekt	Number of previous owners:	2
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	Imitation leather / fabric
Service book available:	digital	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	- / 23.06.2023
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	Eg II (veh - letter)	state outside:	2 - Good
documents:			
visit condition:	-	condition inside:	2 - Good
state general:	2 - Good		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
Hard Disk Drive	2	maintained: digital / yes	- / 23.06.2023
☒ Fernbed . Auxiliary heating	☒ partition net	☒ Wind Deflector	☒ AHK fixed
☒ AHK removable	☒ AHK swivel	☒ AHK key	☒ Fernbed . entertainment
☒ headphone	☒ Load compartment cover	☒ LED headlights	☒ navigation system
☒ Persenning	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Dunlop	255/45/R19/104V 6 mm
1st axis - right / states .	Dunlop	255/45/R19/104V 6 mm
2nd axis - Left / states .	Dunlop	255/45/R19/104V 7 mm
2nd axis - right / states .	Dunlop	255/45/R19/104V 7 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

Unmounted tires		
Tyre / wheel type:	summer tires	aluminum
1st axis - Left / states .	Continental	255/40/R20/101V 4 mm
1st axis - right / states .	Continental	255/40/R20/101V 4 mm
2nd axis - Left / states .	Continental	255/40/R20/101V 4 mm
2nd axis - right / states .	Continental	255/40/R20/101V 4 mm
traffic Safety:	roadworthy	

standard equipment

special Features

standard equipment	
• ABS • board computer • air Conditioning • Multifunction steering wheel • PDC / H • PDC / V + H • cruise control	• Power side mirrors . • Power windows • Climate Control • Fog Lights • PDC / V • power steering • central locking

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	yes yes
reference:	

Note Road Safe:

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross: **no detectable**

As part of a paint film thickness measuring the body outer skin no previous damage could be detected .

Layers of paint thickness measurement:

Within the tolerances

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.

Existing collision damage:

-
-

reference:

Overview conducted technology audit

Alternator / Generator:	✓ examined limited	Battery / accumulator:	✓ in order
oil loss:	✓ examined limited		
air conditioning:	✓ examined limited	lighting system:	✓ examined limited
coupling:	✗ unavailable	exhaust System:	✓ examined limited
engine running:	✓ examined limited	shock absorber:	✓ examined limited
transmission:	✓ examined limited		

Performed testing technology

Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*

damage



	component	Damage	Rep kind
1.	Wartung		Replace
2.	Felge	Scratch(es)	Paint
3.	Türverkleidung h.r.	Wear and tear	acceptable
4.	roof	Wear and tear	acceptable
5.	hood	Wear and tear	acceptable
6.	tailgate	Sticker	

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims




rims



engine compartment



service book



Others



Navigation system



1. Wartung



2. Felge




2. Felge



3. Türverkleidung h.r.



4. roof



4. roof



5. hood



5. hood



6. tailgate