



VOLKSWAGEN TIGUAN: GF-642-ZF

Vinnnummer:	WVGZZZ5NZNW514331	Versionname:	VOLKSWAGEN TIGUAN 2.0 TDI 150 DSG7 R-Line
First Registrationdate:	25/04/2022		Exclusive VP [5P] bva 7-150CH-8cv (SUV)
Expertise Mileage:	53392	Fiscalpower:	110
Bodytype:	SUV	Power Kw:	
Gearbox:	Automatic	Body colour:	Blue
Transmission:	Front	Paint type:	Metallic
Fueltype:	Diesel	Interior colour:	Black
Engine functioning:	Yes	Type of rims (mounted):	Aluminium
Battery functioning:	Yes	Dashboard color:	Black
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Seats electric F L	
GPS big screen color		Seats electric F R	
Windows electric F		Sun Roof electric	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Steering wheel leather		Headlights Xenon/LED/Laser	
Seats F heated		Front parking sensors	
Type of climate control	Autom climate control	Rear parking sensors	
		Roof bar black	
		Rear view camera	
		Seat cover lining	Lining Leather

Degree of wear


	255/40/20/101 Y			
Summer tyres:	Fr.L.	Michelin: 30%	Fr.R.	Michelin: 35%
	Re.L.	Continental: 45%	Re.R.	Continental: 50%
Tyre profile depth FL				6.1
Tyre profile depth FR				6.0
Tyre profile depth RL				5.3
Tyre profile depth RR				5.0
Tyre size FL				255/40 R 20 101 Y
Tyre size FR				255/40 R 20 101 Y
Tyre size RL				255/40 R 20 101 Y
Tyre size RR				255/40 R 20 101 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Interior, Dirty, Chemical cleaning



Glove compartment lid, Scratch(es), Replace




Dashboard, Scratch(es), Repair/replace (lump sum)



Door seal FL, Tear, Replace



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre RL, Tear, Replace



Tyre RR, Tear, Replace



Wing trim RL, Scratch(es), Acceptable



Wing RL, Bad repair, Paint



Side repeater L, Scratch(es), Replace



Outside rear-view mirror housing L, Bad repair, Paint



Wing FL, Bad repair, Paint



Bumper moulding FL, Broken, Replace



Wing trim FR, Scratch(es), Replace



Side repeater R, Crack, Replace



Wing trim FR, Scratch(es), Replace



Luggage cover cord, Missing, Replace



Luggage cover stopper, Missing, Replace




Rear bulkhead lining, Scratch(es), Replace



Boot lid covering R, Scratch(es), Replace



Internal boot lining L, Scratch(es), Replace



Luggage compartment cover, Tear, Repair/replace (lump sum)



Tailgate / Boot, Scratch(es), Acceptable



Rear light L tailgate, Crack, Replace

