



VOLKSWAGEN Golf V 2003 Diesel
golf 1.9 tdi Comfortline 5p 5m

VIN NO WVWZZZ1KZ8W028651
Registration Number DN397TW



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2023-09-27	-	-	195815 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2007-06-01	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251010115908
Inspection Date / Place	2025-10-10 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Black	Engine Size (cc)	1896
Engine Size	1.9	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	Yes
Manufacturer Warrenty			





Equipment

Central locking	Alloys wheels	Parcel Shef	Remote central locking
Stability control	Power assisted steering	Digital Radio	Remote adjusting wing mirrors
Trip Computer			


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Winter	
	GOODRIDE	205/55//R16 - 94V / 3 mm
	GOODRIDE	205/55//R16 - 94V / 3 mm
	GOODRIDE	205/55//R16 - 94V / 3 mm
	GOODRIDE	205/55//R16 - 94V / 3 mm

Cosmetic Damage

31 Danni



8 Danni




Component		Damage	Comments
1	Roof Upholstery	Interior / Broken	
2	Hood	Paint / Scratch / Line	
3	Panel Filling / Front Right	Interior / Broken	
4	Panel Filling / Front Left	Interior / Broken	
5	Seat / Front Left	Interior / Worn - out	
6	Windshield / Front	Glass Break	
7	Panel Filling / Back Left	Interior / Broken	
8	Panel Filling / Back Right	Interior / Broken	
9	Bumper / Back	Bodywork / Breakage	
10	Door / Front Right	Bodywork / Dent	
11	Fender / Front Left	Paint / Scratch / Line	
12	Steering Wheel / Front	Interior / Worn - out	

13	Fender / Back Right	Bodywork / Dent
14	Rocker Panel / Center Right	Bodywork / Dent
15	Mirror Shell / Front Right	Bodywork / Poor Previous Repair
16	Tailgate	Bodywork / Dent / Hail Area
17	Pillar / Front Right	Bodywork / Dent
18	Bumper / Front	Bodywork / Breakage
19	Roof	Bodywork / Dent
20	Mirror Shell / Front Left	Bodywork / Poor Previous Repair
21	Fender / Back Left	Bodywork / Dent
22	Door / Back Right	Bodywork / Dent
23	Fender / Front Right	Paint / Scratch / Line
24	Door / Back Left	Paint / Scratch / Line
25	Rim / Front Right	Out of Bodywork / Scratch
26	Rocker Panel / Center Left	Paint / Chipping
27	Aeration Grid / Front Center	Interior / Broken
28	Back Light / Left	Glass Break
29	Grille / Front	Bodywork / Breakage
30	Rim / Front Left	Out of Bodywork / Scratch
31	Rim / Back Right	Out of Bodywork / Scratch
32	Antenna Rod	Out of Bodywork / Breakage
33	Door / Front Left	Bodywork / Dent
34	Rim / Back Left	Out of Bodywork / Scratch
35	Fender / Front Right	Bodywork / Dent
36	Antenna Base	Bodywork / Breakage
37	Rim Brand Logo / Front Right	Missing Part
38	Rim Brand Logo / Back Right	Missing Part
39	Rim Brand Logo / Back Left	Missing Part



1. Roof Upholstery
Interior / Broken -



2. Hood
Paint / Scratch / Line -




3. Panel Filling / Front Right
Interior / Broken -



4. Panel Filling / Front Left
Interior / Broken -



5. Seat / Front Left
Interior / Worn - out -



6. Windshield / Front
Glass Break -



7. Panel Filling / Back Left
Interior / Broken -



8. Panel Filling / Back Right
Interior / Broken -



9. Bumper / Back
Bodywork / Breakage -



10. Door / Front Right
Bodywork / Dent -



11. Fender / Front Left
Paint / Scratch / Line -



12. Steering Wheel / Front
Interior / Worn - out -



13. Fender / Back Right
Bodywork / Dent -



14. Rocker Panel / Center Right
Bodywork / Dent -



15. Mirror Shell / Front Right
Bodywork / Poor Previous Repair -




16. Tailgate
Bodywork / Dent / Hail Area -



17. Pillar / Front Right
Bodywork / Dent -



18. Bumper / Front
Bodywork / Breakage -



19. Roof
Bodywork / Dent -



20. Mirror Shell / Front Left
Bodywork / Poor Previous Repair -



21. Fender / Back Left
Bodywork / Dent -



22. Door / Back Right
Bodywork / Dent -



23. Fender / Front Right
Paint / Scratch / Line -



24. Door / Back Left
Paint / Scratch / Line -



25. Rim / Front Right
Out of Bodywork / Scratch -



26. Rocker Panel / Center Left
Paint / Chipping -



27. Aeration Grid / Front Center
Interior / Broken -



28. Back Light / Left
Glass Break -




29. Grille / Front
Bodywork / Breakage -



30. Rim / Front Left
Out of Bodywork / Scratch -



31. Rim / Back Right
Out of Bodywork / Scratch -



32. Antenna Rod
Out of Bodywork / Breakage -




33. Door / Front Left
Bodywork / Dent -



34. Rim / Back Left
Out of Bodywork / Scratch -



35. Fender / Front Right
Bodywork / Dent -



36. Antenna Base
Bodywork / Breakage -



37. Rim Brand Logo / Front Right
Missing Part -



38. Rim Brand Logo / Back Right
Missing Part -



39. Rim Brand Logo / Back Left
Missing Part -

Mechanical Condition

Engine			
Engine Starts	✓	Vehicle Start - up	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	✓	AC / Heating System	!
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Other Checks			
Steering	✓	Brakes	✓
Suspension	!		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓	Test Drive Comment	A/C NON RAFFREDDA
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	!
Engine Noise	!		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			