



Hüsges Gruppe®
Die Gutachter

status report

customer: BCA Autoauktionen GmbH
contract number:
reference:

vehicle data

Volkswagen Golf V Lim. United

Vehicle identification number	VWVZZZ1KZ9W009150	mileage read:	146654 km
First Registration / construction year:	09.06.2008 / 2008	Visit Date / place of birth:	05.09.2025 Riedstadt-Goddelau
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	0603//AMK
Fuel / emission class:	gasoline / € 4	transmission type:	manual transmission
Displacement / power:	1390 ccm / 90 kW (122 PS)	Engine:	front-wheel drive
paint:	Reflexsilber Metallic	Number of previous owners:	3
Doors / seats:	3 / 5	number keys:	2
Next HU / AU:	06.2026 / 06.2026	cushion type:	substance
Service book available:	yes	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	124692 / 26.05.2020
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle	-	state outside:	3 - Average
documents:		condition inside:	3 - Average
visit condition:	-		
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	yes / -	124692 / 26.05.2020

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	steel
1st axis - Left / states .	Dunlop	205/55/R16/91H 5 mm
1st axis - right / states .	Dunlop	205/55/R16/91H 5 mm
2nd axis - Left / states .	Dunlop	205/55/R16/91H 6 mm
2nd axis - right / states .	Dunlop	205/55/R16/91H 6 mm
traffic Safety:	roadworthy	
spare wheel:	Tirefit	
state spare wheel:	Vollwertig	

standard equipment	
• 3-point rear center seat belt • Airbag Driver / passenger side • Drive Front Wheel Drive • Audio system RCD 210 with MP3 playback function (radio / CD player , 4 speakers) • Mirrors, aspheric, left • painted mirrors • Doppeltonhorn • Easy Entry Easy-Entry • Electric windows front • Textile floor mats • Cruise control system (cruise control) • Lockable glove compartment • Interior aluminum trim • Isofix admissions for child seat in back seat • Head airbag system (Side Guard) • Lumbar support front • Steering column (steering wheel) mechan. adjustable height / length adjustment • LM rims • Engine 1.4 ltr. - 90 kW 16V TSI • integrated fog lights • Non smoking package • Heated windshield washer nozzles • Protective moldings bumpers body color • Body color side moldings • Seat belts front with belt tensioner, height adjustable • Front right seat height adjustment • Heated front seats • Exterior door handles body color	• Airbag switched off • Anti- lock braking system (ABS) • Display for wash water level • Equipment package Light + Sight <i>Coming-Home-Paket, Automatische Fahrlichtschaltung (ALS), Scheibenwischer mit Regensensor, Fußraumbeleuchtung vorn, Innenspiegel mit Abblendautomatik</i> • Power side mirrors . adjustable and heated, both • brake Assist • Park Distance Control (rear) • Electron. Stability Program (ESP) • Control for central locking • Luggage compartment cover / shade • Transmission 6-speed • rear window wiper • Dust and pollen filter • Body 2-door • Rear headrests (3- fold) • Steering wheel (leather) with multifunction <i>Schalt-/Wählhebelgriff Leder</i> • Front reading lights • Armrest for driver's seat • Multifunctional Display Plus • Rear fog light • Split rear seat back • Headlight cleaning system (SRA) • Front Side Airbags • Controlled electronic power steering (Servotronic) • Front left seat height adjustment • Seat cover / upholstery fabric • Body color bumpers

• Glazing tinted green / black • Central	• Door speaker front • Immobiliser (electronic)
---	---

special Features	
• Anti-theft device for wheels (rim locks) • Metallic paint	• Climate Control <i>Handschuhfach mit Kühlfunktion</i>

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed.
Mileage plausible:	not testable not testable Wartung fällig
reference:	
Note Road Safe:	Rost am Diversen Bauteilen

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			in order		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			examined limited	exhaust System:	
			examined limited		
engine running:			Out of order	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine had to acoustic or visual defects for visiting time . **Engine warning light.
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1. Sitz Vorne Links	Wear and tear	acceptable
2. steering wheel	Damaged	Smart repair
3. headlining	Damaged	Replace
4. maintenance	Due	Replace
5. Motorkontrollleuchte	Error message	Carry out a fault diagnosis
6. spoiler	Scrape	Replace
7. hood	Scratch(es)	Paint
8. Front fender - left	Deformed	Refurbish and paint
9. Front door - left	Deformed	Refurbish and paint
10. side skirt - left	Rust	Replace
11. Sidewall - Rear - Left	Rust	Replace
12. tailgate	Deformed	Refurbish and paint
13. Rear bumper	Scratch(es)	Paint
14. tailgate trim	Breakage	Replace
15. Sidewall - Rear - right	Rust	Replace
16. side skirt - right	Rust	Replace
17.	Scratch(es)	Paint
18. Front fender - right	Rust	Refurbish and paint
19. Front door - right	Deformed	Refurbish and paint
20.	Damaged	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted , and for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment




service book



Others



1. Sitz Vorne Links



1. Sitz Vorne Links



2. steering wheel



3. headlining




5. Motorkontrollleuchte



6. spoiler



7. hood



7. hood



8. Front fender - left



9. Front door - left



10. side skirt - left



10. side skirt - left



10. side skirt - left



11. Sidewall - Rear - Left



11. Sidewall - Rear - Left



11. Sidewall - Rear - Left



11. Sidewall - Rear - Left



11. Sidewall - Rear - Left



11. Sidewall - Rear - Left



12. tailgate



12. tailgate



13. Rear bumper



13. Rear bumper



14. tailgate trim



14. tailgate trim



15. Sidewall - Rear - right



15. Sidewall - Rear - right



16. side skirt - right



16. side skirt - right



17.



18. Front fender - right



18. Front fender - right



19. Front door - right



19. Front door - right



20.