



VOLKSWAGEN Golf VI

Golf Variant 2.0 TDI DPF

VIN NO WVWZZZ1KZDM665939
Registration Number KZDM665939



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	2	2	325283 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2024-04-06	289707	2013-03-21	-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250919085101
Inspection Date / Place	2025-09-19 / Extern	Cosmetic Grade	3


Vehicle Summary




Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Blue	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth/Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	128
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Anti-lock braking	Bluetooth telephone interface	Diesel particulate filter
Heated wing mirrors	Remote central locking	Satellite navigation	CD Player
Radio	Alloys wheels	Bi Xenon Headlamps	Cruise control
Front parking sensors	Remote adjusting wing mirrors	Roof rails	Stability control
Leather steering wheel	Rear parking sensors		

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	16
Seat Heating	Front		

Wheels & Tyres

Right Front Tyre Depth	3	Left Front Tyre Depth	3
Right Rear Tyre Depth	3	Left Rear Tyre Depth	3

Cosmetic Damage


7 Schäden



0 Schäden




Component		Damage	Comments
1	Roof	Bodywork / Dent / Dent	
2	Door / Front Left	Paint / Scratch / Scuff	
3	Door / Back Left	Bodywork / Dent / Dent	
4	Fender / Back Left	Paint / Scratch / Scuff	
5	Bumper / Back	Paint / Scratch / Scuff	
6	Fender / Back Right	Paint / Scratch / Scuff	
7	Door / Front Right	Paint / Scratch / Scuff	



1. Roof
Bodywork / Dent / Dent -



2. Door / Front Left
Paint / Scratch / Scuff -



3. Door / Back Left
Bodywork / Dent / Dent -



4. Fender / Back Left
Paint / Scratch / Scuff -



5. Bumper / Back
Paint / Scratch / Scuff -



6. Fender / Back Right
Paint / Scratch / Scuff -



7. Door / Front Right
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Service Light	⚠
Tire Pressure Monitoring System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Main & Spare Keys Functioning	✓	Navigation System	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Levels

Brakes Fluid	NA	Coolant Fluid	NA
--------------	----	---------------	----

Test Drive Inspection

Engine			
Fume Quantity	✓	Engine Noise	✓
The Gears Scratch / Skip / Abnormal Operation	✓	Power Loss	✓
Brake			
Brake System Anomaly	✓		
Steering Wheel			
Steering Noise / Anomaly	✓		
General			
Test Driven Status	Not Performed		
✓	No troubles detected, good condition or correct tests, according to vehicle age and mileage		
!	Damages or malfunction detected that requires repairs by the buyer		
NA	Not applicable		
☐	Not tested		

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)