

## VOLKSWAGEN Golf VI Golf 1.2 TSI

VIN NO WVWZZZ1KZDW007769 Registration Number KZDW007769



**MOT Date** 

Number of Owners

•

**Odometer Reading** 

☆-

**2:** 1

**P**2

212548 km

Last Service

Last Service Mileage

187128

First Registration Date

Country First Registered

**2**023-09-06

2012-06-22

Number of Keys

**e** 

#### **Inspection Report Summary**

Customer	BCA Online	Report Number	P20250918141458
Inspection Date / Place	2025-09-19 / Extern	Cosmetic Grade	1

#### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Red	Engine Size (cc)	1197
Engine Size	1.2	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	129
Gearbox Type	Manual		

#### Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			





























## Equipment

Tinted Glass	Anti-lock braking	Heated wing mirrors	Remote central locking
CD Player	Radio	Airbag Status	Front parking sensors
Remote adjusting wing mirrors	Stability control	Leather steering wheel	Rear parking sensors


## **Equipment Details**

Air Conditioning	Dual Zone Climate Control	Extra Wheel / Tyre Set	Summer Tyres - Alloy
Seat Heating	Front		

### Wheels & Tyres

Extra Wheel - 1 Tyre Depth	3	Extra Wheel - 2 Tyre Depth	3
Extra Wheel - 3 Tyre Depth	3	Extra Wheel - 4 Tyre Depth	3
Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

### Cosmetic Damage



	Component	Damage	Comments
1	Panel Filling / Back Left	Interior / Scratched	
2	Bumper / Back	Paint / Scratch / Scuff	
3	Panel Filling / Back Right	Interior / Scratched	
4	Hood	Paint / Stone Chip	
5	Seat / Front Left	Interior / Holed	




1. Panel Filling / Back Left Interior / Scratched -

2. Bumper / Back Paint / Scratch / Scuff -



3. Panel Filling / Back Right Interior / Scratched -

4. Hood Paint / Stone Chip -



5. Seat / Front Left Interior / Holed -

#### **Mechanical Condition**

Control Lights			
ABS Warning Light	•	ESP Fault/Traction Control Malfunction Light	<b>②</b>
Airbag Warning Light	•	Oil Pressure Warning Light	•
Brake Warning Light	<b>⊘</b>	Power Steering Warning Light	<b>⊘</b>
Alternator / Battery	•	No Dashboard Lights	<b>⊘</b>
Service Light	(1)	Tire Pressure Monitoring System	•
Engine			
Engine Status / EML	<b>⊘</b>	Engine Starts	<b>⊘</b>
Engine Leak Visible	•		
Gearbox			
Gear Box	<b>⊘</b>		
Equipments Test			
Main & Spare Keys Functioning	<b>⊘</b>	Electric Windows	<b>⊘</b>
Parking Sensors / Cameras Functioning	<b>⊘</b>	AC / Heating System	•
Levels			
Brakes Fluid	<b>⊘</b>	Coolant Fluid	

# Test Drive Inspection

Brake				
Brake System Anomaly	•			
Steering Wheel				
Steering   Noise / Anomaly	<b>⊘</b>			
Engine				
Engine Noise	•	The Gears Scratch / Skip / Abnormal Operation	•	
Fume Quantity	•	Power Loss	•	
Clutch				
Clutch Functioning	•			
General				
Test Driven Status	•			
<ul> <li>No troubles detected, good</li> <li>Damages or malfunction de</li> <li>Not applicable</li> <li>Not tested</li> </ul>		according to vehicle age and mileage rs by the buyer		
Disclaimer				
Please also note the "UserGu	uide condition report", wl	hich shows the scope of the vehicle		Hoor Cuido

<u>User Guide</u>

description.