

## VOLKSWAGEN Passat Passat Variant 1.6

**BCA** 

VIN NO WVWZZZ3BZ3E464067 Registration Number BZ3E464067

MOT Date

**Last Service** 

**☆**-

:2

Last Service Mileage

Number of Owners

Number of Keys

**P**2

First Registration Date

2003-06-26

**Odometer Reading** 

**2** 305827 km

Country First Registered

**=**-

### **Inspection Report Summary**

Customer	BCA Online	Report Number	P20250919121452
Inspection Date / Place	2025-09-19 / Extern	Cosmetic Grade	5

### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	No
Colour	Blue	Engine Size (cc)	1595
Engine Size	1.6	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	192
Gearbox Type	Manual		

### Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			






















# Equipment

Trip Computer	Anti-lock braking	Heated wing mirrors	Remote central locking
Stability control	Radio	Airbag Status	Cruise control
Remote adjusting wing mirrors	Roof rails	CD Player	


## **Equipment Details**

Air Conditioning	Climate Control	Extra Wheel / Tyre Set	Winter Tyres - Steel
Seat Heating	Front		


## Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4
Extra Wheel - 1 Tyre Depth	4	Extra Wheel - 2 Tyre Depth	4
Extra Wheel - 3 Tyre Depth	5	Extra Wheel - 4 Tyre Depth	5

## Cosmetic Damage




	Component	Damage	Comments
1	Bumper / Front	Bodywork / Dent / Dent	
2	Fender / Front Right	Paint / Corrosion	
3	Door / Front Left	Bodywork / Dent / Dent	
4	Door / Back Left	Bodywork / Dent / Dent	
5	Back Light / Left	Glass Break	
6	Fender / Back Right	Bodywork / Dent / Dent	
7	Door / Back Right	Bodywork / Breakage	
8	Door / Front Right	Paint / Scratch / Scuff	
9	Roof Upholstery	Interior / Holed	
10	Roof Upholstery	Interior / Holed	
11	Glovebox	Interior / Broken	




1. Bumper / Front Bodywork / Dent / Dent -

2. Fender / Front Right Paint / Corrosion -



3. Door / Front Left Bodywork / Dent / Dent -

4. Door / Back Left Bodywork / Dent / Dent -



5. Back Light / Left Glass Break -

6. Fender / Back Right Bodywork / Dent / Dent -




7. Door / Back Right Bodywork / Breakage -

8. Door / Front Right Paint / Scratch / Scuff -



9. Roof Upholstery Interior / Holed -

10. Roof Upholstery Interior / Holed -



11. Glovebox Interior / Broken -

### **Mechanical Condition**

Control Lights			
Display Defect	<b>Ø</b>	Service Light	•
ABS Warning Light	•	ESP Fault/Traction Control Malfunction Light	<b>②</b>
Airbag Warning Light	<b>⊘</b>	Oil Pressure Warning Light	<b>Ø</b>
Brake Warning Light	•	Power Steering Warning Light	<b>②</b>
Alternator / Battery	<b>⊘</b>	No Dashboard Lights	<b>Ø</b>
Equipments Test			
Central Locking	•	Main & Spare Keys Functioning	<b>⊘</b>
Electric Windows	<b>⊘</b>	Audio Equipment	<b>⊘</b>
AC / Heating System	•	Other Equipments	•
Engine			
Engine Status / EML		Engine Leak Visible	<b>(1)</b>
Engine Starts	•		
Gearbox			
Gear Box	<b>⊘</b>		
Levels			
Brakes Fluid	•	Coolant Fluid	•

#### **Test Drive Inspection**

# Steering Wheel Steering | Noise / Anomaly Clutch **Clutch Functioning Engine** The Gears Scratch / Skip / **Fume Quantity Abnormal Operation** Power Loss **Engine Noise Brake Brake System Anomaly** General **Test Driven Status** NA No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

<u>User Guide</u>