

VOLKSWAGEN Passat Passat Variant 2.0 TDI DPF

BCA

VIN NO WVWZZZ3CZ9E030284 Registration Number CZ9E030284

Number of Owners

MOT Date

★ 2026-10-01

Last Service Last Service Mileage

2024-10-02 277691

Number of Keys

P2

First Registration Date

2008-10-06

Odometer Reading

288294 km

Country First Registered

Germany

Inspection Report Summary

| Customer | BCA Online | Report Number | P20250523093014 |
|-------------------------|--------------------------------|----------------|-----------------|
| Inspection Date / Place | 2025-05-23 / BCA Heidenheim | Cosmetic Grade | 4 |

Vehicle Summary

| Vehicle Condition | Dunnar | V/AT Type | Morgin |
|--------------------|-----------------------|------------------------|--------|
| venicle Condition | Runner | VAT Type | Margin |
| Fuel Type | Diesel | Road Worthy | Yes |
| Colour | Black | Engine Size (cc) | 1968 |
| Engine Size | 2.0 | No of Doors | 5 |
| Body Type | Stationwagon / Estate | Drive Train | Front |
| Seat Colour | | No of Seats | 5 |
| Seat Covering Name | Schwarz | Seat Covering | Cloth |
| Charging Cables | | NEDC CO2 Rating (q/km) | 148 |
| Gearbox Type | Manual | | |

Vehicle History & Documents

| Service Book Available | Present | Next Service Mileage | km |
|------------------------|---------|----------------------|----|
| Previous Usage | | Imported | No |
| Manufacturer Warrenty | | | |




























Equipment

| Tow ball | Alloys wheels | Cruise control | Front fog lamps |
|---------------------------|-------------------------------|---------------------|------------------------|
| Headlamp wash/wipe | Remote adjusting wing mirrors | Roof rails | Xenon headlamps |
| Leather steering wheel | Radio | Airbag Status | Anti-lock braking |
| Diesel particulate filter | Front parking sensors | Heated wing mirrors | Remote central locking |
| Stability control | CD Player | Privacy glass | Rear parking sensors |
| E. t D. I I. | | | |


Equipment Details

| Tow Ball Type | Static | Air Conditioning | Dual Zone Climate Control |
|------------------|--------|------------------|---------------------------|
| Alloy Wheel Size | 17 | Seat Heating | Front |

Wheels & Tyres

| Right Front Tyre Depth | 4 | Left Front Tyre Depth | 4 |
|------------------------|---|-----------------------|---|
| Right Rear Tyre Depth | 3 | Left Rear Tyre Depth | 3 |

Cosmetic Damage



| 14 | Side Panel / Back Left | Paint / Corrosion |
|----|--------------------------------|---------------------------------|
| 15 | Rim / Back Left | Out of Bodywork / Scratch |
| 16 | Door / Front Left | Paint / Scratch / Scuff |
| 17 | Door Side Molding / Front Left | Bodywork / Poor Previous Repair |
| 18 | Seat / Front Left | Interior / Holed |
| 19 | Gear Knob | Interior / Scratched |
| 20 | Roof Upholstery | Interior / Distorted |
| 21 | Luggage Space Cover / Back | Interior / Missing |
| 22 | Rocker Panel / Center Right | Paint / Corrosion |



1. Fender / Front Left Paint / Poor Previous Repair -



2. Hood Paint / Poor Previous Repair -



3. Hood Paint / Poor Previous Repair -



4. Door / Front Right
Paint / Poor Previous Repair -



5. Tailgate Paint / Poor Previous Repair -



6. Side Panel / Back Left Paint / Poor Previous Repair -



7. Door / Back Left Paint / Poor Previous Repair -

8. Door / Front Left Paint / Poor Previous Repair -



9. Rim / Back Right Out of Bodywork / Scratch -

10. Door / Back Right Paint / Corrosion -



11. Side Panel / Back Right Bodywork / Dent / Dent -

12. Door / Front Right Bodywork / Dent / Dent -




13. Bumper / Back Paint / Scratch / Scuff -

14. Side Panel / Back Left Paint / Corrosion -



15. Rim / Back Left Out of Bodywork / Scratch -

16. Door / Front Left Paint / Scratch / Scuff -



17. Door Side Molding / Front Left Bodywork / Poor Previous Repair -

18. Seat / Front Left Interior / Holed -



19. Gear Knob Interior / Scratched -

20. Roof Upholstery Interior / Distorted -



21. Luggage Space Cover / Back Interior / Missing -

22. Rocker Panel / Center Right Paint / Corrosion -

Mechanical Condition

| Control Lights | | | |
|---|----------|----------------------------------|----------|
| Display Defect | • | ABS Warning Light | ② |
| ESP Fault/Traction Control Malfunction Light | • | Diesel Particulate Filter Light | • |
| Airbag Warning Light | ⊘ | Oil Pressure Warning Light | • |
| Brake Warning Light | • | Power Steering Warning Light | • |
| Alternator / Battery | ⊘ | No Dashboard Lights | • |
| Equipments Test | | | |
| Central Locking | ⊘ | Main & Spare Keys Functioning | • |
| Electric Windows | ⊘ | Audio Equipment | • |
| AC / Heating System | • | Other Equipments | Ø |
| Engine | | | |
| Engine Status / EML | • | Engine Leak Visible | |
| Engine Starts | • | | |
| Levels | | | |
| Brakes Fluid | • | Coolant Fluid | ⊘ |

Test Drive Inspection

description.

| Engine | | | | |
|---|--|--|----------|--|
| Engine Noise | ⊘ | The Gears Scratch / Skip / Abnormal Operation | ⊘ | |
| Fume Quantity | • | Power Loss | • | |
| Clutch | | | | |
| Clutch Functioning | ⊘ | | | |
| Steering Wheel | | | | |
| Steering Noise / Anomaly | • | | | |
| Brake | | | | |
| Brake System Anomaly | • | | | |
| General | | | | |
| Test Driven Status | • | | | |
| No troubles detected, good condition or correct tests, according to vehicle age and mileage □ Damages or malfunction detected that requires repairs by the buyer □ Not applicable □ Not tested | | | | |
| Disclaimer | | | | |
| Please also note the "UserGu | lease also note the "UserGuide condition report", which shows the scope of the vehicle | | | |

User Guide