

Vehicle details

VIN	WVWZZZ3HZ JE504073	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	SN-73-0H	Model	Arteon 2.0 TDI 110kW 7-DSG Elegance Business 5d	Maintenance mileage	-
Registration date	08/05/2018	Year	2018	Exterior Color	Grey Metallic
Odometer	291 300 km	Engine size	1968	interior Color	Black
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	13/08/2025	Inspection loc.	Dekra Ayvens		
					
					
					

Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Sliding roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document

Spare key	✓
Remote key	✓

Tyres

Hankook 245/40/19 Summer 7.0 mm		Pirelli 245/40/19 Summer 4.5 mm	
Pirelli 245/40/19 Summer 4.0 mm		Pirelli 245/40/19 Summer 6.0 mm	

Exterior

2



●●

Part	Door entry seal
Position	Front left
Damages	Worn out
Severity	-
Repair mode	Replace

3



●●

Part	Bumper moulding
Position	Back right
Damages	Broken
Severity	-
Repair mode	Replace

4



●●

Part	Alloy wheel 19"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

5



●●

Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

6



●●●

Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair


7



●●

Part	Alloy wheel 19"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair


8



●●●●●

Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

9



●●

Part	Bumper moulding
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Replace


10



●●●●●●●

Part	Bonnet
Position	-
Damages	Hail damaged
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

11



●●

Part	Alloy wheel 19"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

Interior damage

1



Part	Interior tailgate lining
Position	Down
Damages	Scratched
Severity	-
Repair mode	Replace