



VOLKSWAGEN Polo 2009 Diesel

polo 1.2 tdi Trendline 5p

VIN NO WVWZZZ6RZEY038741

Registration Number ES400LN



MOT Date

2023-09-19

Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date

2013-09-11

Odometer Reading

243990 km

Country First Registered

Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251002142153
Inspection Date / Place	2025-10-02 / BCA Lodi	Cosmetic Grade	5



Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	White	Engine Size (cc)	1198
Engine Size	1.2	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	99

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment

Central locking	Digital Radio	Remote adjusting wing mirrors	Trip Computer
Stability control	Power assisted steering	Parcel Shef	Remote central locking
Tyre Mobility Kit			


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Summer	
	FULDA	185/60//R15 - 88H / 1 mm
	FULDA	185/60//R15 - 88H / 1 mm
	FULDA	185/60//R15 - 88H / 2 mm
	FULDA	185/60//R15 - 88H / 2 mm

Cosmetic Damage

22 Danni



13 Danni



1

Component		Damage	Comments
1	Panel Filling / Front Left	Interior / Broken	
2	Floor Carpet	Interior / Broken	
3	Seat / Front Left	Interior / Broken	
4	Steering Wheel / Front	Interior / Worn - out	
5	Dashboard / Front	Interior / Warning Light ON	
6	Dashboard / Front	Interior / Warning Light ON	
7	Center Console	Interior / Worn - out	
8	Panel Filling / Front Right	Interior / Broken	
9	Ignition Key	Interior / Broken	
10	Window Switch / Front Left	Interior / Broken	
11	Window Switch / Front Left	Interior / Broken	
12	Roof Upholstery	Interior / Broken	


13	Panel Filling / Back Right	Interior / Broken
14	Fender / Front Right	Bodywork / Dent
15	Hubcap / Front Right	Out of Bodywork / Scratch
16	Mirror Shell / Front Right	Bodywork / Breakage
17	Door / Front Right	Bodywork / Dent
18	Door / Back Right	Bodywork / Dent
19	Hubcap / Back Right	Out of Bodywork / Scratch
20	Fender / Back Right	Bodywork / Dent
21	Mirror Shell / Front Right	Bodywork / Breakage
22	Bumper / Front	Bodywork / Breakage
23	Hood	Paint / Chipping
24	Windshield / Front	Glass Break / Impact
25	Hubcap / Front Left	Out of Bodywork / Deformation
26	Fender / Front Left	Bodywork / Dent
27	Mirror Shell / Front Left	Paint / Scratch / Line
28	Mirror Shell / Front Left	Bodywork / Breakage
29	Door / Front Left	Paint / Scratch / Line
30	Door / Back Left	Bodywork / Dent
31	Hubcap / Back Left	Out of Bodywork / Scratch
32	Bumper / Back	Bodywork / Breakage
33	Tailgate	Bodywork / Dent
34	Roof	Bodywork / Dent / Hail Area
35	Back Light / Left	Glass Break / Scratch




1. Panel Filling / Front Left
Interior / Broken -



2. Floor Carpet
Interior / Broken -



3. Seat / Front Left
Interior / Broken -



4. Steering Wheel / Front
Interior / Worn - out -



5. Dashboard / Front
Interior / Warning Light ON -




6. Dashboard / Front
Interior / Warning Light ON -



7. Center Console
Interior / Worn - out -



8. Panel Filling / Front Right
Interior / Broken -



9. Ignition Key
Interior / Broken -



10. Window Switch / Front Left
Interior / Broken -



11. Window Switch / Front Left
Interior / Broken -



12. Roof Upholstery
Interior / Broken -



13. Panel Filling / Back Right
Interior / Broken -



14. Fender / Front Right
Bodywork / Dent -



15. Hubcap / Front Right
Out of Bodywork / Scratch -



16. Mirror Shell / Front Right
Bodywork / Breakage -




17. Door / Front Right
Bodywork / Dent -



18. Door / Back Right
Bodywork / Dent -



19. Hubcap / Back Right
Out of Bodywork / Scratch -



20. Fender / Back Right
Bodywork / Dent -



21. Mirror Shell / Front Right
Bodywork / Breakage -



22. Bumper / Front
Bodywork / Breakage -



23. Hood
Paint / Chipping -



24. Windshield / Front
Glass Break / Impact -



25. Hubcap / Front Left
Out of Bodywork / Deformation -



26. Fender / Front Left
Bodywork / Dent -



27. Mirror Shell / Front Left
Paint / Scratch / Line -



28. Mirror Shell / Front Left
Bodywork / Breakage -



29. Door / Front Left
Paint / Scratch / Line -



30. Door / Back Left
Bodywork / Dent -



31. Hubcap / Back Left
Out of Bodywork / Scratch -



32. Bumper / Back
Bodywork / Breakage -



33. Tailgate
Bodywork / Dent -



34. Roof
Bodywork / Dent / Hail Area -



35. Back Light / Left
Glass Break / Scratch -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	!		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Other Checks			
Brakes	✓	Steering	✓
Suspension	!		
General			
Test Driven Status	✓	Test Drive Comment	SPIA AIRBAG ACCESA
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	!
Engine Noise	!		
Gearbox			
Manual Gearbox	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested