



VOLKSWAGEN POLO

Polo TDI 75

VIN NO WVWZZZ9NZ3D030446
Registration Number 6909XZ30



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCA Auto Encheres	Report Number	P20251002133603
Inspection Date / Place	2025-10-02 / BCA GARONS	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Blue	Engine Size (cc)	1422
Engine Size	1.4	No of Doors	5
Body Type	Hatchback	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	119

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warranty			







Equipment


Central locking	Power assisted steering	Radio
-----------------	-------------------------	-------

Equipment Details


Seat Heating	No	Air Conditioning	Yes
--------------	----	------------------	-----

Cosmetic Damage

38 Dommages



12 Dommages



Component		Damage	Comments
1	Bumper / Back	Paint / Scratch / Line	
2	Bumper / Back	Paint / Scratch / Line	
3	Back Light / Right	Glass Break	
4	Tailgate	Paint / Scratch / Line	
5	Tailgate	Paint / Scratch / Line	
6	Cant Rail / Right	Paint / Scratch / Line	
7	Antenna Rod	Out of Bodywork / Breakage	
8	Tailgate Upholstery / Back	Interior / Scraped	
9	Luggage Space Cover / Back	Interior / Broken	
10	Hubcap / Back Left	Missing element hubcap	
11	Tire / Back Left	Tire	
12	Fender / Back Left	Bodywork / Dent / Dent	

13	Fender / Back Left	Bodywork / Dent / Deformation
14	Door / Back Left	Paint / Scratch / Line
15	Door / Back Left	Paint / Scratch / Line
16	Door / Back Left	Paint / Chipping
17	Rocker Panel / Center Left	Bodywork / Dent / Deformation
18	Door / Front Left	Bodywork / Dent / Dent
19	Door / Front Left	Paint / Scratch / Line
20	Cant Rail / Left	Paint / Scratch / Line
21	Panel Filling / Back Left	Interior / Broken
22	Backrest Cover / Front Left	Interior / Ripped
23	Gear Knob	Interior / Scraped
24	Digital Combined Instrument Panel	Interior / Scraped
25	Rearview Mirror / Front Center	Interior / Worn - out
26	Roof Upholstery	Interior / Loose
27	Panel Filling / Front Left	Interior / Loose
28	Hubcap / Front Left	Missing element hubcap
29	Fender / Front Left	Bodywork / Dent / Dent
30	Hood	Paint / Scratch / Line
31	Bumper / Front	Paint / Scratch / Line
32	Front Light / Front Left	Glass Break
33	Front Light / Front Right	Glass Break
34	Bumper / Front	Paint / Scratch / Line
35	Hubcap / Front Right	Out of Bodywork / Scratch
36	Mirror / Front Right	Bodywork / Breakage
37	Door / Front Right	Bodywork / Dent / Dent
38	Panel Filling / Front Right	Interior / Broken
39	Glovebox	Interior / Scraped
40	Door / Back Right	Bodywork / Dent / Deformation
41	Fender / Back Right	Bodywork / Dent / Dent

42	Panel Filling / Back Right	Interior / Loose
43	Hubcap / Back Right	Out of Bodywork / Scratch
44	Rocker Panel / Center Right	Bodywork / Dent / Deformation
45	Door / Front Right	Bodywork / Dent / Deformation
46	Door / Front Right	Bodywork / Dent / Dent
47	Roof	Paint / Poor Previous Repair
48	Door / Back Left	Bodywork / Dent / Dent



1. Bumper / Back
Paint / Scratch / Line -



3. Back Light / Right
Glass Break -




4. Tailgate
Paint / Scratch / Line -



5. Tailgate
Paint / Scratch / Line -



6. Cant Rail / Right
Paint / Scratch / Line -



7. Antenna Rod
Out of Bodywork / Breakage -



8. Tailgate Upholstery / Back Interior / Scraped -



9. Luggage Space Cover / Back Interior / Broken -



10. Hubcap / Back Left
Missing element hubcap -



11. Tire / Back Left
Tire -



12. Fender / Back Left
Bodywork / Dent / Dent -



13. Fender / Back Left
Bodywork / Dent / Deformation -




14. Door / Back Left
Paint / Scratch / Line -



15. Door / Back Left
Paint / Scratch / Line -




16. Door / Back Left
Paint / Chipping -



17. Rocker Panel / Center Left
Bodywork / Dent / Deformation -




18. Door / Front Left
Bodywork / Dent / Dent -



19. Door / Front Left
Paint / Scratch / Line -



20. Cant Rail / Left
Paint / Scratch / Line -



21. Panel Filling / Back Left
Interior / Broken -



22. Backrest Cover / Front Left
Interior / Ripped -



23. Gear Knob
Interior / Scraped -



24. Digital Combined Instrument Panel
Interior / Scraped -



25. Rearview Mirror / Front Center
Interior / Worn - out -



26. Roof Upholstery
Interior / Loose -




27. Panel Filling / Front Left
Interior / Loose -




28. Hubcap / Front Left
Missing element hubcap -




29. Fender / Front Left
Bodywork / Dent / Dent -



30. Hood
Paint / Scratch / Line -




31. Bumper / Front
Paint / Scratch / Line -



32. Front Light / Front Left
Glass Break -



33. Front Light / Front Right
Glass Break -




34. Bumper / Front
Paint / Scratch / Line -



35. Hubcap / Front Right
Out of Bodywork / Scratch -



36. Mirror / Front Right
Bodywork / Breakage -



37. Door / Front Right
Bodywork / Dent / Dent -




38. Panel Filling / Front Right
Interior / Broken -



39. Glovebox
Interior / Scraped -




40. Door / Back Right
Bodywork / Dent / Deformation -



41. Fender / Back Right
Bodywork / Dent / Dent -




42. Panel Filling / Back Right
Interior / Loose -



43. Hubcap / Back Right
Out of Bodywork / Scratch -



44. Rocker Panel / Center Right
Bodywork / Dent / Deformation -



45. Door / Front Right
Bodywork / Dent / Deformation -



46. Door / Front Right
Bodywork / Dent / Dent -



47. Roof
Paint / Poor Previous Repair -



48. Door / Back Left
Bodywork / Dent / Dent -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.