



VOLKSWAGEN Polo IV

Polo 1.2

VIN NO WVVZZZ9NZ6D054004

Registration Number NZ6D054004



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



174499 km

Country First Registered



Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250825134632
Inspection Date / Place	2025-08-25 / ARS Altmann AG Riedstadt	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	No
Colour	Blue	Engine Size (cc)	1198
Engine Size	1.2	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Grau	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	142
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warranty			







Equipment

Airbag Status	Anti-lock braking	Remote adjusting wing mirrors	Stability control
Alloys wheels	Heated wing mirrors	Remote central locking	Radio

Equipment Details

Air Conditioning	Yes	Alloy Wheel Size	14
Extra Wheel / Tyre Set	Winter Tyres - Steel	Seat Heating	Front

Wheels & Tyres

Right Front Tyre Depth	3	Left Front Tyre Depth	3
Right Rear Tyre Depth	2	Left Rear Tyre Depth	2
Extra Wheel - 1 Tyre Depth	3	Extra Wheel - 2 Tyre Depth	3
Extra Wheel - 3 Tyre Depth	5	Extra Wheel - 4 Tyre Depth	5

Cosmetic Damage


	Component	Damage	Comments
1	Bumper / Front	Missing Part	
2	Hood	Bodywork / Dent / Dent	
3	Bumper / Front	Paint / Scratch / Scuff	
4	Fender / Front Left	Bodywork / Dent / Dent	
5	Rocker Panel / Center Left	Paint / Corrosion	
6	Side Panel / Back Left	Bodywork / Dent / Dent	
7	Bumper / Back	Paint / Scratch / Scuff	
8	Side Panel / Back Right	Bodywork / Dent / Dent	
9	Rocker Panel / Center Right	Paint / Corrosion	
10	Fender / Front Right	Paint / Scratch / Scuff	
11	Fender / Front Right	Paint / Corrosion	



1. Bumper / Front
Missing Part -



2. Hood
Bodywork / Dent / Dent -



3. Bumper / Front
Paint / Scratch / Scuff -



4. Fender / Front Left
Bodywork / Dent / Dent -




5. Rocker Panel / Center Left
Paint / Corrosion -



6. Side Panel / Back Left
Bodywork / Dent / Dent -



7. Bumper / Back
Paint / Scratch / Scuff -



8. Side Panel / Back Right
Bodywork / Dent / Dent -



9. Rocker Panel / Center Right
Paint / Corrosion -




10. Fender / Front Right
Paint / Scratch / Scuff -




11. Fender / Front Right
Paint / Corrosion -

Mechanical Condition

Engine

Engine Leak Visible		Engine Starts	
---------------------	---	---------------	---

Levels


Coolant Fluid	
---------------	---

Control Lights

Display Defect		Alternator / Battery	
----------------	---	----------------------	---

Equipments Test


Electric Windows		Central Locking	
------------------	---	-----------------	---

Audio Equipment	
-----------------	---

 **No troubles detected, good condition or correct tests, according to vehicle age and mileage**

 **Damages or malfunction detected that requires repairs by the buyer**

 **Not applicable**

 **Not tested**

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)