

VOLKSWAGEN Up

up!

VIN NO WVWZZZAAZFD046338 Registration Number AZFD046338



MOT Date

2027-07-01

Last Service

2023-07-17

Number of Owners

2

Last Service Mileage

87119

Number of Keys

P2

First Registration Date

2014-12-22

Odometer Reading

106550 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250924082112
Inspection Date / Place	2025-09-24 / ARS Altmann AG Wolnzach	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Petrol	Road Worthy	Yes
Colour	White	Engine Size (cc)	999
Engine Size	1.0	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	4
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	105
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			










































Equipment

Right Rear Tyre Depth


5

Airbag Status	Remote central locking	Central locking	Radio
Anti-lock braking	CD Player	Leather steering wheel	
Equipment Details			
Air Conditioning	Yes	Extra Wheel / Tyre Set	Summer Tyres - Steel
Seat Heating	Front		
Wheels & Tyres			
Extra Wheel - 1 Tyre Depth	3	Extra Wheel - 2 Tyre Depth	3
Extra Wheel - 3 Tyre Depth	3	Extra Wheel - 4 Tyre Depth	3
Right Front Tyre Depth	5	Left Front Tyre Depth	5


Left Rear Tyre Depth

5

Cosmetic Damage



	Component	Damage	Comments
1	Hood	Bodywork / Dent / Dent	
2	Side Panel / Back Left	Bodywork / Dent / Dent	
3	Side Panel / Back Right	Bodywork / Dent / Dent	
4	Bumper / Front	Paint / Scratch / Scuff	
5	Door / Front Left	Paint / Scratch / Scuff	
6	Pillar / Back Left	Bodywork / Dent / Dent	
7	Pillar / Back Left	Paint / Scratch / Scuff	
8	Side Panel / Back Left	Paint / Scratch / Scuff	
9	Bumper / Back	Paint / Scratch / Scuff	
10	Side Panel / Back Right	Paint / Corrosion	
11	Side Panel / Back Right	Bodywork / Dent / Dent	
12	Antenna Rod	Out of Bodywork / Breakage	



1. Hood Bodywork / Dent / Dent -

2. Side Panel / Back Left Bodywork / Dent / Dent -



3. Side Panel / Back Right Bodywork / Dent / Dent -

4. Bumper / Front Paint / Scratch / Scuff -



5. Door / Front Left Paint / Scratch / Scuff -

6. Pillar / Back Left Bodywork / Dent / Dent -



7. Pillar / Back Left Paint / Scratch / Scuff -

8. Side Panel / Back Left Paint / Scratch / Scuff -



9. Bumper / Back Paint / Scratch / Scuff -

10. Side Panel / Back Right Paint / Corrosion -



11. Side Panel / Back Right Bodywork / Dent / Dent -

12. Antenna Rod Out of Bodywork / Breakage -



13. Bumper / Front Paint / Scratch / Scuff -

Mechanical Condition

Control Lights			
ABS Warning Light	•	Airbag Warning Light	•
Oil Pressure Warning Light	•	Brake Warning Light	•
Power Steering Warning Light	•	Alternator / Battery	•
No Dashboard Lights	⊘	Display Defect	⊘
Service Light	(1)	Tire Pressure Monitoring System	⊘
Engine			
Engine Status / EML	⊘	Engine Leak Visible	⊘
Engine Starts	②		
Gearbox			
Gear Box	•		
Levels			
Brakes Fluid	•	Coolant Fluid	•
Equipments Test			
Central Locking	•	Main & Spare Keys Functioning	•
Electric Windows	⊘	Audio Equipment	⊘
AC / Heating System	•		

Test Drive Inspection

description.

Engine				
Engine Noise	•	Fume Quantity	⊘	
Power Loss	⊘	The Gears Scratch / Skip / Abnormal Operation	(1)	
Brake				
Brake System Anomaly	•			
Steering Wheel				
Steering Noise / Anomaly	•			
Clutch				
Clutch Functioning	(1)			
General				
Test Driven Status	•			
	d condition or correct tests, accord			
Discidiffet				
Please also note the "UserGuide condition report", which shows the scope of the vehicle			<u>User G</u>	<u>uide</u>