

## VEHICLE INSPECTION REPORT

### Overview

**Order Number**

1001843807

**VIN**

WVWZZZAAZLD904956



Vehicle view - diagonal front left



Vehicle view - diagonal rear right



Interior - driver's side

### Vehicle data

**Make & model**

e-up! move up! electric 61kW 1-speed 1-speed automatic 4 doors

**Roadworthy**

Yes

**Vehicle category**

Passenger car

**Vehicle type**

Small car

**Date of first registration**

28/02/2020

**Interior colour**

Black

**Exterior colour**

White

**Roof colour**

White

**Mileage**

17591

**Engine type**

Electric

**Mode of drive**

Front wheel drive

**Number of doors**

5

**Number of seats**

5

**Gearbox**

Automatic

**Number of keys**

2

**Number of cylinders**

4

**Number of gears**

7

### Documents & maintenance

**Next statutory inspection date**

28/02/2026

**Registration certificate available**

Yes

**Maintenance last mileage****Maintenance booklet**

No

**Maintenance last date**

## Vehicle equipment

Driving on the right	e-move upÜ
Part set without country-specific prescriptive standard	Type approval country Italy (San Marino, State of Vatican City)
4 alloy wheels "Blade" 5J x 15	Operating permit, alteration
Volkswagen Car-Net e-Remote (contract duration 1 year free of charge)	CCS vehicle inlet
Mains charging cable for household outlet	No special edition
Customized installation	No special purpose vehicle, standard equipment
Electronic engine sound	Vehicles with special upgrade measures
Shock absorption in front	Transmission for electric drive (1-speed)
Tires 165/65 R15 low rolling resistance	Without bracket
Radio "Composition Phone"	Battery 175 A (36 Ah)
Rear view camera system	Without fuse box
Refrigerant R1234yf	Chrome bezels for rotary light switch and air conditioning controls
Hatchback	Left-hand drive
Suspension range 12 installation control only, no requirement forecast	Electric motor, 61 kW
Inserts of front seats and outer rear seats in fabric "Fusion"	Design Pack "Interior"
Comfort package	Driver Assistance package
design pack "exterior"	Leather-wrapped multi-function steering wheel
Without LongLife Service Regime	Multifunction camera
Ambient lighting	Digital radio reception DAB+
Electric motor unit 0EA.C	USB interface also for iPod/iPhone
Instrument cluster, km/h speedometer	Service indicator 30 000 km or 2 years ( fix ) electric vehicle
Tire suppliers for EU countries	Preparation for e-Remote
4 doors, hinged rear side windows	Vehicle class differentiation -12E -
Transmission for electric drive	Without specific emission standard
Without decals and emblems	Elimination of nameplate for engine designation on luggage compartment lid
Labels in Italian	Carpet mats in front and rear with decorative stitching
Manual in Italian	Weight range 2 installation control only, no requirement forecast
Standard climatic zones	Electronic Stability Control with hill hold control, ABS, ASR, EBD, and EDTC
Special identification label for EC for M1 passenger vehicles	Tire Mobility Set: 12-volt compressor and tire sealant
Rear shock absorption, basic version 2	Drum brakes in rear
Ventilated disc brakes in front	Trims for alloy wheels
Electromechanical power steering	Wheel locks with extended theft protection
Tool kit	Warning triangle
Bumpers in front with air intakes in honeycomb structure, sill in body color	Without additional tires
Leather-wrapped multi-function steering wheel	Without partition
Without roof insert (standard roof)	Luggage compartment floor
Interior door handle in chrome	Front seats with height adjustment
Standard floor covering	Without special measures
Unsplit rear bench seat, 2 seats, asymmetric split folding backrest	2 head restraints in rear, lowerable
Luggage compartment cover	3-point seat belts, outer rear with ECE label
Without seat heater	Laminated safety glass windshield, heat-insulating
Central locking system without SAFELOCK,incl. radio remote control	Privacy glass for rear side windows and rear window
Power windows in front	Driver and front passenger airbag with front passenger airbag deactivation
Curtain airbag system for front and rear passengers incl. side airbags in front	Carrier frequency 433.92 MHz-434.42 Mhz
Transport protection film (minimum protection) with additional transport protection measures	Right exterior mirror, convex
Without lashing rings for load restraintsystem	Without fire extinguisher
Body-colored exterior mirror housings and door handles	Vanity mirror in the front passenger's sun visor
light gray headliner	Left/right vent bezels and controls for radio and HVAC painted in chrome
Rear license plate carrier (ECE)	Hand brake lever handle in leather, hand brake lever button in chrome
Front license plate carrier (large)	Gearshift knob in leather
Tire Pressure Monitoring System	Exterior mirrors, adjustable from inside
maps + more dock	Front scuff plates in aluminum, with "e-upÜ" lettering
Without extended safety system	Dash pad "Shark Skin"
Charging cable mode 3 type 2, 32 A	Park Distance Control - acoustic warning signal for obstacles in the rear
Aut. headlight control w/ separate daytime running light, Leaving Home and manual Coming Home feature	Halogen headlamps and turn signals under one clear lens with LED separate daytime running light
Rear fog lamp for driving on the right	2 speakers
Without front fog lamps	Cruise control system
Antenna for FM reception	High-tone horn
Air conditioning system Climatronic	Not hot country
Non-smoker's package: 12-V outlet in front	Luggage compartment lighting
Multi-function display	Warning signal and warning light for front and rear seat belts not fastened
Equipment options subset for Italy	Mobile phone interface
	Alloy wheels

## Tyres (mounted)

Make	Location	Position	Type	Rim	Dimensions	Load	Speed	Profile depth	Permitted	Roadworthy
Michelin	Front	Left	Summer	Alu	165 15 R65	81	T	5.5 mm	V	V
Michelin	Front	Right	Summer	Alu	165 15 R65	81	T	5.3 mm	V	V
Goodyear	Back	Left	Summer	Alu	165 15 R65	81	T	4.8 mm	V	V
Goodyear	Back	Right	Summer	Alu	165 15 R65	81	T	4.5 mm	V	V

## Spare/emergency tyre & accessories

### Toolkit present

Yes

### Repair kit present

No

### Compressor present

No

### Spare wheel

No

### Temporary spare wheel

No

Devaluation factors

Nr.	Location	Damage type	Repair type
1	Rimozione adesivi	Dirty	Repair
2	Front wheel Left	Scratched	Repair
3	Igienizzazione interior	Dirty	Forfait
4	Front bumper	Scratched	Repair
5	Bumper dismantling	N/a	N/a
6	Rear bumper	Scratched	Repair
7	Bumper dismantling	N/a	N/a
8	Front door Right	Dentend	Repair
9	Roof	Hail dented	Repair
10	Door perimeter substructure complete with rear fender Right	Hail dented	Repair
11	Front lid	Hail dented	Repair

Usage damages

Nr.	Location	Damage type	Repair type
1	Front fender Left	Dentend	Reminder
2	Rear door Left	Scratched	Reminder

Missing parts

Nr.	Location	Damage type	Repair type
1	Tire inflation kit	Missing	Replace
2	Antenna	Missing	Replace

Mercantile depreciation

Known previous damages		Previous damages detectable		Repainting present	
Yes		No		No	
Repainting professionally executed		Paint thickness measurement performed			
No		No			
PAINT THICKNESS MEASUREMENT RESULTS					
Part		Paint (um)		Cost €	
Front lid		0,00			
Door perimeter substructure complete with rear fender Right		0,00			
Roof		0,00			
				2.745,54	









Notes on the assessment

Vehicle identification :	WVWZZZAAZLD904956
Vehicle condition :	Clean
Inspection condition :	Sunny
Engine test carried out :	Yes

Detail of the assignement and the scope of the assestment :



# Commercial pictures














Commercial pictures





Damages

Devaluation factors

Component	Rimozione adesivi			Side	
1					
Component	Front wheel			Side	Left
2					
Component	Igienizzazione interior			Side	
3					
Component	Front bumper			Side	
4					
Component	Bumper dismantling			Side	
5					



Damages





Devaluation factors

Component

Rear bumper

Side

6



Component

Bumper dismantling

Side

7



Component

Front door

Side

Right

8







Component

Roof

Side

9







Component

Door perimeter substructure complete with rear fender

Side

Right

10



Damages




Devaluation factors

Component

Front lid

Side

11



Danni from normale usura1



Component

Front fender

Side

Left

1




Component

Rear door

Side

Left

2



Missing parts

Component

Tire inflation kit

Side

1

Component

Antenna

Side

2

