

VOLKSWAGEN Golf VII Golf Sportsvan 1.4 TSI (BlueMotion Technology) DSG



VIN NO WVWZZZAUZGW528952 Registration Number UZGW528952

MOT Date 2024-08-01

Last Service

2023-11-07

Number of Owners

3 1

Last Service Mileage

65983

Number of Keys

P2

First Registration Date

2015-09-30

Odometer Reading

66274 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20251009100910
Inspection Date / Place	2025-10-09 / BCA Oberndorf	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	1395
Engine Size	1.4	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz/ Grau	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	120
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			



























Equipment

Airbag Status	Anti-lock braking	Fatiguewarningsystem	Front parking sensors
Remote adjusting wing mirrors	Split folding rear seats	Xenon headlamps	Emergencybrakeassist
Radio	Alloys wheels	Auxiliary Socket	Front fog lamps
Heated wing mirrors	Remote central locking	Stability control	Central locking
Leather steering wheel	Rear parking sensors		


Equipment Details

Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	17
Extra Wheel / Tyre Set	Winter Tyres - Steel	Seat Heating	Front

Wheels & Tyres

Extra Wheel - 1 Tyre Depth	7	Extra Wheel - 2 Tyre Depth	7
Extra Wheel - 3 Tyre Depth	7	Extra Wheel - 4 Tyre Depth	7
Right Front Tyre Depth	5	Left Front Tyre Depth	5
g		20.01. от 1 уго 2 ор иг	
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5
3 ,		, , , , , , , , , , , , , , , , , , ,	

Cosmetic Damage




	Component	Damage	Comments
1	Bumper / Front	Paint / Scratch / Scuff	
2	Corner Bumper / Front Left	Paint / Scratch / Scuff	
3	Fender / Back Right	Bodywork / Dent / Dent	
4	Bumper / Back	Paint / Scratch / Scuff	
5	Mirror / Front Right	Bodywork / Breakage / Crack	
6	Door / Back Right	Paint / Scratch / Scuff	
7	Tailgate	Paint / Scratch / Scuff	
8	Fender / Front Right	Paint / Scratch / Scuff	
9	Mirror / Front Left	Bodywork / Breakage / Crack	



1. Bumper / Front Paint / Scratch / Scuff -

2. Corner Bumper / Front Left Paint / Scratch / Scuff -




3. Fender / Back Right Bodywork / Dent -

4. Bumper / Back Paint / Scratch / Scuff -



5. Mirror / Front Right Bodywork / Breakage / Crack -

6. Door / Back Right Paint / Scratch / Scuff -



7. Tailgate Paint / Scratch / Scuff -

8. Fender / Front Right Paint / Scratch / Scuff -



9. Mirror / Front Left Bodywork / Breakage / Crack -

Mechanical Condition

Control Lights			
ABS Warning Light	•	ESP Fault/Traction Control Malfunction Light	⊘
Airbag Warning Light	•	Oil Pressure Warning Light	•
Brake Warning Light	•	Power Steering Warning Light	•
Alternator / Battery	•	No Dashboard Lights	•
Display Defect	•	Service Light	(1)
Tire Pressure Monitoring System	⊘		
Engine			
Engine Status / EML	•	Engine Leak Visible	•
Engine Starts	•		
Gearbox			
Gear Box	•		
Levels			
Brakes Fluid	•	Coolant Fluid	•
Equipments Test			
Central Locking	•	Main & Spare Keys Functioning	•
Electric Windows	•	Audio Equipment	•
Parking Sensors / Cameras Functioning	•	AC / Heating System	•
Other Equipments	•		

Test Drive Inspection

description.

Engine The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity** Power Loss **Brake Brake System Anomaly Steering Wheel** Steering | Noise / Anomaly General **Test Driven Status** Not Performed No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer

User Guide

Please also note the "UserGuide condition report", which shows the scope of the vehicle