



status report

customer:	BCA Autoauktionen GmbH
reference:	

vehicle data			
Volkswagen Golf VII Variant Highline BMT/Start-Stopp			
Vehicle identification number	WVWZZZAUZJP599499	mileage read:	242632 km
..			
First Registration / construction year:	23.05.2018 / 2018	Visit Date / place of birth:	04.09.2025 Hoppegarten
Bodywork:	cars	Re - import:	no
Body type:	station wagon	KBA no. :	0603//BOD
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1968 ccm / 110 kW (150 PS)	Engine:	front-wheel drive
paint:	Tornadorot	Number of previous owners:	2
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	no	Vehicle roadworthy:	no
Submitted vehicle	Eg II (veh - letter)	state outside:	3 - Average
documents:			
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)			
GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
SD Card	2	maintained:	- / -
		no / 6	
☒ Fernbed . Auxiliary heating	☒ partition net	☒ Wind Deflector	☒ AHK fixed
☒ AHK removable	☒ AHK swivel	☒ AHK key	☒ Fernbed . entertainment
☒ headphone	☒ Load compartment cover	☒ LED headlights	☒ navigation system
☒ Persenning	☒ Xenon headlights		

☒ available ☒ not available

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Pirelli	235/45/R18/94V 2 mm
1st axis - right / states .	Bridgestone	195/65/R15/95T 2 mm
2nd axis - Left / states .	Pirelli	235/45/R18/94V 2 mm
2nd axis - right / states .	Pirelli	235/45/R18/94V 2 mm
traffic Safety:	not roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• 3-point rear center seat belt • Airbag Driver / passenger side • Anti- lock braking system (ABS) • Drive Front Wheel Drive • Auto-Hold function • Power side mirrors . adjustable and heated • painted mirrors • Indicator integrated into mirrors • Lining Wear • Chrome strip front bumper • Doppeltonhorn • Park Distance Control (front and rear) • Electron. Differential lock (XDS) • Trailer stabilization program • Driving Assistance System environment monitoring system (front assist) with City Emergency Braking <i>Fahrassistenz-System: City-Notbremsfunktion, Fahrassistenz-System: Fußgängererkennung</i> • Front glass laminated glass tinted • Textile floor mats • Transmission 7 - speed dual - clutch gearbox DSG • LED Taillights • Interior decor inlays Linearus • Body 5-door • Climatronic air conditioning 2-zone <i>Innenraumfilter: Staub- und Pollenfilter mit Aktivkohlefilter</i> • Head airbag system, front and rear incl . Side airbags • Radiator grille black with chrome strip below • Lumbar support seat front right • Steering column (steering wheel) mechan.	• Airbag switched off • Ambient lighting • Acceleration skid control (ASR) • Amenities High Line • Mirrors, aspheric, left • Mirrors convex, right • Exterior mirrors with automatic . kneeling • brake Assist • Chrome package 2 <i>Chromeinfassung Lichtschalter, Chromeinfassung Fensterheberschalter, Chromeinfassung Spiegelverstellung</i> • Silver roof rails • Durchladeeinrichtung (rear center armrest) • Electron. Differential lock (EDL) • Electron. Stability Program (ESP) • Driving Assistance System fatigue detection sensor • Power windows • Radio key (2) foldable • Footwell lighting front LED • Glove compartment with cooling function • rear window wiper • Isofix admissions for child seat in back seat • LED License Plate Lights • Knee airbag , driver's side • Rear headrests (3- fold) • 8 speakers • Steering wheel (leather) with multifunction and switching function • Reading lights front and rear LED • Front center armrest • Engine 2.0 ltr. - 110 kW TDI



adjustable height / length adjustment • LM rims • model refinement • Multi-function display Premium • Rear fog light • Parking brake electrically • Tire pressure warning indicator • Split rear seat back • Gearshift / selector lever leather • Seat belts front with belt tensioner, height adjustable • Front right seat height adjustment • Sun visors with mirrors (illuminated) • Socket (12V) port in the trunk / cargo area • LED daytime running lights • First aid kit and warning triangle • Immobiliser (electronic) • Central locking with remote control	• Fog lights with static cornering light <i>Abbieglicht</i> • Non smoking package • Tire repair kit • Rußpartikelfilter • Low emissions Euro 6 emission standards • Power steering electro-mechanical and speed-dependent • Front left seat height adjustment • Seat relation / upholstery fabric / micro fleece • Start / Stop system • bumper painted • Exterior door handles body color • Warning system for safety • Winter package <i>Scheinwerfer-Reinigungsanlage (SRA), Scheibenwaschdüsen heizbar, Anzeige für Waschwasserstand, Sitzheizung vorn</i>
---	--

special Features	
• Audio System Composition Media (MP3 playback capability , Radio / CD player , Bluetooth) <i>Antennen-Diversity, Audiosystem: CD-Player, Multimedia-Schnittstelle USB (iPhone / iPod) mit AUX-IN, Bluetooth-Schnittstelle für Mobiltelefon</i> • Driving Assistance package Plus <i>Fahrassistenz-System: Blind Spot Sensor mit Auspark-Assistent, Scheinwerfer LED mit dynamischem Kurvenlicht, Leuchtweitenregelung automatisch, Automatische Fahrlichtschaltung (ALS) mit Leaving Home / Coming-Home-Lichtfunktion, Fahrassistenz-System: Dynamische Fernlichtregulierung (Dynamic Light Assist), Frontkamera (Multifunktionskamera Frontscheibe), Scheibenwischer mit Regensensor, Innenspiegel mit Abblendautomatik, Diebstahl-Warnanlage mit Innenraumüberwachung, Safesicherung, Fahrassistenz-System: Emergency Assist, Fahrassistenz-System: Autom. Distanzregelung (ACC inkl. Stop&Go-Funktion) mit Umfeldbeobachtungssystem (Front assist), Fahrassistenz-System: Automatische Distanzregelung (ACC), Geschwindigkeits-Begrenzeranlage, Fahrassistenz-System: Umfeldbeobachtungssystem (Front assist) mit City-Notbremsfunktion, Fahrassistenz-System: City-Notbremsfunktion, Fahrassistenz-System: Fußgängererkennung</i> • Mobile Online Services Car Net	• Business Package Premium with Navigation <i>Multimedia-Schnittstelle 2 x USB (iPhone / iPod), Gepäckraum-Abtrennung (Netztrennwand), Sitze: Sport-Komfortsitze vorn, Sitz vorn links mit ausziehbarer Oberschenkelauflage, Sitz vorn links mit Massagefunktion, Lendenwirbelstütze Sitz vorn links, elektr. verstellbar, Fahrassistenz-System: Autom. Distanzregelung (ACC inkl. Stop&Go-Funktion) mit Umfeldbeobachtungssystem (Front assist), Fahrassistenz-System: Automatische Distanzregelung (ACC), Geschwindigkeits-Begrenzeranlage, Fahrassistenz-System: Umfeldbeobachtungssystem (Front assist) mit City-Notbremsfunktion, Fahrassistenz-System: City-Notbremsfunktion, Fahrassistenz-System: Fußgängererkennung</i> • Driving Assistance System Traffic Sign Recognition • Mobile phone interface Comfort with wireless charging function <i>Bluetooth-Schnittstelle für Mobiltelefon, Multimedia-Schnittstelle 2 x USB (iPhone / iPod)</i> • Special paint Tornado Red • Glazing behind darkened (65 %)

- Navigation module Discover Media (audio system)
Volkswagen Media Control
- Mirror package
*Außenspiegel elektr. anklappbar, Außenspiegel mit
 Umfeldleuchte, Außenspiegel mit autom. Absenkfunktion,
 rechts*
- Winter tires also

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Unfallschaden

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	found At the unrepaired vehicle accident damage were observed on visual examination on the body skin .
reference:	Front, nicht sichtbare Schäden möglich

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
					Out of order
oil loss:			examined limited		
air conditioning:			not possible	lighting system:	
					Out of order
coupling:			unavailable	exhaust System:	
					not possible
engine running:			not possible	shock absorber:	
					not possible
transmission:			not possible		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was discharged for visiting time . **Battery deep discharge. Vehicle was bridged with a jumper.
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning could not be checked during the inspection .
lighting system:	For sightseeing timing defects in the lighting system were noted .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system could not be checked during the inspection .
engine running:	A field test of the engine could not be performed
shock absorber:	The shock absorber could not be checked during the inspection .
transmission:	The transmission could not be checked for visiting time .
reference:	*

damage



component	Damage	Rep kind
1. Front door - left	Subsequently painted	acceptable
2. battery	Not okay	Replace
3. maintenance	Due	Replace
4. exterior body	Accident damage	Refer to calculation
5.	Scratch(es)	Paint
6. Sidewall - Rear - Left	Wear and tear	acceptable
7. Rear bumper	Scratch(es)	Paint
8.	Scratch(es)	Paint
9.	Missing	Replace
10. roof	Corroded	Paint
11. proof of maintenance	Missing	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted , and for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



1. Front door - left



4. exterior body



4. exterior body



4. exterior body



4. exterior body



4. exterior body



4. exterior body



4. exterior body



4. exterior body



4. exterior body



4. exterior body




4. exterior body



4. exterior body



5.



6. Sidewall - Rear - Left



7. Rear bumper



8.



10. roof