



Hüsges Gruppe®
Die Gutachter

status report

customer: BCA Autoauktionen GmbH
contract number:
reference:

vehicle data

Volkswagen Golf VII Lim. GTI TCR Start-Stopp

Vehicle identification number	VWZZZAUZKW213637	mileage read:	152915 km
First Registration / construction year:	08.07.2019 / 2019	Visit Date / place of birth:	26.09.2025 Knautnaundorf
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	0603//CIY
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	1984 ccm / 213 kW (290 PS)	Engine:	front-wheel drive
paint:	Pure Grey	Number of previous owners:	2
Doors / seats:	3 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	Leather / fabric
Service book available:	digital	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	57499 / 28.03.2023
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle	-	state outside:	5 - neglected
documents:		condition inside:	5 - neglected
visit condition:	-		
state general:	5 - neglected		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
Hard Disk Drive	2	maintained:	57499 / 28.03.2023
		digital / -	

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Michelin	205/50/R17/93H 1.3 mm
1st axis - right / states .	Michelin	205/50/R17/93H 1 mm
2nd axis - Left / states .	Michelin	205/50/R17/93H 2 mm
2nd axis - right / states .	Michelin	205/50/R17/93H 1.5 mm
traffic Safety:	not roadworthy	
spare wheel:	Tirefit	
state spare wheel:	-	

standard equipment

- | | |
|--|--|
| <ul style="list-style-type: none"> • 3-point rear center seat belt • • Airbag Driver / passenger side • Anti- lock braking system (ABS) • Amenities GTI • Automatic headlight activation (AS) and Leaving Home / Coming Home light function • Power side mirrors . adjustable and heated • Exterior mirrors with automatic . kneeling • brake Assist • Chrome package 2
<i>Chromeinfassung Lichtschalter, Chromeinfassung Fensterheberschalter, Chromeinfassung Spiegelverstellung</i> • roof spoiler • Doppeltonhorn • Park Distance Control (front and rear) • • Electron. Differential lock (XDS) • Trailer stabilization program • Driving Assistance System environment monitoring system (front assist) with City Emergency Braking
<i>Fahrassistenz-System: City-Notbremsfunktion, Fahrassistenz-System: Fußgängererkennung</i> • Front glass laminated glass tinted • Textile floor mats • Glove compartment with cooling function • rear window wiper • Rearview mirror with auto dip • • Knee airbag , driver's side • Rear headrests (3- fold) | <ul style="list-style-type: none"> • cornering • Airbag switched off • Ambient lighting • Acceleration skid control (ASR) • Auto-Hold function • Mirrors, aspheric, left • Mirrors convex, right • Indicator integrated into mirrors • Red painted brake calipers • Headliner fabric , black • Differential lock (front axle) • Durchladeeinrichtung (rear center armrest) • Easy Entry Easy-Entry • Electron. Differential lock (EDL) • Electron. Stability Program (ESP) • Driving Assistance System fatigue detection sensor • Power windows • Radio key (2) foldable • Transmission 7 - speed dual - clutch gearbox DSG • Tail lights LED, dark red, turn signals dynamic • • Isofix admissions for child seat in back seat • Climatronic air conditioning 2-zone
<i>Innenraumfilter: Staub- und Pollenfilter mit Aktivkohlefilter</i> • Head airbag system, front and rear incl . Side airbags • 8 speakers • Lumbar support seat front right • Steering column (steering wheel) mechan. adjustable height / length adjustment • |
|--|--|

• Lumbar support front left seat • Steering wheel (Sport / Leather - TCR) with multifunction and shift function • Reading lights front and rear LED • Front center armrest • Motor 2,0 Ltr. - 213 kW 16V TSI • Rear fog light • emergency call system • Parking brake electrically • progressive steering • Tire pressure warning indicator • Low emissions according to Euro 6d TEMP emission standard • Windscreen wipers with rain sensor • Front left seat height adjustment • Seat cover / upholstery fabric • Stabilizer front • Socket (12V) port in the trunk / cargo area • LED daytime running lights • Warning system for safety • Winter package <i>Scheinwerfer-Reinigungsanlage (SRA), Scheibenwaschdüsen heizbar, Anzeige für Waschwasserstand, Sitzheizung vorn</i>	• model refinement • Multi-function display Premium • Non smoking package • Otto Particle Filter (OPF) • Pedals stainless steel • Tire repair kit • Split rear seat back • Gearshift / selector lever aluminum • Seat belts front with belt tensioner, height adjustable • Front right seat height adjustment • Top Sport Seats front • Start / Stop system • Bumper sports design painted, • Exterior door handles body color • Immobiliser (electronic) • Central locking with remote control
---	---

special Features	
• Active Lighting Package <i>Scheinwerfer LED mit dynamischem Kurvenlicht, Leuchtweitenregelung automatisch, Automatische Fahrlichtschaltung (ALS) mit Leaving Home / Coming-Home-Lichtfunktion, Fahrassistenz-System: Dynamische Fernlichtregulierung (Dynamic Light Assist), Frontkamera (Multifunktionskamera Frontscheibe), Scheibenwischer mit Regensensor, Innenspiegel mit Abblendautomatik</i> • Mirrors carbon • Driving Assistance System Blind Spot Assist Sensor with Auspark • extinguisher • Sound system DYNAUDIO Sound <i>10-Kanal-Verstärker, Subwoofer, Lautsprecher (8)</i> • Glazing behind darkened (90 %)	• Navigation module Discover Pro (with hard drive space) <i>Audiosystem: CD-/DVD-Player, Lautsprecher (8), Sprachsteuerungs-System, Multimedia-Schnittstelle USB (iPhone / iPod), Bluetooth-Schnittstelle für Mobiltelefon, Volkswagen Media Control und App-Connect / MirrorLink, App-Connect</i> • Adaptive Chassis Control (DCC) <i>Fahrassistenz-System: Fahrprofilwahl</i> • Driving Assistance System Traffic Sign Recognition • Rear View Camera • Mirror package <i>Außenspiegel elektr. anklappbar, Außenspiegel mit Umfeldleuchte, Außenspiegel mit autom. Absenkfunktion, rechts</i>

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Bereifung nicht in Ordnung

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	found At the unrepaired vehicle accident damage were observed on visual examination on the body skin .
reference:	Fahrzeug mit bestehenden Unfallschaden, zur Schadensermittlung wurden keine Demontearbeiten durchgeführt, verborgen gebliebene Schäden können nicht ausgeschlossen werden. Unfallschaden Kosten wurden überschlägig Kalkuliert, Kostenerweiterung möglich.

Overview conducted technology audit					
Alternator / Generator:		examined limited	Battery / accumulator:		examined limited
oil loss:		not possible			
air conditioning:		examined limited	lighting system:		examined limited
coupling:		unavailable	exhaust System:		examined limited
engine running:		Out of order	shock absorber:		not possible
transmission:		examined limited			

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could not be checked during the inspection on oil losses.
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine had to acoustic or visual defects for visiting time . **Engine warning light.
shock absorber:	The shock absorber could not be checked during the inspection .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Das Fahrzeug hat starke Alters- und Gebrauchsspuren

damage



component	Damage	Rep kind
1. Laderaumabdeckung	Missing	Replace
2. motor	Error message	Carry out a fault diagnosis
3. Wartung	Error message	Replace
4. Reifendruckkontrolle	Error message	Carry out a fault diagnosis
5. brake system	Error message	Carry out a fault diagnosis
6. tire front - left	Worn	Replace
7. tire front - right	Worn	Replace
8. tire rear - right	Worn	Replace
9. tire rear - left	Worn	Replace
10. Kofferraum und Innenraum	Wear and tear	acceptable
11. Zigarettenanzünder vorn: Verschlusskappe	Missing	Replace
12.	Dirty	
13. steering wheel	Scrape	Replace
14. tailgate trim	Damaged	Replace
15. Motorhaubenentriegelung	Not okay	Replace
16. Motorraum		Carry out a fault diagnosis
17. roof	chipped paint	Paint
18.	Scrape	Replace
19. Front door - left	Wear and tear	acceptable
20. Sidewall - Rear - Left	Damaged	Refurbish and paint
21. tailgate	Scratch(es)	Paint
22. Rear bumper	Scrape	Paint
23. Fahrzeug rechts	Accident damage	Replace
24. hood	chipped paint	Paint
25. spoiler	Scrape	Replace
26. Fahrzeug vorn	Clearance not exact	Uninstall/install
27. brake system	Abnormal noises	Carry out a fault diagnosis
28. Fahrzeug (Kratzer, Harz-/Säureeinwirkung)	Not looked after	

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted , and for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims




rims



engine compartment




service book



Others



Navigation system



2. motor



3. Wartung



4. Reifendruckkontrolle



5. brake system



6. tire front - left




7. tire front - right



8. tire rear - right



9. tire rear - left



10. Kofferraum und Innenraum



10. Kofferraum und Innenraum



10. Kofferraum und Innenraum



11. Zigarettenanzünder vorn: Verschlusskappe



12.




12.



12.



12.



12.



13. steering wheel



13. steering wheel



13. steering wheel



13. steering wheel



14. tailgate trim



14. tailgate trim



14. tailgate trim



14. tailgate trim



14. tailgate trim



15. Motorhaubenentriegelung



17. roof



17. roof



17. roof



17. roof



18.



18.



19. Front door - left



19. Front door - left



20. Sidewall - Rear - Left



20. Sidewall - Rear - Left



20. Sidewall - Rear - Left



20. Sidewall - Rear - Left



21. tailgate



21. tailgate



21. tailgate



21. tailgate



22. Rear bumper



22. Rear bumper



22. Rear bumper




22. Rear bumper




23. Fahrzeug rechts



23. Fahrzeug rechts




23. Fahrzeug rechts



23. Fahrzeug rechts



23. Fahrzeug rechts



23. Fahrzeug rechts



23. Fahrzeug rechts




23. Fahrzeug rechts



23. Fahrzeug rechts




23. Fahrzeug rechts



24. hood



24. hood




24. hood



24. hood



24. hood



25. spoiler



25. spoiler



25. spoiler



26. Fahrzeug vorn



26. Fahrzeug vorn



26. Fahrzeug vorn



26. Fahrzeug vorn



26. Fahrzeug vorn




26. Fahrzeug vorn



26. Fahrzeug vorn



26. Fahrzeug vorn



28. Fahrzeug (Kratzer, Harz-/Säureeinwirkung)



28. Fahrzeug (Kratzer, Harz-/Säureeinwirkung)