



status report

customer: Bank 11, Neuss
contract number: 893204230
reference:

vehicle data

Volkswagen Golf VII Lim. GTI Performance BMT/Start-Stopp

Vehicle identification number	WVWZZZAUZLW024379	mileage read:	47395 km
First Registration / construction year:	24.09.2019 / 2019	Visit Date / place of birth:	18.08.2025 Neuss
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	0603//CCS
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	1984 ccm / 180 kW (245 PS)	Engine:	front-wheel drive
paint:	Atlantik Blue Metallic	Number of previous owners:	2
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	leather
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	Eg II (veh - letter)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
SD Card	2	no / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	aluminum
1st axis - Left / states .	Bridgestone	225/40/R18/92Y 3 mm
1st axis - right / states .	Bridgestone	225/40/R18/92Y 3 mm
2nd axis - Left / states .	Bridgestone	225/40/R18/92Y 3 mm
2nd axis - right / states .	Bridgestone	225/40/R18/92Y 3 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

Unmounted tires		
Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Pirelli	225/40/R18/92H 4 mm
1st axis - right / states .	Pirelli	225/40/R18/92H 4 mm
2nd axis - Left / states .	Pirelli	225/40/R18/92H 5 mm
2nd axis - right / states .	Pirelli	225/40/R18/92H 5 mm
traffic Safety:	roadworthy	

standard equipment	
• 3-point rear center seat belt • Exhaust system performance • Airbag switched off • Ambient lighting • Acceleration skid control (ASR) • Audio System Composition Media (MP3 playback capability , Radio / CD player , Bluetooth) <i>Antennen-Diversity, Audiosystem: CD-Player, Multimedia-Schnittstelle USB (iPhone / iPod), Bluetooth-Schnittstelle für Mobiltelefon</i> • Auto-Hold function • Mirrors, aspheric, left • Mirrors convex, right • Exterior mirrors with automatic . kneeling • brake Assist • Chrome package 2 <i>Chromefassung Lichtschalter, Chromefassung Fensterheberschalter, Chromefassung Spiegelverstellung</i> • roof spoiler • Doppeltonhorn • Park Distance Control (front and rear) • Electron. Differential lock (EDL) • Electron. Stability Program (ESP) • Driving Assistance System fatigue detection sensor	• cornering • • Airbag Driver / passenger side • Anti- lock braking system (ABS) • Drive Front Wheel Drive • Amenities GTI • Automatic headlight activation (AS) and Leaving Home / Coming Home light function • Power side mirrors . adjustable and heated • painted mirrors • Indicator integrated into mirrors • Red painted brake calipers • Headliner fabric , black • Differential lock (front axle) • Durchladeeinrichtung (rear center armrest) • • Electron. Differential lock (XDS) • Trailer stabilization program • Driving Assistance System environment monitoring system (front assist) with City Emergency Braking <i>Fahrassistenz-System: City-Notbremsfunktion, Fahrassistenz-System: Fußgängererkennung</i> • Radio key (2) foldable • Transmission 7 - speed dual - clutch gearbox DSG



- Power windows
- Textile floor mats
- Glove compartment with cooling function
- rear window wiper
- Rearview mirror with auto dip
- Body 5-door
- Knee airbag , driver's side
- Rear headrests (3- fold)
- Lumbar support seat front right
- Steering column (steering wheel) mechan. adjustable height / length adjustment
- Front center armrest
- model refinement
- Multi-function display Premium
- Non smoking package
- Otto Particle Filter (OPF)
- Pedals stainless steel
- Tire repair kit
- Split rear seat back
- Gearshift / selector lever aluminum
- Seat belts front with belt tensioner, height adjustable
- Front right seat height adjustment
- Stabilizer front
- Socket (12V) port in the trunk / cargo area
- LED daytime running lights
- Warning system for safety
- Winter package
Scheinwerfer-Reinigungsanlage (SRA), Scheibenwaschdüsen heizbar, Anzeige für Waschwasserstand, Sitzheizung vorn
- Central locking with remote control

- Tail lights LED, dark red, turn signals dynamic
-
- Isofix admissions for child seat in back seat
- Climatronic air conditioning 2-zone
Innenraumfilter: Staub- und Pollenfilter mit Aktivkohlefilter
- Head airbag system, front and rear incl . Side airbags
- 8 speakers
- Steering wheel (sport / leather) with multifunction and switching function
- Reading lights front and rear LED
- Mobile Online Services VW Connect
-
- Rear fog light
- emergency call system
- Parking brake electrically
- progressive steering
- Tire pressure warning indicator
- Low emissions according to Euro 6d TEMP emission standard
- Windscreen wipers with rain sensor
- Front left seat height adjustment
- Top Sport Seats front
- Start / Stop system
- Bumper sports design painted,
- Exterior door handles body color
- Immobiliser (electronic)
- Tinted heat insulating glass green

special Features

- | | |
|---|---|
| <ul style="list-style-type: none"> • Active Lighting Package
 <i>Scheinwerfer LED mit dynamischem Kurvenlicht, Leuchtweitenregelung automatisch, Automatische Fahrlichtschaltung (ALS) mit Leaving Home / Coming-Home-Lichtfunktion, Fahrassistenz-System: Dynamische Fernlichtregulierung (Dynamic Light Assist), Frontkamera (Multifunktionskamera Frontscheibe), Scheibenwischer mit Regensensor, Innenspiegel mit Abblendautomatik</i> • Adaptive Chassis Control (DCC)
 <i>Fahrassistenz-System: Fahrprofilwahl</i> | <ul style="list-style-type: none"> • Business Package Premium with Navigation
 <i>Multimedia-Schnittstelle 2 x USB (iPhone / iPod), Fahrassistenz-System: Autom. Distanzregelung (ACC inkl. Stop&Go-Funktion) mit Umfeldbeobachtungssystem (Front assist), Fahrassistenz-System: Automatische Distanzregelung (ACC), Geschwindigkeits-Begrenzeranlage, Fahrassistenz-System: Umfeldbeobachtungssystem (Front assist) mit City-Notbremsfunktion, Fahrassistenz-System: City-Notbremsfunktion, Fahrassistenz-System: Fußgängererkennung</i> • Driving Assistance System Blind Spot Assist |
|---|---|

• Driving Assistance System Park Assist (Park Assist) • Interior leather Vienna incl. Top sports seats front • • Mobile phone interface Comfort with wireless charging function <i>Bluetooth-Schnittstelle für Mobiltelefon, Multimedia-Schnittstelle 2 x USB (iPhone / iPod)</i> • Fog lights with static cornering light • Rear View Camera • Mirror package <i>Außenspiegel elektr. anklappbar, Außenspiegel mit Umfeldleuchte, Außenspiegel mit autom. Absenkfunktion, rechts</i> • Winter tires also	• Sensor with Auspark • Heated front window , wireless and infrared - reflective • Occupant protection system proactively • Metallic paint • Navigation module Discover Media (audio system) <i>Volkswagen Media Control</i> • Digital radio reception (DAB +) • Rear side airbag <i>Sicherheitsgurte hinten außen mit Gurtstraffer</i> • Top Package <i>Panorama-Schiebedach elektrisch, Kennzeichenbeleuchtung LED, Schließ-/Startsystem Keyless Access, Safesicherung, Diebstahl-Warnanlage mit Innenraumüberwachung</i>
--	---

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit					
Alternator / Generator:		examined limited	Battery / accumulator:		examined limited
oil loss:		examined limited			
air conditioning:		examined limited	lighting system:		examined limited
coupling:		unavailable	exhaust System:		examined limited
engine running:		examined limited	shock absorber:		not possible
transmission:		examined limited			

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could not be checked during the inspection .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Alters-, Transport- und Laufleistungsbedingte Gebrauchsspuren vorhanden. Kosten- und Schadenserweiterung möglich.

damage



component	Damage	Rep kind
1. proof of maintenance	Missing	Replace
2. Windshield	Chipping from stones in field of view	Replace
3.	Damaged	Replace
4. spoiler	Scrape	Replace
5. Halogen headlights - left	Chipping from stones	Replace
6. Windshield	Chipping from stones in field of view	Replace
7. Sunroof	Chipping from stones	Replace
8. roof	Deformed	Smart repair
9.	Scrape	Paint
10. Sidewall - Rear - Left		Refurbish and paint
11. Rear bumper	Scratch(es)	Paint
12. tailgate	Wear and tear	acceptable
13. Sidewall - Rear - right	Damaged	Refurbish and paint
14. Front door - right		Refurbish and paint
15. Türeinstieg Vorne - Rechts	Scratch(es)	Paint
16. Front bumper	Scrape	Refurbish and paint
17. tailgate trim	Scrape	Replace
18.	Scrape	Paint
19.	Damaged	Replace
20.	Deformed	Replace
21. Sitz - Hinten - Mitte: Lehne Rückseite (Leder)	Damaged	Smart repair
22. Spoiler Heckklappe	Scratch(es)	Paint
23. maintenance	Due	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims




rims



engine compartment



service book



Others



Navigation system



3.



3.



4. spoiler



5. Halogen headlights - left



5. Halogen headlights - left



6. Windshield



6. Windshield



7. Sunroof



7. Sunroof



8. roof



8. roof



9.



9.



10. Sidewall - Rear - Left



10. Sidewall - Rear - Left



11. Rear bumper




11. Rear bumper



11. Rear bumper



12. tailgate



12. tailgate



13. Sidewall - Rear - right



13. Sidewall - Rear - right



13. Sidewall - Rear - right



13. Sidewall - Rear - right



14. Front door - right



14. Front door - right



14. Front door - right



15. Türeinstieg Vorne - Rechts



15. Türeinstieg Vorne - Rechts



16. Front bumper



16. Front bumper



17. tailgate trim



17. tailgate trim



17. tailgate trim



18.



18.



18.




19.



19.



19.



20.



20.



20.



21. Sitz - Hinten - Mitte: Lehne Rückseite (Leder)



21. Sitz - Hinten - Mitte: Lehne Rückseite (Leder)



22. Spoiler Heckklappe



22. Spoiler Heckklappe